

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21002495/APS3Q2  
**Date:** 27/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070016103
<b>Claimant Vehicle No :</b>	SLL9690T	<b>Insured Vehicle No :</b>	SMS3069D
Date of Loss:	22/02/2021	Nature of Claim:	TP
		Claim No:	0248852990SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLL9690T</b>	Engine No:	1ZRY337637
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104559713
Reg. Date:	17/03/2017 (Man. Year: 2016)	Odometer:	60185 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,189.15	12,487.07	13,702.08	52.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,570.00	4,340.00	4,230.00	49.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,759.15</b>	<b>16,827.07</b>	<b>17,932.08</b>	<b>51.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,400.00</b>		

<b>Nett Amount (S\$)</b>	<b>34,759.15</b>	<b>13,400.00</b>	<b>21,359.15</b>	<b>61.45</b>
<b>+ Car Rental (10.0 x S\$100.00/day) (S\$)</b>		1,000.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>14,407.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>14,300.00</b>		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 23/02/2021

Estimated Period of Repair: 14.0 days

Inspected At:

Ishare Auto Pte. Ltd. (HQ)  
8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT  
Singapore 415875

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	515.10 FL	*515.10 FL
2	2		*FRONT BUMPER FOG LAMP	Not Necessary	595.60 FL	*- FL
3	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	273.20 FL	*- FL
4	1		*FRONT BUMPER LOGO	Necessary	74.20 FL	*74.20 FL
5	1		*FRONT BUMPER LOWER GRILLE	Cracked	210.70 FL	*210.70 FL
6	1		*FRONT GRILLE TOP RUBBER	Not Necessary	79.40 FL	*- FL
7	1		*FRONT BUMPER BOTTOM COVER	Torn	217.30 FL	*217.30 FL
8	2		*FRONT BUMPER SIDE RETAINER	Necessary	118.80 FL	*118.80 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	397.30 FL	*397.30 FL
10	1		*FRONT RADIATOR GRILLE C/W CHROME	Cracked	676.10 FL	*382.00 FL
11	2		*FRONT FENDER INNER COWLING	Not Necessary	368.40 FL	*- FL
12	1		*BONNET	Not Necessary	1,040.40 FL	*- FL
13	2		*BONNET STOPPER	Not Necessary	38.40 FL	*- FL
14	1		*BONNET LOCK	Not Necessary	145.10 FL	*- FL
15	1		*BONNET LOCK BRACE PANEL	Bent	160.70 FL	*160.70 FL
16	2		*HORN	Not Necessary	216.80 FL	*- FL
17	2		*HEADLAMP	Cracked	5,699.60 FL	*4,446.00 FL
18	4		*HEAD LAMP LOWER BRACKET	Not Necessary	313.60 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Buckled	997.20 FL	*891.00 FL
20	1		*AIR CONDENSOR	Bent	1,495.60 FL	*1,287.00 FL
21	1		*RADIATOR	Dented	1,780.40 FL	*1,510.00 FL
22	2		*RADIATOR TOP BRACKET	Not Necessary	120.40 FL	*- FL
23	4		*RADIATOR MOUNTING	RADIATOR	260.40 FL	*- FL
24	1		*RADIATOR TOP GARNISH	Not Necessary	227.90 FL	*- FL
25	1		*TEMPERATURE SENSOR	Not Necessary	198.40 FL	*- FL
26	1		*REAR BUMPER	Missing	515.10 FL	*515.10 FL
27	2		*REAR BUMPER REFLECTOR	Missing	150.20 FL	*150.20 FL
28	1		*REAR BUMPER SIDE RETAINER	O/S Damaged	210.20 FL	*105.10 FL
29	1		*REAR BUMPER REINFORCEMENT	Dented	395.10 FL	*395.10 FL
30	1		*REAR BUMPER REINFORCEMENT BRACKET	O/S Dented	180.20 FL	*90.10 FL
31	1		*BOOTLID	Buckled	756.10 FL	*756.10 FL
32	1		*BOOTLID REFLECTOR	Not Necessary	385.00 FL	*- FL
33	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
34	1		*BOOTLID EMBLEM COROLLA	Necessary	70.00 FL	*70.00 FL
35	1		*BOOTLID EMBLEM ALTIS	Necessary	70.00 FL	*70.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*BOOT LID HINGE	Not Necessary	140.00 FL	*- FL
37	1		*BOOTLID TOP LOCK	Not Necessary	318.10 FL	*- FL
38	1		*BOOTLID LOWER LOCK	Not Necessary	20.00 FL	*- FL
39	1		*BOOTLID WEATHERSTRIP	Cut	195.00 FL	*195.00 FL
40	1		*TAILLAMP	O/S Cut	930.00 FL	*391.00 FL
41	1		*TAILLAMP PANEL RH	Repair	198.00 FL	*- FL
42	2		*TAILLAMP LOWER BRACKET	Not Necessary	230.20 FL	*- FL
43	1		*REAR FENDER RH	Distorted	987.00 FL	*987.00 FL
44	2		*REAR FENDER INNER COWLING	Torn	700.40 FL	*172.00 FL
45	2		*REAR FENDER INNER TRIM	Not Necessary	1,540.20 FL	*- FL
46	1		*REAR WINDSCREEN MOULDING	Necessary	163.00 FL	*163.00 FL
47	1		*REAR END PANEL	Distorted	695.30 FL	*695.30 FL
48	1		*REAR END PANEL TOP GARNISH	Not Necessary	250.10 FL	*- FL
49	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	271.10 FL	*- FL
50	1		*REAR FLOOR PANEL	Not Necessary	940.20 FL	*- FL
51	1		*REAR FLOOR SIDE PANEL RH	Repair	294.60 FL	*- FL
52	1		*REAR CHASSIS MEMBER RH	Repair	650.30 FL	*- FL
53	1		*CENTER EXHAUST	Not Necessary	1,942.60 FL	*- FL
54	1		*CENTER EXHAUST INSULATOR	Not Necessary	163.20 FL	*- FL
55	1		*SET CENTER EXHAUST GASKET	Not Necessary	47.30 FL	*- FL
56	1		*REAR EXHAUST PIPE	Bent	930.20 FL	*786.00 FL
57	1		*REAR EXHAUST INSULATOR	Not Necessary	147.10 FL	*- FL
58	1		*REAR EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
59	4		*REAR EXHAUST MOUNTING	Not Necessary	220.40 FL	*- FL
60	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*50.00 FS
61	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
62	1		*SET FRONT RADIATOR GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
63	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
64	1		*BONNET LOCK BRACE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
65	1		*SET BONNET INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
66	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
67	1		*SET RADIATOR TOP COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
68	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
69	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
70	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
71	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
72	1		*SET TAILLAMP CLIPS	Necessary	60.00 FS	*10.00 FS
73	1		*TAILLAMP PANEL SEALANT RH	Not Necessary	60.00 FS	*- FS
74	1		*REAR FENDER SEALANT RH	Necessary	150.00 FS	*50.00 FS
75	1		*SET REAR FENDER COWLING CLIPS	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
77	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
78	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
79	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
80	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
81	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
82	1		*BREAKDOWN TRIANGLE SIGN	Not Necessary	180.00 FS	*- FS
83	1		*SET REVERSE SENSOR	Missing	220.00 FS	*200.00 FS
84	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>33,962.20</b>	<b>16,446.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	7,773.05	3,959.03
<b>Total Parts (\$\$)</b>	<b>26,189.15</b>	<b>12,487.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,200.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	400.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
5	REFOCUS HEADLAMP BEAM	New	60.00	30.00
6	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,200.00	1,300.00
7	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,300.00
8	TUFF COAT	New	250.00	100.00
9	WIRING CHECK	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	REMOVE AND REFIT REAR WINDSCREEN	New	250.00	120.00
14	TRANFER BOOTLID MECHANISM	New	80.00	80.00
15	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
16	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
17	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,570.00</b>	<b>4,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >