

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002496/UPA3Q2
Date: 30/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900148704
Claimant Vehicle No :	SLE3489K	Insured Vehicle No :	SMW5699B
Date of Loss:	21/02/2021	Nature of Claim:	TP
		Claim No:	4629071278SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3489K	Engine No:	3A92UHL8559
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH000554
Reg. Date:	25/03/2019 (Man. Year: 2018)	Odometer:	27424 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,133.66	4,875.50	7,258.16	59.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,650.00	1,320.00	33.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,103.66	7,525.50	8,578.16	53.27
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	16,103.66	6,000.00	10,103.66	62.74
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		6,800.00		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 23/02/2021

Estimated Period of Repair: 7.0 days

Inspected At: Zoom Autowerks Pte Ltd (Bedok)
130 Bedok Reservoir Road, #08-1339
Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	758.40 FL	*748.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	130.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	156.00 FL	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
5	1		*REAR BOOTLID PANEL	Dented / Bent	876.50 FL	*791.00 FL
6	1		*REAR BOOTLID CHROME MOULDING	Cracked	318.50 FL	*285.00 FL
7	1		*REAR BOOTLID INNER LOCK	Bent	286.40 FL	*218.00 FL
8	1		*REAR BOOTLID CATCH	Not Necessary	38.70 FL	*- FL
9	1		*REAR BOOTLID LOGO	Necessary	98.20 FL	*69.00 FL
10	1		*REAR BOOTLID NAME PLATE (MIVEC)	Necessary	78.40 FL	*25.00 FL
11	1		*REAR BOOTLID NAME PLATE (ATTRAGE)	Necessary	95.60 FL	*21.00 FL
12	1		*REAR BOOTLID WEATHERSTRIP	Twisted	210.50 FL	*157.00 FL
13	1		*REAR BOOTLID KEYLESS SENSOR	Cracked	286.20 FL	*91.00 FL
14	2		*REAR TAILLAMPS	Cracked	1,370.80 FL	*670.00 FL
15	1		*REAR TAILLAMP PANEL	Repair	620.00 FL	*- FL
16	1		*REAR END PANEL	Badly Dented	825.40 FL	*425.00 FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	215.80 FL	*148.00 FL
18	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
19	2		*REAR FENDER	Repair	1,572.00 FL	*- FL
20	1		*REAR FENDER INNER TRIM GARNISH	N/S Deformed	771.40 FL	*242.00 FL
21	1		*REAR FENDER INNER TRIM GARNISH CLIPS	Not Necessary	80.00 FL	*- FL
22	2		*REAR FENDER INNER SHIELD	Not Necessary	352.00 FL	*- FL
23	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Torn	265.40 FL	*255.00 FL
25	2		*REAR SPARE TYRE TOP BOARD FOAM	Not Necessary	651.20 FL	*- FL
26	1		*REAR SPARE TYRE PANEL	Repair	980.00 FL	*- FL
27	1		*REAR TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
28	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
30	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR BUMPER LOWER SPOILER (ACCESSORIES)	Cracked	850.00 FS	*850.00 FS
32	2		*REAR EXHAUST MUFFLER CHROME	Not Necessary	510.00 FS	*- FS
33	1		*REAR NUMBER PLATE W/BASE GARNISH	Serviceable	80.00 FS	*- FS
34	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	1,100.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,600.00	1,260.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	150.00	0.00
5	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH	New	150.00	60.00
6	TO REMOVE & INSTALL REAR FENDERS TRIM ,GARNISH	New	150.00	80.00
7	TO RE-POSITION & ALIGN REVERSE SENSOR	New	120.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	80.00
			Gross Labour Cost (\$\$)	3,970.00
				2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >