

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21002498/R1GS3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMR8643T	Insured Vehicle No :	GBG1535G
Date of Loss:	20/02/2021	Nature of Claim:	TP
		Claim No:	4244022482SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8643T	Engine No:	CZCC03892
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZAUZKW154804
Reg. Date:	26/01/2020 (Man. Year: 2019)	Odometer:	10602 km
Colour:	Red		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,612.26	4,865.61	746.65	13.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,580.00	4,140.00	2,440.00	37.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,192.26	9,005.61	3,186.65	26.14
+ GST 7.00/7.00% (S\$)	853.46	630.39	223.07	26.14

Nett Amount (S\$)	13,045.72	9,636.00	3,409.72	26.14
+ Car Rental (6.0 x S\$80.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,151.60		

INSPECTION

Date of Assignment: 25/02/2021

Date Inspected: 25/02/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,247.94 FS	*1,247.94 FS
2	1		*SUPPORT PART (BUMPER INNER BRACKET RH)	Serviceable	57.27 FS	*- FS
3	1		*GUIDE PIECE (BUMPER SIDE BRACKET RH)	Serviceable	21.92 FS	*- FS
4	1		*FENDER	Bent	623.70 FS	*623.70 FS
5	1		*CROSS SUPPORT RHS FENDER BRACKET	Bent	33.22 FS	*33.22 FS
6	4		*RIVETTED CAP NUT	Necessary	9.12 FS	*9.12 FS
7	1		*WHEELHOUSE LINER RHS FENDER LINER UPPER	Serviceable	178.34 FS	*- FS
8	1		*WHEELHOUSE LINER RHS FENDER LINER LOWER	Serviceable	88.41 FS	*- FS
9	1		*LED HEADLIGHT	Cracked	2,759.41 FS	*2,759.41 FS
10	1		*STEUERG H/LAMP CONTROL UNIT	Serviceable	400.71 FS	*- FS
11	1		*SENSOR BRACKET	Necessary	12.86 FS	*12.86 FS
12	2		*SENSOR BRACKET	Necessary	24.78 FS	*24.78 FS
13	1		*SENSOR BRACKET	Necessary	12.86 FS	*12.86 FS
14	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
15	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
					Total Parts (S\$)	5,612.26
						4,865.61

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	LABOUR	New	2,520.00	1,680.00
5	SPRAY PAINTING	New	3,200.00	1,600.00
Gross Labour Cost (S\$)			6,580.00	4,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >