

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002499/NBA3Q2
Date: 11/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993764
Claimant Vehicle No :	SHA3891A	Insured Vehicle No :	GBG8377A
Date of Loss:	22/02/2021	Nature of Claim:	TP
		Claim No:	9607762458SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3891A	Engine No:	G4LEKU399134
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVLU186596
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	186679 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	Davanti 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	Davanti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,726.44	3,726.44	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,750.00	350.00	16.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,826.44	5,476.44	350.00	6.01
+ GST 7.00/7.00% (S\$)	407.85	383.35	24.50	6.01

Nett Amount (S\$)	6,234.29	5,859.79	374.50	6.01
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,743.23		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment:	23/02/2021		
Date Inspected:	23/02/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY -FRONT DOOR RH	Deformed	1,797.20 FL	*1,797.20 FL
2	1		*MOULDING ASSY -W/LINER FRT	Deformed	186.20 FL	*186.20 FL
3	1		*GRIP-FRONT DOOR OUTSIDE R	Deformed	234.80 FL	*234.80 FL
4	1		*MOULDING ASSY W/LINER RR D	Deformed	166.20 FL	*166.20 FL
5	1		*PANEL ASSY -REAR DOOR RH	Deformed	1,789.90 FL	*1,789.90 FL
6	1		*MOULDING ASSY -SIDE SILL R	Deformed	290.00 FL	*290.00 FL
7	1		*FRT DOOR LOGO COMFORTDELG	Necessary	75.00 FS	*75.00 FS
8	1		*APP LOGO REAR DOOR L/R CT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,619.30	4,619.30
- List Item Discount on L Items 20.00/20.00% (S\$)	892.86	892.86
Total Parts (S\$)	3,726.44	3,726.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	60.00	60.00
2	PANEL BEATING (REPAIR RR FENDER RH)	New	900.00	700.00
3	SPRAYPAINT ON AFFECTED AREA	New	850.00	850.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	40.00
5	TRANSFER OF DOOR FRT RH	New	120.00	50.00
6	TRANSFER OF DOOR REAR RH	New	120.00	50.00
			Gross Labour Cost (S\$)	2,100.00
				1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >