

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002511/KTF3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00068162001
Claimant Vehicle No :	SLZ4154J	Insured Vehicle No :	YN768Z
Date of Loss:	20/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D201005/C02/CHUAKK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ4154J	Engine No:	P520503542
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8J0213891
Reg. Date:	30/04/2018 (Man. Year: 2018)	Odometer:	25674 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,630.02	3,188.08	5,441.94	63.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,100.00	1,980.00	64.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,710.02	4,288.08	7,421.94	63.38
Approved Total (Overridden) (S\$)		3,400.00		
	(S\$)	11,710.02	3,400.00	8,310.02
+ GST 7.00/7.00% (S\$)	819.70	238.00	581.70	70.96
Nett Amount (S\$)	12,529.72	3,638.00	8,891.72	70.97

INSPECTION

Date of Assignment:	25/02/2021	
Date Inspected:	23/02/2021	Inspected At:
Estimated Period of Repair:	4.0 days	

S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ)
 BLK 8 SIN MING IND EST #01-64/66
 Singapore 575643

3/10/2021

Adjuster Report

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2021)
Parts:	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ4154J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Broken	2,295.00 FL	*1,075.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Cracked	28.00 FL	*28.00 FL
3	1		*FRONT BUMPER	Buckled/Cracked	1,025.00 FL	*925.20 FL
4	1		*FRONT BUMPER TOP	Repair	170.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	56.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	56.00 FL	*- FL
7	1		*FRONT BUMPER BRACKET LH	Cracked	43.00 FL	*43.00 FL
8	1		*FRONT BUMPER FOGLAMP COVER LH	Mtg Cracked	149.30 FL	*149.30 FL
9	1		*FRONT BUMPER FOGLAMP	Mtg Cracked	318.50 FL	*318.50 FL
10	1		*FRONT BUMPER LOWER GRILLE	Serviceable	452.00 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING	Serviceable	106.48 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	410.00 FL	*410.00 FL
13	1		*FRONT BUMPER LOWER GARNISH	Serviceable	36.00 FL	*- FL
14	1		*FRONT GRILLE LOGO	Necessary	31.20 FL	*31.20 FL
15	1		*FRONT GRILLE	Mtg Cracked	522.00 FL	*380.40 FL
16	1		*FRONT GRILLE CHROME LH	Dented	142.20 FL	*142.20 FL
17	1		*FRONT GRILLE CHROME RH	Serviceable	142.20 FL	*- FL
18	1		*FRONT FENDER LH	Repair	325.00 FL	*- FL
19	1		*FRONT FENDER INNER SHIELD LH	Serviceable	158.00 FL	*- FL
20	1		*BONNET	Repair	736.20 FL	*- FL
21	1		*BONNET RUBBER	Serviceable	53.60 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Serviceable	355.40 FL	*- FL
23	1		*RADIATOR	Serviceable	745.00 FL	*- FL
24	1		*AIR CON CONDENSOR	Serviceable	487.20 FL	*- FL
25	1		*FRONT NUMBER PLATE GARNISH	Serviceable	55.00 FL	*- FL
26	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*FRONT SUPPORT PANEL CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*FRONT NO PLATE	Serviceable	50.00 FS	*- FS
31	1		*COOLANT	Not Necessary	50.00 FS	*- FS
32	1		*FRONT BUMPER BRACKET RH	Cracked	43.00 FL	*43.00 FL
33	1		*FRONT FOG LAMP COVER BRACKET LH	Cracked	135.30 FL	*135.30 FL
34	1		*FRONT REINFORCEMENT PLASTIC	Cracked	179.00 FL	*179.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,555.58	3,960.10
- List Item Discount on L Items 10.00/20.00% (\$\$)	925.56	772.02
Total Parts (\$\$)	8,630.02	3,188.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,200.00	480.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,400.00	600.00
3	CHECK AND REPAIR WIRING SYSTEM	New	120.00	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	120.00	0.00
5	R&R RADIATOR TO ASSIST REPAIR	New	120.00	0.00
6	R&R AIRCON CONDENSOR & CHARGE UP GAS	New	120.00	0.00
Gross Labour Cost (\$\$)			3,080.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >