

S THREE AUTOMOTIVE RECOVERY PTE LTD
 Blk 8 Sin Ming Industrial Estate
 #01-64/66 Singapore 575643
 Tel : 6284 1542 / 6284 1575
 Fax : 6487 5315
 sthreeautomotive@gmail.com

Not Notain!
 1/10/83804
 Recovery After Pain
 4 days

TO :
 ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : YN768Z

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

CONTACT : _____

NAME : TAN TEE WAH

ADDRESS : _____

LICENSE NO. : SLZ4154J

CHASSIS NO. : _____

MAKE / MODEL : MAZDA 3

ENGINE NO. : _____

OWNER'S INSURER : MSIG INSURANCE

ACCIDENT DATE : 20-Feb-21

JOB-CODE : TP

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC. PRICE	SUR. DISP	REV. PRICE
1 FRONT HEADLAMP LH 1075.00	1.00	2295.00	10.00	2065.50	Y	✓
2 FRONT HEADLAMP LOWER BRACKET LH	1.00	28.00	10.00	25.20	Y	✓
3 FRONT BUMPER 925.20	1.00	1025.00	10.00	922.50	Y	✓
4 FRONT BUMPER TOP	1.00	170.00	10.00	153.00	Y	✗
5 FRONT BUMPER SIDE RETAINER LH	1.00	56.00	10.00	50.40	Y	✗
6 FRONT BUMPER SIDE RETAINER RH	1.00	56.00	10.00	50.40	Y	✗
7 FRONT BUMPER BRACKET LH	1.00	43.00	10.00	38.70	Y	✓
8 FRONT BUMPER FOGLAMP COVER LH	1.00	149.30	10.00	134.37	Y	✓
9 FRONT BUMPER FOG LAMP	1.00	318.50	10.00	286.65	Y	✓
10 FRONT BUMPER LOWER GRILLE	1.00	452.00	10.00	406.80	Y	✗
11 FRONT BUMPER LOWER GRILLE CHROME MOULDING	1.00	106.48	10.00	95.83	Y	✗
12 FRONT BUMPER REINFORCEMENT	1.00	410.00	10.00	369.00	Y	✓
13 FRONT BUMPER LOWER GARNISH	1.00	36.00	10.00	32.40	Y	✗
14 FRONT GRILLE LOGO	1.00	31.20	10.00	28.08	Y	✓
15 FRONT GRILLE 380.40	1.00	522.00	10.00	469.80	Y	✓
16 FRONT GRILLE CHROME LH	1.00	142.20	10.00	127.98	Y	✓
17 FRONT GRILLE CHROME RH	1.00	142.20	10.00	127.98	Y	✗
18 FRONT FENDER LH	1.00	325.00	10.00	292.50	Y	✗
19 FRONT FENDER INNER SHIELD LH	1.00	158.00	10.00	142.20	Y	✗
20 BONNET	1.00	736.20	10.00	662.58	Y	✗
21 BONNET RUBBER	1.00	53.60	10.00	48.24	Y	✗
22 FRONT SUPPORT PANEL	1.00	355.40	10.00	319.86	Y	✗
23 RADIATOR	1.00	745.00	10.00	670.50	Y	✗
24 AIR CON CONDENSOR	1.00	487.20	10.00	438.48	Y	✗
25 FRONT NUMBER PLATE GARNISH	1.00	55.00	10.00	49.50	Y	✓

TOTAL (PARTS) :

8898.28

8008.45

201

SPECIAL NETT ITEM

1	FRONT FENDER INNER SHIELD CLIPS	1.00	na	50.00	0.00	50.00	Y	X
2	FRONT BUMPER CLIPS	1.00	na	50.00	0.00	50.00	Y	✓
3	FRONT SUPPORT PANEL CLIPS	1.00	na	50.00	0.00	50.00	Y	X
4	FRONT GRILLE CLIPS	1.00	na	50.00	0.00	50.00	Y	2
5	FRONT NO. PATE	1.00	sh	50.00	0.00	50.00	Y	X
6	COOLANT	1.00	na	50.00	0.00	50.00	Y	X
TOTAL (PARTS) :				300.00		300.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00		1200.00	0.00	1200.00	Y	48cl
2	SPRAY PAINTING ON ACCIDENT AREAS	1.00		1400.00	0.00	1400.00	Y	60cl
3	CHECK AND REPAIR WIRING SYSTEM	1.00		120.00	0.00	120.00	Y	2cl
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	1.00	na	120.00	0.00	120.00	Y	X
5	R&R RADIATOR TO ASSIST REPAIR	1.00	na	120.00	0.00	120.00	Y	X
6	R&R AIRCON CONDENSOR & CHARGE UP GAS	1.00	na	120.00	0.00	120.00	Y	X
TOTAL (LABOUR) :				3080.00		3080.00		

TOTAL PARTS & LABOUR 12278.28 11388.45

EXCESS : S\$

NO. OF DAY : 04 days

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : 23/2/21

SURVEY BY : Kenneth

CONTACT NO :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

Supplement

- 1) Front Bumper Bracket RH
- 2) Front Fog lamp Cover Bracket LH
- 3) Front Reinforcement Plastic

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : YN768Z

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR

JOB NO. : _____

NAME : TAN TEE WAH
ADDRESS :

CONTACT :

LICENSE NO. : SLZ4154J
MAKE / MODEL : MAZDA 3
OWNER'S INSURER : MSIG INSURANCE
JOB-CODE : TP

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 20-Feb-21

SUPPLEMENTARY
CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER BRACKET RH	1.00	\$ 43.00	10.00	\$ 38.70	Y	✓
2 FRONT FOG LAMP COVER BRACKET LH	1.00	\$ 135.30	10.00	\$ 121.77	Y	✓
3 FRONT REINFORCEMENT PLASTIC	1.00	\$ 179.00	10.00	\$ 161.10	Y	✓

EXCESS : : S\$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.