LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG21002512/AQF3E2

Singapore 079120 Date: 11/08/2021

REFERENCE

Insured/Claimant: Zhang Hong Wei Policy No: 1800028155

Date of Loss: 17/02/2021 Nature of Claim: OD Claim No: 2012426564SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK6817U

Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: CVK050358

Reg. Date: 19/03/2018 (Man. Year: 2017) Chassis No: WAUZZZF48JA072634

Colour: Black Odometer: 25769 km

Engine Capacity: 1984 cc
Market Value/New Car Price: \$\$115,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		29,356.00	7,067.12	22,288.88	75.93
Miscellaneous Items		0.00	0.00	0.00	
Labour		28,614.00	7,342.00	21,272.00	74.34
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	57,970.00	14,409.12	43,560.88	75.14
	- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
	(S\$)	56,870.00	13,309.12	43,560.88	76.60
	+ GST 7.00/7.00% (S\$)	3,980.90	931.64	3,049.26	76.60
	Nett Amount (S\$)	60,850.90	14,240.76	46,610.14	76.60

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 23/02/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,181.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*REAR BUMPER GUIDE SECTION CENTER	Not Necessary	44.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	46.00 FS	*- FS
5	1		*SIDE PANEL FRAME LH	Repair	3,034.00 FS	*- FS
6 7	1		*REAR WINDOW	Not Necessary	1,154.00 FS	*- F5
<i>r</i> 8	1 1		*SIDE WINDOW LH *SILL TRIM STRIP LH	Not Necessary Not Necessary	616.00 FS 120.00 FS	- F3 *- F3
9	1		*REAR WHEEL HOUSING LINER LH	Not Necessary	240.00 FS	*- F
10	1		*REAR WHEEL HOUSING LINER ATTACHMENT PART (NPA)	Not Necessary	0.00 FS	*-F
11	1		*REAR DOOR LH	Dented	3,192.00 FS	*2,553.60 F
12	1		*REAR DOOR OUTER SEAL LH	Necessary	205.00 FS	*164.00 F
13	1		*BONDING AGENT	Not Necessary	49.00 FS	*- F
14	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- F\$
15	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
16	1		*REAR DOOR SEALING STRIP LH	Not Necessary	17.00 FS	*- FS
17 18	1		*REAR DOOR ATTACHMENT PARTS LH (NPA) *REAR DOOR CATCH LH	Not Necessary Not Necessary	0.00 FS 120.00 FS	*- F\$ *- F\$
19	1		*REAR DOOR HANDLE LH	Repair	88.00 FS	*-FS
19 20	1		*REAR DOOR HANDLE TRIM LH - INNER	Not Necessary	8.00 FS	*- FS
21	1		*REAR DOOR HANDLE LH COVER	Not Necessary	6.00 FS	*-FS
22	1		*FRONT DOOR LH	Dented		*2,553.60 FS
23	1		*FRONT OUTER DOOR SEAL LH	Necessary	205.00 FS	*164.00 FS
24	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
25	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
26	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
27	1		*FRONT DOOR ATTACHMENT (NPA)	Not Necessary	0.00 FS	*- FS
28	1		*FRONT DOOR CATCH LH	Not Necessary	105.00 FS	*- F\$
29	1 1		*FRONT DOOR HANDLE LH *FRONT DOOR HANDLE TRIM LH - INNER	Not Necessary	88.00 FS 8.00 FS	*- F\$ *- F\$
30 31	1		*FRONT DOOR HANDLE LH COVER	Not Necessary Not Necessary	6.00 FS	*-F
31 32	1		*FRONT DOOR MOUNTING BAR	Not Necessary	164.00 FS	*- FS
33	1		*FRONT WING MIRROR MOUNTING LH	Cut	1,089.00 FS	*871.20 F
34	1		*FRONT WING MIRROR CAP - LH	Repair	289.00 FS	*-F
35	1		*FRONT FENDER LH	Dented	767.00 FS	*613.20 FS
36	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	202.00 FS	*- FS
37	1		*FRONT FENDER BRACE LH	Not Necessary	118.00 FS	*- FS
38	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	240.00 FS	*- FS
39	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS LH (NPA)	Not Necessary	0.00 FS	*-FS
40	1		*FRONT FENDER FLEDGE COVER LONG LH	Not Necessary	31.00 FS	*- FS
41	1		*FRONT FENDER FLEDGE COVER LH SHORT	Not Necessary	23.00 FS	*-FS
42	1		*FRONT WHEEL STONE CHIP GUARD	Cut	51.00 FS	*40.32 FS
43	1		*LED HEADLIGHT LH	Not Necessary	7,693.00 FS	*-FS
44 45	2		*ALUMINIUM RIM LH FRONT / REAR *ACRYLIC SEALANT	Not Necessary	2,284.00 FS	*- FS
45 46	1		*ACRYLIC SEALANT *CAVITY WAX	Not Necessary Not Necessary	180.00 FS 140.00 FS	*- F3
4 0 47	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
48	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
49	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*-FS
50	1		*REAR WS SEALANT	Not Necessary	200.00 FS	*- FS
51	1		*SUNDRIES	Necessary	400.00 FS	*107.20 FS
		part. S=Spc		- ,		

Report was unsubmitted during this print-out.

No. Qty Part No. Particulars	Condition	Repairer's	Amount
	Total Parts (S\$)	29,356.00	7,067.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Labour Items 1 TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE 2 TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL 3 TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS 4 TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS 5 TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT 6 TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER 7 TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR 8 TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES 9 TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	360.00	
SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	360.00	
FENDER RENEWAL TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL			360.00
TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	600.00	0.00
5 TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT 6 TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER 7 TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR 8 TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES 9 TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	400.00	0.00
BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	200.00	0.00
 TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL 	New	1,400.00	0.00
REPAIR TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	800.00	0.00
DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	2,400.00	0.00
BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL	New	700.00	700.00
AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. RE INSTALL ALL PARTS REMOVED	New	10,500.00	2,750.00
10 TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, LHS FRONT FENDER, FRONT BUMPER, LHS WING MIRROR COVER, DOOR HANDLES, DOOR ENTRANCES, ROOF CHANNEL, LHS SILL PANEL, LHS B-PILLAR, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK	New	8,950.00	3,100.00
11 TO RENEW LHS FRONT AND LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	240.00
12 TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	192.00
13 TO REMOVE AND REINSTALL REAR SEAT, BACK REST HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS	New	1,400.00	0.00
Gross Labour C	Cost (S\$)	28,614.00	7,342.00
Report was unsubmitted during this pri			

< END OF ESTIMATES >