

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC6/AIG21002517/ABS3Q2

**Date:**

14/09/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800058523

**Claimant Vehicle No :** SMG8497G**Insured Vehicle No :**

SLZ9150L

Date of Loss: 14/02/2021

Nature of Claim:

TP

Claim No:

8550682649SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMG8497G**

Make &amp; Model: MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)

Engine No: P520377529

Reg. Date: 28/04/2017 (Man. Year: 2016)

Chassis No: JM6DJ2HAA01101044

Colour: Purple

Odometer: 34032 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 8,426.88          | 5,908.88          | 2,518.00          | 29.88         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,310.00          | 2,220.00          | 1,090.00          | 32.93         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>11,736.88</b>  | <b>8,128.88</b>   | <b>3,608.00</b>   | <b>30.74</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>6,500.00</b>   |                   |               |

|                                                 |                  |                 |                 |              |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| (S\$)                                           | 11,736.88        | 6,500.00        | 5,236.88        | 44.62        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 821.58           | 455.00          | 366.58          | 44.62        |
| <b>Nett Amount (S\$)</b>                        | <b>12,558.46</b> | <b>6,955.00</b> | <b>5,603.46</b> | <b>44.62</b> |
| <b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b> |                  | 420.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>7,377.00</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>7,300.00</b> |                 |              |

INSPECTION

Date of Assignment: 22/02/2021

Date Inspected: 22/02/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Kang Car Repairers Pte Ltd (HQ)  
 No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit  
 Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BOOT LID                       | Dented        | 1,056.70 FL | *1,056.70 FL |
| 2   | 1   |          | *BOOTLID LOGO                   | Necessary     | 61.20 FL    | *61.20 FL    |
| 3   | 1   |          | *BOOTLID MAZDA 2 EMBLEM         | Necessary     | 58.30 FL    | *58.30 FL    |
| 4   | 1   |          | *BOOTLID SKYACTIV EMBLEM        | Necessary     | 49.80 FL    | *49.80 FL    |
| 5   | 1   |          | *BOOT LID LAMP LH               | Cracked       | 283.70 FL   | *283.70 FL   |
| 6   | 1   |          | *BOOT LID LAMP RH               | Not Necessary | 283.70 FL   | *- FL        |
| 7   | 1   |          | *BOOT LID LOCK                  | Damaged       | 277.10 FL   | *277.10 FL   |
| 8   | 1   |          | *BOOT LID LOCK CHECKER          | Not Necessary | 58.40 FL    | *- FL        |
| 9   | 1   |          | *BOOT LID RUBBER                | Cut           | 188.90 FL   | *188.90 FL   |
| 10  | 1   |          | *BOOT LID AUTO LOCKING          | Not Necessary | 220.70 FL   | *- FL        |
| 11  | 1   |          | *BOOT LID TRIM                  | Cracked       | 199.70 FL   | *199.70 FL   |
| 12  | 1   |          | *REAR WIPER MOTOR               | Damaged       | 456.70 FL   | *456.70 FL   |
| 13  | 1   |          | *TAIL LAMP LH                   | Cracked       | 825.70 FL   | *788.00 FL   |
| 14  | 1   |          | *TAIL LAMP RH                   | Not Necessary | 825.70 FL   | *- FL        |
| 15  | 1   |          | *REAR FENDER TRIM LH            | Deformed      | 288.60 FL   | *288.60 FL   |
| 16  | 1   |          | *REAR FENDER TRIM RH            | Not Necessary | 288.60 FL   | *- FL        |
| 17  | 1   |          | *REAR PANEL                     | Dented        | 688.90 FL   | *530.00 FL   |
| 18  | 1   |          | *REAR PANEL TRIM                | Deformed      | 138.70 FL   | *138.70 FL   |
| 19  | 1   |          | *SPARE TYRE SPONGE              | Cracked       | 291.70 FL   | *291.70 FL   |
| 20  | 1   |          | *SPARE TYRE COVER               | Deformed      | 388.30 FL   | *388.30 FL   |
| 21  | 1   |          | *REAR BUMPER                    | Distorted     | 958.10 FL   | *893.00 FL   |
| 22  | 2   |          | *REAR BUMPER LOWER BRACKET      | Deformed      | 119.20 FL   | *119.20 FL   |
| 23  | 2   |          | *REAR BUMPER SIDE RETAINER      | Necessary     | 133.80 FL   | *133.80 FL   |
| 24  | 2   |          | *REAR NUMBER PLATE LAMP         | Cracked       | 170.20 FL   | *170.20 FL   |
| 25  | 1   |          | *REAR BUMPER REFLECTOR COVER LH | Not Necessary | 58.70 FL    | *- FL        |
| 26  | 1   |          | *SET BOOT LID TRIM CLIPS        | Not Necessary | 40.00 FS    | *- FS        |
| 27  | 1   |          | *REAR WINDSCREEN SEAL           | Necessary     | 60.00 FS    | *40.00 FS    |
| 28  | 1   |          | *REAR WINDSCREEN SEALANT        | Necessary     | 60.00 FS    | *40.00 FS    |
| 29  | 1   |          | *SET REAR FENDER TRIM CLIPS LH  | Necessary     | 60.00 FS    | *30.00 FS    |
| 30  | 1   |          | *SET REAR FENDER TRIM CLIPS RH  | Not Necessary | 60.00 FS    | *- FS        |
| 31  | 1   |          | *SET REAR PANEL TRIM CLIPS      | Necessary     | 40.00 FS    | *20.00 FS    |
| 32  | 1   |          | *REAR NUMBER PLATE              | Bent          | 50.00 FS    | *50.00 FS    |
| 33  | 1   |          | *SET REAR BUMPER CLIPS          | Necessary     | 60.00 FS    | *30.00 FS    |
| 34  | 1   |          | *SET REVERSE SENSORS            | Damaged       | 250.00 FS   | *200.00 FS   |
| 35  | 1   |          | *REVERSE CAMERA                 | Damaged       | 480.00 FS   | *380.00 FS   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's | Amount    |
|-----|-----|----------|----------------------------------|---------------|------------|-----------|
| 36  | 1   |          | *REAR WINDSCREEN VIDEO CAMERA    | Not Necessary | 500.00 FS  | *- FS     |
| 37  | 1   |          | *WEEK END SEAL                   | Necessary     | 30.00 FS   | *20.00 FS |
| 38  | 1   |          | *REAR BUMPER LOWER TRIM CLIPS LH | Not Necessary | 40.00 FS   | *- FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>10,101.10</b> | <b>7,183.60</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 1,674.22         | 1,274.72        |
| <b>Total Parts (\$)</b>                                  | <b>8,426.88</b>  | <b>5,908.88</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                 | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                                             |          |                 |                 |
| 1                               | TO CHECK WIRING                                                                                             | New      | 50.00           | 30.00           |
| 2                               | TO REMOVE AND REFIT REAR WINDSCREEN VIDEO CAMERA                                                            | New      | 80.00           | 50.00           |
| 3                               | TO REMOVE AND REFIT THIRD BRAKE LIGHT                                                                       | New      | 80.00           | 0.00            |
| 4                               | TO REMOVE AND REFIT REAR CAMERA                                                                             | New      | 80.00           | 50.00           |
| 5                               | TO REMOVE AND REFIT INNER TRIM                                                                              | New      | 120.00          | 60.00           |
| 6                               | TO REMOVE AND REFIX REAR EXHAUST PIPE                                                                       | New      | 150.00          | 0.00            |
| 7                               | TO REMOVE AND REFIT REVERSE SENSOR                                                                          | New      | 80.00           | 50.00           |
| 8                               | TO SPRAY UNDERSEAL                                                                                          | New      | 150.00          | 60.00           |
| 9                               | (REAR) TO SPRAY PAINTING                                                                                    | New      | 1,200.00        | 1,000.00        |
| 10                              | TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS | New      | 1,200.00        | 800.00          |
| 11                              | TO REMOVE AND REFIT REAR WINDSCREEN                                                                         | New      | 120.00          | 120.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                             |          | <b>3,310.00</b> | <b>2,220.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >