

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002520/KGA3Q2
Date: 19/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070163098
Claimant Vehicle No :	SMG8562B	Insured Vehicle No :	SMW3503X
Date of Loss:	19/02/2021	Nature of Claim:	TP
		Claim No:	9754551820SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8562B	Engine No:	G4FGJH711645
Make & Model:	KIA CERATO, 1.6 SX (A)	Chassis No:	KNAF3416MK5021809
Reg. Date:	03/01/2019 (Man. Year: 2018)	Odometer:	14515 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,335.20	1,141.10	3,194.10	73.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	665.00	565.00	45.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,565.20	1,806.10	3,759.10	67.55
+ GST 7.00/7.00% (S\$)	389.56	126.43	263.13	67.55

Nett Amount (\$)	5,954.76	1,932.53	4,022.23	67.55
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 25/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming AutoCare
Singapore 575721

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	633.00 FL	*633.00 FL
2	1		*FRONT BUMPER SPONGE	*Check	84.00 FL	*- FL
3	1		*FRONT BUMPER CENTRE GARNISH	Buckled	484.00 FL	*484.00 FL
4	1		*FRONT BUMPER CENTRE PARKING SENSOR	*Check	163.00 FL	*- FL
5	1		*RADIATOR GRILLE	Serviceable	328.00 FL	*- FL
6	1		*EMBLEM FRONT CENTRE BADGE	Serviceable	32.00 FL	*- FL
7	20		*FRONT BUMPER CLIPS	Necessary	100.00 FL	*100.00 FL
8	1		*FRONT TOWING COVER	Cracked	12.00 FL	*12.00 FL
9	1		*FRONT BUMPER TOP COVER	Serviceable	38.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	*Check	497.00 FL	*- FL
11	1		*HEADLAMP L/R	Serviceable	2,210.00 FL	*- FL
12	1		*FRONT BUMPER LOWER GARNISH	Serviceable	197.00 FL	*- FL
13	1		*NO PLATE	Bent	35.00 FS	*35.00 FS
					Sub Total (\$\$)	4,813.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	477.80
					Total Parts (\$\$)	4,335.20
						1,264.00
						1,141.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	30.00	15.00
2	TO DISMANTLE AND INSTALL DAMAGE PARTS ,TO KNOCK AND REPAIR FRONT AND REAR AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME	New	600.00	250.00
3	TO SPRAY FRONT AND REAR BUMPER	New	600.00	400.00
Gross Labour Cost (S\$)			1,230.00	665.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >