



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD UNKNOWN (SCW6266D)
Date of Loss	22 February 2021
Time of Loss	11.50
Loss Description	SLE8333T (insd)>> SCW6266D (TP) > SHB2437E
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="24865"/>
Nett Loss Amount	\$20,135.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Vehicle & Driver Details

Vehicle Registration# SCW6266D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

10/02/2009



Mileage

311762

Age of Vehicle

12

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		2009
Make	TPVD	TOYOTA

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CHOO KELVIN	
Date of Birth		dd/mm/yyyy

Model CATEGORY	UNKNOWN POLICY INFORMATION	WISH 1.8 AUTO ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JTDER12W103001904"/>
Engine No		<input type="text" value="1ZZ3228203"/>
Engine Capacity		<input type="text" value="1794"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="45000"/>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	TBC, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/65R15

Rear Tyre Size

195/65R15

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

25

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BONNET	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BONNET CHROME	Cracked	0	254.43	No		25			190.82	Reviewing
<input type="checkbox"/>		0	1		FRONT BONNET UNDER RUBBER SEAL	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		SET FRONT BONNET UNDERCOVER CLIP	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BONNET LOCK	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		FRONT BONNET HINGE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TOYOTA CENTRE LOGO	Serviceable	0	0	No		25			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	2		HEADLAMP	Cracked	0	670.1	No		25			1005.15	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER	Dented	0	498.1	No		25			373.58	Reviewing
<input type="checkbox"/>		0	2		FRONT BUMPER SIDE RETAINER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER REINFORCEMENT	Dented	0	366.1	No		25			274.58	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER SPONGE	Damaged	0	131.2	No		25			98.4	Reviewing
<input type="checkbox"/>		0	1		SET FRONT BUMPER CLIP	Necessary	0	50	No		25			37.5	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER LOWER GRILLE	Damaged	0	125.6	No		25			94.2	Reviewing
<input type="checkbox"/>		0	2		FOGLAMP COVER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILLE	Cracked	0	161.8	No		25			121.35	Reviewing
<input type="checkbox"/>		0	1		FRONT FENDER (LH)	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL TOP GARNISH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RADIATOR	Serviceable	0	0	No		25			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		RADIATOR LOWER UNDERCOVER	Damaged	0	128.54	No		25			96.41	Reviewing
<input type="checkbox"/>		0	1		AIR CON CONDENSER	Bent	0	624.36	No		25			468.27	Reviewing
<input type="checkbox"/>		0	2		HORN	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER	Damaged	0	485.1	No		25			363.83	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE RETAINER O/S	Bent	0	66.5	No		25			49.88	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE RETAINER N/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER REFLECTOR (RH)	Broken	0	89.15	No		25			66.86	Reviewing
<input type="checkbox"/>		0	1		SET REAR BUMPER CLIP	Necessary	0	50	No		25			37.5	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER BRACKET (RH)	Dented	0	90.95	No		25			68.21	Reviewing
<input type="checkbox"/>		0	1		TAILLAMP O/S	Cracked	0	408.1	No		25			306.08	Reviewing
<input type="checkbox"/>		0	1		TAILLAMP N/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILLAMP LOWER RETAINER (RH)	Cracked	0	65	No		25			48.75	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		AIR DUCT (RH)	Damaged	0	85.4	No		25		64.05	64.05	Reviewing
<input type="checkbox"/>		0	1		TAILLAMP LOWER PANEL (RH)	Buckled	0	488.2	No		25		366.15	366.15	Reviewing
<input type="checkbox"/>		0	1		REAR FENDER UNDER GARNISH (RH)	Deformed	0	145.8	No		25		109.35	109.35	Reviewing
<input type="checkbox"/>		0	1		SET REAR FENDER INNER GARNISH CLIP	Serviceable	0	0	No		25		0	0	Deny
<input type="checkbox"/>		0	1		REAR FENDER INNER TRIMBOARD (RH)	Damaged	0	421.1	No		25		315.83	315.83	Reviewing
<input type="checkbox"/>		0	1		SET REAR FENDER INNER TRIMBOARD CLIP	Serviceable	0	0	No		25		0	0	Deny
<input type="checkbox"/>		0	1		REAR BOOT	Bent	0	1209.1	No		25		906.83	906.83	Reviewing
<input type="checkbox"/>		0	1		REAR TOYOTA LOGO	Necessary	0	65.1	No		25		48.83	48.83	Reviewing
<input type="checkbox"/>		0	1		"AEROTOURER" EMBLEM	Necessary	0	85.6	No		25		64.2	64.2	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT INNER LOCK	Serviceable	0	0	No		25		0	0	Deny
<input type="checkbox"/>		0	1		REAR BOOT CATCH	Serviceable	0	0	No		25		0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT INNER TRIMBOARD	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		SET REAR BOOT INNER TRIMBOARD CLIP	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT WEATHERSTRIP	Damaged	0	285.2	No		25			213.9	Reviewing
<input type="checkbox"/>		0	1		END PANEL	Dented	0	600.1	No		25			450.08	Reviewing
<input type="checkbox"/>		0	1		END PANEL TOP GARNISH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		SET REAR WINDSCREEN MOULDING	Necessary	0	128.1	No		25			96.08	Reviewing
<input type="checkbox"/>		0	1		REAR EXHAUST	Bent	0	856.2	No		25			642.15	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TOWING CHARGES	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO CHECK FRONT ELECTRICAL WIRING SYSTEM AND FOCUS HEADLAMPS	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE & REINSTALL RADIATOR, AIR CONDENSER, REFILL AIR CONDENSER, REFILL AIR CONDENSER, REFILL AIR CONDENSER ETC	0	100	0	0	Reviewing	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO REMOVE & REINSTALL REAR BUMPER SENSORS	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO TRANSFER REAR BOOT COMPONENTS FROM OLD BOOT TO NEW BOOT	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE & REINSTALL REAR WINDSCREEN	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE & REINSTALL REAR INNER TRIMS, GARNISHES ETC TO FACILITATE REPAIR	0	80	0	0	Reviewing	
<input type="checkbox"/>		0		TO APPLY ANTI RUSTING COATING ON NEW AND AFFECTED PANELS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE & REINSTALL REAR BOOT TOP SPOILER	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE & REINSTALL REAR EXHAUST	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	0	1100	0	0	Reviewing	
<input type="checkbox"/>		0		TO SPRAY PAINTING ON AFFECTED AREA	0	1500	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 8 DAYS	Reviewing		0		
<input type="checkbox"/>		0	FRONT NUMBER PLATE WITH CASING	Deny		0	SERVICEABLE	
<input type="checkbox"/>		0	RADIATOR COOLANT	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	SET REVERSE	Reviewing		200	SHORTED	

	EDIT	SR NO	SENSOR NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	REVERSE SENSOR WIRE HARNESS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	END PANEL SEALANT	Reviewing		50	NECESSARY	
<input type="checkbox"/>		0	REAR WINDSCREEN SEALANT	Reviewing		40	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$10,478.82

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$6,978.82

Labour

\$0.00

\$3,210.00

Miscellaneous

\$0.00

\$290.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add Approve Deny Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		8300		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$8,300.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$8,300.00

Submit for Review