



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2103086
3 ANSON ROAD #16-00	INV Date	03/05/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21002531/Ara3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SJJ 4828G
Insured Veh.	SMY 1531S
Claim No.	SNM21D201048/LKKDS
Policy No.	DMPCSNW00038542100
Accident Date	23/02/2021
Inspection Date	24/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21002531/Ara3q2 Date: 03/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMY 1531S	Veh. Inspected	SJJ 4828G
Policy No.	DMPCSNW00038542100	Coverage (\$)	0.00
Claim No.	SNM21D201048/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	24/02/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA AIRWAVE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GJ11302961	Colour	BLACK
Odometer	239673 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	SILVERSTONE	6 mm
L/H Front Tyre	195/60 R15	SILVERSTONE	6 mm
R/H Rear Tyre	195/60 R15	SILVERSTONE	6 mm
L/H Rear Tyre	195/60 R15	SILVERSTONE	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	23/02/2021	Inspection Date	24/02/2021
Survey held at	ISHARE AUTO PTE. LTD. 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 4828G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DISTORTED	1,382.50	1,145.00
1	TAILGATE LOGO	NECESSARY	45.20	45.20
2	TAILGATE LAMP @\$289.40	CUT	578.80	578.80
1	TAILGATE CHROME MOULDING	NOT NECESSARY	369.20	-
2	TAILGATE DAMPER @\$89.10	NOT NECESSARY	178.20	-
1	TAILGATE OUTER GARNISH	DEFORMED	451.50	451.50
1	TAILGATE OUTER HANDLE	NOT NECESSARY	160.00	-
1	TAILGATE INNER TRIM	CRACKED	279.50	279.50
1	TAILGATE INNER LOCK	DAMAGED	137.80	137.80
1	TAILGATE WEATHERSTRIP	CUT	193.90	193.90
2	TAILGATE STOPPER @\$19.00	NOT NECESSARY	38.00	-
1	TAILGATE INNER HOLDER	NOT NECESSARY	59.10	-
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	136.70	136.70
2	REAR NUMBER PLATE LAMP @\$62.30	NOT NECESSARY	124.60	-
1	REAR BUMPER	DEFORMED	1,078.50	1,078.50
1	REAR BUMPER CENTRE BEAM	BENT	231.40	231.40
2	REAR BUMPER SIDE RETAINER @\$45.00	NECESSARY	90.00	90.00
2	TAILLAMP @\$358.50	CUT	717.00	717.00
2	REAR FENDER INNER COWLING @\$169.50	NOT NECESSARY	339.00	-
2	REAR FENDER INNER TRIM @\$396.80	CRACKED	793.60	793.60
1	REAR FENDER QUARTER GLASS C/W MOULDING LH	NOT NECESSARY	687.30	-
1	REAR END PANEL	DISTORTED	509.70	509.70
1	REAR END PANEL TOP GARNISH	CRACKED	189.50	189.50
1	REAR END PANEL BOTTOM (CENTRE)	DENTED	358.00	358.00
1	REAR END PANEL BOTTOM EXTENSION LH	TO REPAIR SEE LABOUR	198.00	-
1	REAR SPARE TYRE BOLT	BENT	45.00	45.00
1	REAR CHASSIS MEMBER LH	TO REPAIR SEE LABOUR	504.00	-
1	REAR FLOOR PANEL	BUCKLED	1,396.50	1,124.00
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	548.70	231.00

Report Ref No. CC6/CTI21002531/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR TOWING PANEL	TO REPAIR SEE LABOUR	396.10	-
	LESS 20% DISCOUNT		-2,443.46	-1,667.22
			9,773.84	6,668.88
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	80.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET TAILGATE CHROME MOULDING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET TAILGATE OUTER GARNISH CLIP (SN)	NECESSARY	60.00	20.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	50.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	TAILGATE WINDSCREEN INNER SHIELD (SN)	NECESSARY	60.00	30.00
1	SET TAILLAMP CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR FENDER INNER COWLING (SN)	NOT NECESSARY	80.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY	80.00	60.00
1	REAR FENDER QUARTER GLASS SEALANT LH (SN)	NOT NECESSARY	60.00	-
1	REAR FENDER QUARTER GLASS INNER SEAL LH (SN)	NOT NECESSARY	40.00	-
1	REAR FENDER QUARTER GLASS SOLAR FILM LH (SN)	NOT NECESSARY	250.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	SET REAR END PANEL TOP GARNISH CLP (SN)	NECESSARY	40.00	20.00
1	REAR FLOOR PANEL INSULATOR SEAL (SN)	NECESSARY	350.00	200.00
1	REAR FLOOR TOWING PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	TRAIANGLE BREAK DOWN SIGN (SN)	CRUMPLED	180.00	120.00
1	REVERSE CAMERA (SN)	DAMAGED	450.00	380.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			2,700.00	1,270.00
	<u>LABOUR</u>			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS .INCLUSIVE OF THE REPAIR OF REAR END PANEL BOTTOM EXTENSION LH,REAR CHASSIS MEMBER LH AND REAR FLOOR TOWING PANEL .		1,800.00	1,200.00
	TO SPRAY PAINT AFFECTED AREA .		1,600.00	1,200.00
	TUFF COAT.		250.00	80.00

Report Ref No. CC6/CTI21002531/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING AND BULB CHECK .		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR .		250.00	200.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING .		80.00	50.00
	REAR CHASSIS ALIGNMENT .	NOT NECESSARY	250.00	-
	TRANSFER TAILGATE MECHANISM .		80.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX TAILGATE WINDSCREEN .		120.00	120.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING .		80.00	50.00
	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH .	NOT NECESSARY	100.00	-
	REMOVE AND REFIX PETROL TANK TO FACILITATE FLOOR PANEL REPLACEMENT .		100.00	80.00
	TO CHECK AND DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION .	NOT NECESSARY	180.00	-
			5,190.00	3,090.00
	GRAND TOTAL		17,663.84	11,028.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,500.00

Report Ref No. CC6/CTI21002531/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJJ 4828G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJJ 4828G

RE-INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

