

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJJ4828G
 MODEL : HONDA AIRWAVE
 DATE OF ACCIDENT : 23.02.21
 TIME OF ACCIDENT : 10:50HRS

27	REAR CHASSIS MEMBER LH <i>Repair</i>	1	\$ 504.00	\$ 504.00	+
28	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 1,396.50	\$ 1,396.50	1124
29	REAR FLOOR PANEL TOP BOARD <i>Deltd</i>	1	\$ 548.70	\$ 548.70	231
30	REAR FLOOR TOWING PANEL <i>Repair</i>	1	\$ 396.10	\$ 396.10	+

8 336 10
 6668-88

TOTAL PRICE \$ 12,217.30
 LESS 20% \$ 2,443.46
 SUB TOTAL PRICE \$ 9,773.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 80.00	\$ 80.00	50
2	REAR BUMPER CLIPS (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00	30
3	TAILGATE SEALANT <i>Not in</i>	1	\$ 150.00	\$ 150.00	+
4	TAILGATE CHROME MOULDING CLIP (SET) <i>Not in</i>	1	\$ 60.00	\$ 60.00	+
5	TAILGATE OUTER GARNISH CLIP (SET) <i>Nec</i>	1	\$ 60.00	\$ 60.00	20
6	TAILGATE INNER TRIM CLIP (SET) <i>Nec</i>	1	\$ 50.00	\$ 50.00	30
7	TAILGATE WINDSCREEN SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00	40
8	TAILGATE WINDSCREEN INNER SHIELD <i>Nec</i>	1	\$ 60.00	\$ 60.00	30
9	TAILLAMP CLIP (SET) <i>Nec</i>	1	\$ 30.00	\$ 30.00	✓
10	REAR FENDER INNER COWLING (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER INNER TRIM CLIPS (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00	60
12	REAR FENDER QUARTER GLASS SEALANT LH <i>Nec</i>	1	\$ 60.00	\$ 60.00	+
13	REAR FENDER QUARTER GLASS INNER SEAL LH <i>Nec</i>	1	\$ 40.00	\$ 40.00	+
14	REAR FENDER QUARTER GLASS SOLAR FILM LH <i>Nec</i>	1	\$ 250.00	\$ 250.00	+
15	REAR END PANEL INSULATION SEAL <i>Nec</i>	1	\$ 150.00	\$ 150.00	60
16	REAR END PANEL TOP GARNISH CLIP (SET) <i>Nec</i>	1	\$ 40.00	\$ 40.00	20
17	REAR FLOOR PANEL INSULATOR SEAL <i>Nec</i>	1	\$ 350.00	\$ 350.00	200
18	REAR FLOOR TOWING PANEL SEALANT <i>Nec</i>	1	\$ 150.00	\$ 150.00	+
19	TRAIANGLE BREAK DOWN SIGN <i>cracked</i>	1	\$ 180.00	\$ 180.00	120
20	REVERSE CAMERA <i>Damaged</i>	1	\$ 450.00	\$ 450.00	380
21	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 2,700.00

1270

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1200

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJJ4828G
 MODEL : HONDA AIRWAVE
 DATE OF ACCIDENT : 23.02.21
 TIME OF ACCIDENT : 10:50HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	1200
3	TUFF COAT	\$ 250.00	80
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	\$ 250.00	200
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
12	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	\$ 100.00	X
13	REMOVE AND REFIX PETROL TANK TO FACILIATATE FLOOR PANEL REPLACEMENT	\$ 100.00	80
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

3090

TOTAL \$ 5,190.00

ESTIMATE REPORT

TOTAL PARTS COST : \$12,473.84
 TOTAL LABOUR COST : \$5,190.00
 TOTAL REPAIR COST : \$17,663.84

Adrian King.
 L/s 24/02/21
 09 Days.

Total: 11028.88
 L/s: 8.5K (nett Value)
 8.5K

LKK Auto Repairs
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party liability/medical/property claims
- No illegal parts prices are subject to changes.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.