

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21002532/T1TF3E2

**Date:** 19/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100508849  
Claimant Vehicle No : SBS3112S Insured Vehicle No : SCP9083G  
Date of Loss: 24/01/2021 Nature of Claim: TP Claim No: 1508680271SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS3112S**  
Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9186657  
Reg. Date: 11/05/2012 (Man. Year: 2012) Chassis No: YV3S4P920CA155335  
Colour: Multi-colour Odometer: 622152 km  
Engine Capacity: 9364 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,783.00	1,783.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	650.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,433.00</b>	<b>2,433.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>170.31</b>	<b>170.31</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>2,603.31</b>	<b>2,603.31</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment: 23/02/2021  
Date Inspected: 24/02/2021 Inspected At: Sbs Transit Ltd ( Bedok) (HQ)  
1470 BEDOK NORTH AVE 4  
Singapore 489946  
Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE SHEETMETAL PANEL	Bent	853.00 F	*853.00 F
2	1		*SIDE SHEETMETAL PANEL	Bent	930.00 F	*930.00 F
					<b>Total Parts (S\$)</b>	<b>1,783.00</b>
						<b>1,783.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTOR LABOUR	New	650.00	650.00
			<b>Gross Labour Cost (\$\$)</b>	<b>650.00</b>
				<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >