

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 2563U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	868.80	-
1	RADIATOR GRILLE (CONSISTENT)	NOT NECESSARY	292.60	-
1	TOP PANEL GARNISH (CONSISTENT)	NOT NECESSARY	86.80	-
1	SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,179.50	-
1	FRONT BUMPER (CONSISTENT)	DISTORTED	694.90	585.00
1	BUMPER FOG LAMP ASSEMBLY (CONSISTENT)	CRACKED	298.60	298.60
2	BUMPER SIDE RETAINER @\$42.80 (CONSISTENT)	O/S NECESSARY	85.60	42.80
2	HEAD LAMP RH/LH @\$1080.60 (CONSISTENT)	CRACKED	2,161.20	1,344.00
1	RADIATOR SPARE TANK (CONSISTENT)	DEFORMED	163.10	163.10
1	WIPER TANK (CONSISTENT)	DEFORMED	146.50	146.50
1	FRONT FENDER (CONSISTENT)	DISTORTED	875.90	875.90
1	FENDER UNDERGARNISH (CONSISTENT)	DEFORMED	196.70	196.70
1	UNDERCARRIAGE KNUCKLE ARM (CONSISTENT)	DAMAGED	487.20	487.20
1	UNDERCARRIAGE LOWER ARM (CONSISTENT)	BENT	492.80	492.80
1	UNDERCARRIAGE WHEELHUB (CONSISTENT)	DAMAGED	197.90	197.90
1	UNDERCARRIAGE BEARING (CONSISTENT)	DAMAGED	139.40	139.40
1	UNDERCARRIAGE SHOCK ABSORBER (CONSISTENT)	BENT	429.50	429.50
1	UNDERCARRIAGE STEERING RACK (CONSISTENT)	NOT NECESSARY	1,524.90	-
1	UNDERCARRIAGE CROSS -MEMBER (CONSISTENT)	BENT	1,758.30	1,758.30
1	UNDERCARRIAGE DRIVESHAFT (CONSISTENT)	BENT	1,499.80	1,499.80
1	UNDERCARRIAGE LINKAGE (CONSISTENT)	BENT	170.90	170.90
1	BONNET STAY-CLIP (CONSISTENT)	NOT NECESSARY	53.80	-
	LESS 25% DISCOUNT		-	-2,207.10
			13,804.70	6,621.30
	SPECIAL NETT ITEMS			
1	RH SIDE SKIRT (CONSISTENT) (SN)	TORN	1,161.70	680.00
	BUMPER CLIP(CONSISTENT) (SN)	NECESSARY	40.00	30.00
	TOP PANEL GARNISH CLIP (CONSISTENT) (SN)	NOT NECESSARY	30.00	-
	TYRE (CONSISTENT) (SN)	PUNCTURE	280.00	200.00

Report Ref No. CC4/ASM21002535/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	RIM (CONSISTENT) (SN)	CUT	650.00	500.00
1	FENDER UNDERGARNISH CLIP (CONSISTENT) (SN)	NECESSARY	40.00	30.00
			2,201.70	1,440.00
	<u>LABOUR</u>			
	KNOCKING OF ALL AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND SUPPORT PANEL.		1,200.00	800.00
	COMPUTERISED WHEEL ALIGNMENT.		250.00	80.00
	REMOVE & REPLACE UNDERCARRIAGE CROSS - MEMBER .		550.00	350.00
	TUFF KOTE.		150.00	50.00
	TO CONDUCT WIRING CHECKS .		80.00	30.00
	SPRAY PAINTING SIDE SKIRT ,DOOR ,FENDER BONNET ,BUMPER AND TOP PANEL.		1,200.00	1,000.00
			3,430.00	2,310.00
	GRAND TOTAL		19,436.40	10,371.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,300.00

Report Ref No. CC4/ASM21002535/Apa3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.