

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21002537/GQF3E2

**Date:** 12/04/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070015323
<b>Claimant Vehicle No :</b>	SLX8567K	<b>Insured Vehicle No :</b>	SMS4336B
Date of Loss:	21/02/2021	Nature of Claim:	TP
		Claim No:	3443360683SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX8567K	Engine No:	2ZR8329130
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	ZVW518042486
Reg. Date:	13/04/2018 (Man. Year: 2017)	Odometer:	130679 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,057.52	2,608.45	3,449.07	56.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,390.00	1,090.00	43.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,537.52</b>	<b>3,998.45</b>	<b>4,539.07</b>	<b>53.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,537.52</b>	<b>3,200.00</b>	<b>5,337.52</b>	<b>62.52</b>

### INSPECTION

Date of Assignment:	23/02/2021	Neo Automotive Pte Ltd (HQ)
Date Inspected:	23/02/2021 Inspected At:	53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK
Estimated Period of Repair:	4.0 days	Singapore 408934

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,641.50 FL	*- FL
2	1		*TAILGATE NO. PLATE GARNISH	Dented / Cracked	891.20 FL	*891.20 FL
3	1		*TAILGATE EMBLEM (LOGO)	Necessary	46.30 FL	*46.30 FL
4	1		*TAILGATE EMBLEM (PRIUS)	Necessary	52.30 FL	*52.30 FL
5	1		*TAILGATE EMBLEM (HYBRID)	Necessary	52.90 FL	*52.90 FL
6	1		*TAILGATE INNER MID TRIM	Serviceable	218.50 FL	*- FL
7	1		*TAILGATE INNER TRIM	Dented / Deformed	251.50 FL	*251.50 FL
8	1		*TAILGATE LOCK ASSY	Dented / Damaged	452.10 FL	*452.10 FL
9	1		*TAILGATE WEATHERSTRIP	Torn / Necessary	360.70 FL	*360.70 FL
10	1		*TAILLAMP RH	Serviceable	433.70 FL	*- FL
11	1		*RR BUMPER	Dented / Deformed	423.90 FL	*423.90 FL
12	1		*RR BUMPER CENTER GUARD	Dented / Deformed	558.30 FL	*558.30 FL
13	1		*RR BUMPER TOW COVER	Broken / Dislodged / Missing	21.00 FL	*21.00 FL
14	1		*RR BUMPER TOW BRACKET	Dented	82.60 FL	*82.60 FL
15	2		*RR BUMPER SIDE EXTENSION R/L	Serviceable	300.00 FL	*- FL
16	1		*RR BUMPER SIDE LAMP RH	Serviceable	486.80 FL	*- FL
17	6		*RR BUMPER CLIP	Necessary	22.80 FL	*22.80 FL
18	2		*RR BUMPER RETAINER R/L	Serviceable	223.00 FL	*- FL
19	1		*RR BUMPER REINFORCEMENT	Serviceable	318.80 FL	*- FL
20	1		*RR END PANEL	Repair	629.80 FL	*- FL
21	1		*RR END PANEL TRIM	Dented / Deformed	122.80 FL	*122.80 FL
22	1		*RR LOCK ANTENNA	Dented / Damaged	86.20 FL	*86.20 FL
23	2		*RR FENDER R/L	Repair	0.00 FL	*- FL
			(NPA)			
24	1		*RR FLOOR PANEL	Repair	0.00 FL	*- FL
			(NPA)			
25	2		*RR CHASSIS MMEBER R/L	Repair	0.00 FL	*- FL
			(NPA)			
26	1		*RR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
27	1		*SET RR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
28	1		*RR END PANEL SEALANT	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,976.70	3,464.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,919.18	856.15
Total Parts (\$\$)	6,057.52	2,608.45

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	30.00	20.00
2	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	New	100.00	60.00
3	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE	New	120.00	0.00
4	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	New	100.00	60.00
5	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	50.00	50.00
6	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	500.00
7	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,000.00	700.00
8	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,480.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >