

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21002541/QEA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SME3471Z**Insured Vehicle No :** SLC1730L

Date of Loss: 09/12/2020

Nature of Claim: TP

Claim No: 1098055344SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SME3471Z**

Make &amp; Model: HYUNDAI ACCENT, 1.4 (A)

Engine No: G4LCJU042929

Reg. Date: 27/09/2018 (Man. Year: 2018)

Chassis No: KMHCU41BTKU444722

Colour: Silver

Odometer: 125587 km

Engine Capacity: 1368 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,148.40	386.00	2,762.40	87.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,330.00	1,320.00	49.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,798.40</b>	<b>1,716.00</b>	<b>4,082.40</b>	<b>70.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,350.00</b>		
<b>(S\$)</b>	5,798.40	1,350.00	4,448.40	76.72
<b>+ GST 7.00/7.00% (S\$)</b>	405.89	94.50	311.39	76.72
<b>Nett Amount (S\$)</b>	<b>6,204.29</b>	<b>1,444.50</b>	<b>4,759.79</b>	<b>76.72</b>
<b>+ Loss of Use (4.0 x S\$80.00/day) (S\$)</b>		320.00		
<b>(S\$)</b>		1,764.50		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>882.25</b>		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>918.70</b>		
<b>Global Sum Settlement (S\$)</b>		<b>900.00</b>		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 01/03/2021 Inspected At:

My Car Consultant Pte Ltd ( Jalan Lam Huat )  
(HQ)  
60 Jalan Lam Huat, Carros Centre #05-21  
Singapore 737869

Estimated Period of Repair: 2.0 days

---

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	498.00 FL	*420.00 FL
2	1		*FRONT FENDER COWLING LH	Serviceable	187.00 FL	*- FL
3	1		*FRONT DOOR LH	Repair	892.00 FL	*- FL
4	1		*REAR DOOR LH	Repair	875.00 FL	*- FL
5	1		*REAR FENDER LH	Repair	598.00 FL	*- FL
6	1		*REAR BUMPER	Repair	698.00 FL	*- FL
7	1		*REAR WHEEL HUB CAP LH	Scratched	50.00 FS	*50.00 FS
8	2		*SET FRONT DOOR INNER TRIM CLIPS	Serviceable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,898.00	470.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	749.60	84.00
Total Parts (\$\$)	3,148.40	386.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL WIRING	New	50.00	30.00
2	REMOVE AND REFIX DOOR GLASS	New	300.00	0.00
3	REMOVE AND REFIX FRONT DOOR MECHANISM	New	100.00	0.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	1,000.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	300.00
<b>Gross Labour Cost (\$)</b>			<b>2,650.00</b>	<b>1,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >