



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2105324
3 ANSON ROAD #16-00	INV Date	29/07/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21002542/Kra3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SMG 2971T
Insured Veh.	PD 3939L
Claim No.	SNM21D200210/LKKDS
Policy No.	DMB1SNW00010352000
Accident Date	12/01/2021
Inspection Date	22/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21002542/Kra3q2 Date: 29/07/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PD 3939L	Veh. Inspected	SMG 2971T
Policy No.	DMB1SNW00010352000	Coverage (\$)	0.00
Claim No.	SNM21D200210/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	22/02/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1173422N257672	Colour	METALLIC PEARL WHITE
Odometer	58565 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	8 mm
L/H Front Tyre	225/40 R18	GOODYEAR	8 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	8 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	8 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	12/01/2021	Inspection Date	22/02/2021
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2971T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / DENTED	1,341.00	1,341.00
1	REAR BUMPER LOWER	SERVICEABLE	259.00	-
2	REAR BUMPER RETAINER @\$142.00	SERVICEABLE	284.00	-
1	SET REAR REVERSE SENSOR	SERVICEABLE	306.00	-
1	REAR EMBLEM 'CLA 180'	NOT NECESSARY	102.00	-
1	REAR LID STAR	NOT NECESSARY	55.00	-
	LESS 10% DISCOUNT		-234.70	-134.10
			2,112.30	1,206.90
LABOUR				
	TO CHECK REAR WIRING FUNCTION .		65.00	15.00
	TO APPLY RUSTPROOFING ON AFFECTED AREA.	NOT NECESSARY	120.00	-
	LABOUR TO REPLACE & RESET REVERSE SENSOR & CHECK WIRING .		120.00	60.00
	TO REPAIR ,PANEL BEAT ON REAR AFFECTED AREA END PANEL ,AND LABOUR TO REPLACE ABOVE PARTS.		700.00	250.00
	TO SPRAY PAINT ON REAR AFFECTED PANEL ,REAR BUMPER SENSOR USING 2K PAINT.		1,000.00	250.00
	LABOUR TO REPAIR AND ALIGN ON AFFECTED SILENCER .	NOT NECESSARY	80.00	-
	TO TOUCH UP ON REAR BUMPER LIP .	NOT NECESSARY	150.00	-
			2,235.00	575.00
GRAND TOTAL			4,347.30	1,781.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CC6/CT121002542/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 2971T

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 2971T

RE-INSPECTION

