



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103087

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 03/05/2021
Reference CC6/CTI21002543/Kra3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLL 6811G
Insured Veh. GBH 5579Z
Claim No. SNM21D200721/LKKDS
Policy No. DMCVSNW00049852000
Accident Date 05/02/2021
Inspection Date 22/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21002543/Kra3q2 Date: 03/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 5579Z	Veh. Inspected	SLL 6811G
	Policy No.	DMCVSNW00049852000	Coverage (\$)	0.00
	Claim No.	SNM21D200721/LKKDS	Excess (\$)	0.00
	Assign From		Assign Date	22/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJGK85GG081736	Colour	METALLIC GREY
	Odometer	42751 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	PIRELLI	8 mm
	L/H Front Tyre	225/55 R18	PIRELLI	8 mm
	R/H Rear Tyre	225/55 R18	PIRELLI	8 mm
	L/H Rear Tyre	225/55 R18	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/02/2021	Inspection Date	22/02/2021
	Survey held at	KING'S AUTO SPRAY PAINT PTE LTD 160 SIN MING DRIVE #05-10 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6811G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / CRACKED	580.30	580.30
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	310.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	110.00	-
2	REAR BUMPER SIDE RETAINER @\$16.00	SERVICEABLE	32.00	-
2	REAR BUMPER REFLECTOR @\$24.00	SERVICEABLE	48.00	-
2	REAR BUMPER BRACKETS @\$20.00	SERVICEABLE	40.00	-
8	REAR BUMPER CLIPS @\$3.50	NECESSARY	28.00	28.00
1	REAR CENTER PANEL	BENT	288.00	288.00
2	REAR EXHAUST @\$608.00	TO REPAIR SEE LABOUR	1,216.00	-
6	REAR PANEL TOP GARNISH CLIPS @\$3.50	NOT NECESSARY	21.00	-
1	REAR BOOT LID SUBARA EMBLEM	NECESSARY	48.00	48.00
1	REAR BOOT LID DWD-EMBLEM	NECESSARY	28.00	28.00
1	REAR BOOT LID FORESTER EMBLEM	NECESSARY	48.00	48.00
1	REAR BOOT LID XT EMBLEM	NECESSARY	25.00	25.00
1	REAR TAIL LAMP	CUT	432.00	432.00
	LESS 20% DISCOUNT		-650.86	-295.46
			2,603.44	1,181.84
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER SENSOR (SN)	SHORTED	320.00	200.00
			320.00	200.00
	<u>LABOUR</u>			
	TO DISMANTLE & REFIX EXHAUST .	NOT NECESSARY	100.00	-
	RENEW THE ABOVE MENTIONED PARTS KNOCKING ,CUTTING ,WELDING & STRAIGHTEN REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM AND REAR EXHAUST.		880.00	600.00
	SPRAY PAINTING .		750.00	600.00
			1,730.00	1,200.00
	GRAND TOTAL		4,653.44	2,581.84

Report Ref No. CC6/CTI21002543/Kra3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CC6/CTI21002543/Kra3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 6811G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 6811G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 6811G

RE-INSPECTION

