

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20013066/UTF3E2-1

Date: 25/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant Vehicle No : GBA3537U

Insured Vehicle No : SLP6034L

Date of Loss: 22/11/2020

Nature of Claim: TP Claim No: 631200

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA3537U**

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD1641072

Reg. Date: 13/06/2007 (Man. Year: 2007)

Chassis No: JTFHT02P700004140

Colour: Silver

Odometer: 465839 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: Maxxis 5 mm

Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,300.25	1,977.25	3,323.00	62.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,430.00	1,520.00	51.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,250.25	3,407.25	4,843.00	58.70
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	8,250.25	2,700.00	5,550.25	67.27

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 26/11/2020 Inspected At:

15 KAKI BUKIT ROAD 4 # 01-53

Repairer : Asia Motorsports Solution Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Feb 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA3537U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS SLIDING DOOR	Dented	2,145.00 FL	*2,145.00 FL
2	1		*RHS SLIDING DOOR INNER LOCK ASSY	Damaged	378.00 FL	*378.00 FL
3	1		*RHS REAR PANEL	Repair	1,782.00 FL	*- FL
4	1		*RHS ROCKER PANEL	Repair	782.00 FL	*- FL
5	1		*RHS REAR RIM COVER	Missing	85.00 FS	*85.00 FS
6	1		*RHS SLIDING DOOR INNER TOP ALUMINIUM PANEL	Not Necessary	300.00 FS	*- FS
7	1		*RHS SLIDING DOOR INNER LOWER ALUMINIUM PANEL	Not Necessary	300.00 FS	*- FS
8	1		*RHS REAR PANEL INNER ALUMINIUM PANEL	Not Necessary	800.00 FS	*- FS
					Sub Total (\$\$)	6,572.00 2,608.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,271.75 630.75
					Total Parts (\$\$)	5,300.25 1,977.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREA. REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	600.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,000.00	600.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	150.00	20.00
4	TO REMOVE SLIDING DOOR FITTINGS, GARNISH, TRIMMINGS ETC	New	150.00	60.00
5	TO REMOVE AND REFIX ALL ALUMINIUM PANEL	New	300.00	100.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	50.00
Gross Labour Cost (\$\$)			2,950.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >