S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference:

TP/020/0155SK

Your Reference:

TBA

Erate:

5/12/2020

TO:

SIN YONG HUAT CATERING SERVICES

C/o Asia Motor Sports Solution Pte Ltd

37A Everitt Road Singapore 428586

Assessment of Vehicle No

: GBA 3537 U

Date of Accident

:22/11/2020 .

Date of Inspection

: 26/11/2020

We have carried out a physical assessment of GBA3537U at Asia Motor Sports Solution PL according to your instructions on 26/11/20120 and are pleased to submit our report as follows;

1. VEHICLE PARTICULARS

Registration No.

GBA 3537 U

Make & Model

TOYOTA HIACE

Year of Pegistration

13/6/2007 (EXPIRY12/06/2022)

Engine Capacity (cc)

3.0L

Chassis No.

JTFHT02P700004140

Engine No.

1KD1641072

Colour

SILVER

Mileage (km)

465839

2. VEHICLE CONDITION

Body Paint:

: Good

Steering

*

Foot Brake :

Serviceable Serviceable

Paddice Brake

Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size

.

Maxxis 195R15C - 80%

LH Make/Size

Maxxis 195R15C - 80%

Rear

RH Make/Size

Maxxis 195R15C - 80%

LH Make/Size

Maxxis 195R15C - 80%

Note: % denotes the remaining percentage of the tyre

SKAUTO CONSULTANTS

Page No. 2


Our Reference Vehicle No. TP/020/0155SK

GBA 3537U

4.DESCRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the RHS BODY portion

Please see attached schedule for details.



Estimated Amount

: S\$8,250.25

Adjusted Amount

: S\$6,200/-

Estimated Repair Days

: 7 days

Pursuant to your instruction, we have NOT AUTHORIZED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within <u>14 Days</u> from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by <u>S K AUTO CONSULTANTS</u> for any reliance on this report by any third party.

S K AUTO CONSULTANTS

Page No. 3

Our Reference TP/020/0155SK

Vehicle No.

GBA 3537U

QTY	DESCRIPTION	CONDITION	REPAIRER'S		OUR	
QII		COMPLITION	ESTIMATE(S\$)		ASSESSMENT(S\$)	
	PARTS (LIST ITEMS)					
1	RHS sliding door	Dent		2145.00		2145.00
1	RHS sliding door inner lock assy	Damaged		378.00		378.00
1	RHS rear panel	Dent		1782.00		1782.00
1	RHS rocker panel	Distorted		782.00		782.00
Administrative Control				5087.00		5087.00
C and a Colomon or service of the Colomon or service		less	25%	1271.75	25%	1271.75
				3815.25		3815.25
	SPECIAL NETT ITEMS					
1	RHS rear rim cover	Missing		85.00		85.00
1	RHS sliding door inner top aluminium panel	Necessary		300.00		300.00
1	RHS sliding door inner lower aluminium panel	Necessary		300.00		300.00
tum;	RHS rear panel inner aluminium panel	Necessary		800.00		800.00
		TOTAL PARTS	5300.25		5300.25	

SKAUTO CONSULTANTS

Page No. 4

Vehicle No.

Our Reference TP/020/0155SK GBA 3537U

S/N	DESCRIPTION	REPAIRER'S	OUR	
3/14	DESCRIPTION	ESTIMATE (S\$)	ASSESSMENT (S\$)	
	LABOUR *	The state of the s		
T I	To remove the affected parts & fittings to commence	1200.00	1000.00	
	repairs; panel beat & reshape the affected areas;	# 1	ACCUPACION COMPANIAN COMPA	
	replace the damaged parts and components.		ra n	
2	To supply paint materials, expandable items & putty,	1000.00	800.00	
_	respray paint on parts replaced and repaired areas			
3	To remove and re-fix wiring and check all electrical	150.00	120.00	
	components at damaged areas for proper functions			
4		150.00	130.00	
4	To remove sliding door fittings, garnish, trimmings etc	150.00 	120.00	
5	To remove and replace all aluminum panel	300.00	250.00	
ū	and territorie direct expenses on alternation parties	300.00	250.00	
6	To provide anti-rust treatment on affected areas	150.00	120.00	
	·			
	Labour Total :	2950.00	2410.00	
TOTAL (PARTS & LABOUR):		8250.25	7710.25	

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted Lupp Sum contract amount is \$\$6,200/-

JOHN LOW

Motor Surveyor



