

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21002544/R1TF3E2**Date:** 12/08/2021**REFERENCE**

Insured/Claimant: Cai Hong Bo Policy No: 2070161915  
Date of Loss: 20/02/2021 Nature of Claim: OD Claim No: 2603346910SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMW4803Z**  
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZDC06828  
Reg. Date: 24/11/2020 (Man. Year: 2020) Chassis No: WAUZZZF33M1014796  
Colour: Red Odometer: 3611 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$142,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	29,640.00	12,671.84	16,968.16	57.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,672.00	5,832.00	5,840.00	50.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>41,312.00</b>	<b>18,503.84</b>	<b>22,808.16</b>	<b>55.21</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	40,512.00	17,703.84	22,808.16	56.30
<b>+ GST 7.00/7.00% (S\$)</b>	2,835.84	1,239.27	1,596.57	56.30
<b>Nett Amount (S\$)</b>	<b>43,347.84</b>	<b>18,943.11</b>	<b>24,404.73</b>	<b>56.30</b>

**INSPECTION**

Date of Assignment: 24/02/2021

Date Inspected: 23/02/2021 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 9.0 days

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,161.00 FS	*1,728.40 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Serviceable	59.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Serviceable	59.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	217.00 FS	*173.20 FS
5	1		*FRONT BUMPER LOWER GRILLE COVER	Cracked	51.00 FS	*40.80 FS
6	2		*FRONT BUMPER GRILLE - LH / RH	Serviceable	220.00 FS	*- FS
7	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Cracked	190.00 FS	*151.60 FS
8	1		*FRONT BUMPER SPOILER	Cracked	383.00 FS	*306.40 FS
9	1		*FRONT BUMPER SPOILER BRACKET	Serviceable	21.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Serviceable	306.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	1,433.00 FS	*1,146.40 FS
12	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
13	1		*RADIATOR GRILLE COVER CAP	Serviceable	45.00 FS	*- FS
14	1		*PARKING MODULE BRACKET	Serviceable	41.00 FS	*- FS
15	1		*PARKING MODULE SECURING PLATE	Serviceable	33.00 FS	*- FS
16	1		*FRONT BUMPER CAMERA	Serviceable	1,141.00 FS	*- FS
17	1		*FRONT BUMPER REINFORCEMENT	Bent	916.00 FS	*732.40 FS
18	1		*FRONT BUMPER REINFORCEMENT FOAM FILLER	Cracked	102.00 FS	*81.60 FS
19	1		*FRONT BUMPER TOP COVER	Deformed	123.00 FS	*98.00 FS
20	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Serviceable	78.00 FS	*- FS
21	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
22	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
23	1		*SIGNAL HORN HIGH TONE - LH	Serviceable	137.00 FS	*- FS
24	1		*SIGNAL HORN HIGH TONE - RH	Serviceable	130.00 FS	*- FS
25	2		*HORN BRACKET - LH / RH	Serviceable	44.00 FS	*- FS
26	2		*FRONT PARKING SENSOR	Serviceable	500.00 FS	*- FS
27	4		*FRONT PARKING SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
28	1		*FRONT FENDER - LH	Serviceable	1,286.00 FS	*- FS
29	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	63.00 FS	*- FS
30	1		*FRONT FENDER BRACKET - LH REAR	Serviceable	88.00 FS	*- FS
31	1		*FRONT FENDER BRACKET - LH FRONT	Serviceable	32.00 FS	*- FS
32	1		*FRONT FENDER SEAL - LH	Not Necessary	36.00 FS	*- FS
33	1		*FRONT FENDER DAMPER - LH UPPER	Not Necessary	32.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER - LH FRONT	Serviceable	240.00 FS	*- FS
35	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
36	1		*BONNET	Bent	3,508.00 FS	*2,806.40 FS
37	2		*BONNET HINGE - LH / RH	Bent	146.00 FS	*115.52 FS
38	1		*BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
39	2		*BONNET STRIKER - LH / RH	Serviceable	220.00 FS	*- FS
40	1		*BONNET SOUND ABSORBER	Deformed	219.00 FS	*175.20 FS
41	1		*BONNET IMPACT PROTECTION	Cut	28.00 FS	*21.84 FS
42	1		*PLENUM CHAMBER COVER	Scratched	129.00 FS	*103.20 FS
43	1		*BONNET BOWDEN CABLE	Serviceable	58.00 FS	*- FS
44	1		*BONNET LOCK W/MICRO SWITCH	Serviceable	427.00 FS	*- FS
45	1		*BONNET RELEASE ELEMENT	Bent	58.00 FS	*46.00 FS
46	1		*BONNET RELEASE LEVER	Scratched	14.00 FS	*11.20 FS
47	1		*BONNET BOWDEN CABLE COVER	Serviceable	10.00 FS	*- FS
48	1		*HEADLIGHT MOUNTING - LH / RH	N/S Cracked / O/S Serviceable	236.00 FS	*94.40 FS
49	1		*LED HEADLIGHT - LH	Serviceable	5,589.00 FS	*- FS
50	2		*LIFT CYLINDER - LH / RH	Serviceable	420.00 FS	*- FS
51	1		*LIFT CYLINDER HOSE	Serviceable	80.00 FS	*- FS
52	1		*FRONT LOCK CARRIER	Cracked	1,272.00 FS	*1,017.60 FS
53	1		*A/C CONDENSER	Bent	551.00 FS	*440.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*TEMPERATURE SENSOR HOLDER	Serviceable	7.00 FS	*- FS
55	1		*ADDITIONAL RADIATOR	Bent	920.00 FS	*736.00 FS
56	1		*RADIATOR	Bent	1,035.00 FS	*828.00 FS
57	4		*READY-MIX COOLANT FLUID (1 LTR)	Necessary	179.00 FS	*143.04 FS
58	1		*RADIATOR FAN	Serviceable	1,529.00 FS	*- FS
59	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	76.00 FS	*59.52 FS
60	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Cracked	84.00 FS	*66.08 FS
61	2		*FRONT WHEEL ARC COVER - LH / RH	Necessary	536.00 FS	*428.80 FS
62	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*60.00 FS
63	1		*SUNDRIES	Necessary	350.00 FS	*5.52 FS
64	1		*AIR INTAKE GUIDE - LOWER (Supplementary)	Cracked	56.00 FS	*44.48 FS
65	1		*AIR INTAKE GUIDE - INNER (Supplementary)	Cracked	20.00 FS	*15.36 FS
66	1		*ADDITIONAL RADIATOR BUSH - LOWER (Supplementary)	Cracked	19.00 FS	*15.04 FS
67	1		*ADDITIONAL RADIATOR BRACKET - UPPER (Supplementary)	Cracked	82.00 FS	*65.28 FS
68	1		*SET FRONT BUMPER WIRING (Supplementary)	Cut	676.00 FS	*540.80 FS
69	1		*RADIATOR FAN RING (Supplementary)	Distorted	202.00 FS	*161.60 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 29,640.00 12,671.84**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND FRONT FENDER	New	3,600.00	1,260.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>11,672.00</b>
				<b>5,832.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >