

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002549/KBA3Q2
Date: 15/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509806	
Claimant Vehicle No :	SLG4781Z	Insured Vehicle No :	SLP5081G	
Date of Loss:	23/02/2021	Nature of Claim:	TP	Claim No: 4865335819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG4781Z		
Make & Model:	MAZDA 5 SP, 2.0 (A)	Engine No:	P520356776
Reg. Date:	30/09/2016 (Man. Year: 2016)	Chassis No:	JM6DJ2HAA01100843
Colour:	Metallic Maroon	Odometer:	43720 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R16	Rear Tyre Size:	185/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,455.88	4,761.86	2,694.02	36.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	3,000.00	350.00	10.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,805.88	7,761.86	3,044.02	28.17
+ GST 7.00/7.00% (S\$)	756.41	543.33	213.08	28.17

Nett Amount (S\$)	11,562.29	8,305.19	3,257.10	28.17
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,207.19		

INSPECTION

Date of Assignment: 24/02/2021

Date Inspected: 24/02/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	956.70 FL	*956.70 FL
2	1		*TAILGATE EMBLEM	Necessary	61.20 FL	*61.20 FL
3	1		*TAILGATE MAZDA 2 LOGO	Necessary	58.30 FL	*58.30 FL
4	1		*TAILGATE SKYACTIV TECHNOLOGY LOGO	Necessary	68.00 FL	*68.00 FL
5	2		*TAILGATE LAMP LH & RH	Serviceable	466.00 FL	*- FL
6	2		*TAILGATE BRACKET LH & RH	Distorted	47.00 FL	*47.00 FL
7	1		*TAILGATE LOCK	Dented	212.30 FL	*212.30 FL
8	1		*TAILGATE LOCK STRIKER	Repair	25.80 FL	*- FL
9	1		*TAILGATE LOCK SENSOR	Dented	121.00 FL	*121.00 FL
10	1		*TAILGATE OPENER CONTROL (SWITCH)	Serviceable	96.20 FL	*- FL
11	1		*TAILGATE OPENER CONTROL	Dented	15.00 FL	*15.00 FL
12	1		*TAILGATE INNER TRIMBOARD	Serviceable	93.50 FL	*- FL
13	2		*TAILGATE ABSORBER LH & RH	Serviceable	136.00 FL	*- FL
14	1		*TAILGATE RUBBER (50%)	Cut	134.88 FS	*84.30 FS
15	2		*TAILLAMP LH & RH	Serviceable	1,528.80 FL	*- FL
16	2		*TAILAMP PANEL LH & RH (NPA)	Repair	0.00 FL	*- FL
17	1		*REAR BUMPER	Bent	893.40 FL	*893.40 FL
18	1		*REAR BUMPER NO PLATE LAMP LH & RH	N/S Cracked	111.60 FL	*55.80 FL
19	1		*REAR BUMPER SPLASH SHIELD LH & RH	N/S Cracked / O/S Serviceable	124.60 FL	*62.30 FL
20	2		*REAR BUMPER SIDE RETAINER LH & RH	Distorted	54.40 FL	*54.40 FL
21	12		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
22	2		*REAR FENDER AIR VENT GRILLE LH & RH	Serviceable	98.40 FL	*- FL
23	2		*REAR FENDER INNER TRIMBOARD LH & RH	Buckled /Bent	423.80 FL	*423.80 FL
24	1		*REAR END PANEL	Bent	399.30 FL	*399.30 FL
25	1		*REAR END PANEL GARNISH	Distorted	77.00 FL	*77.00 FL
26	1		*SPARE TYRE PANEL	Bent / Buckled	878.70 FL	*878.70 FL
27	1		*SPARE TYRE PANEL COVER TOP	Cracked	327.00 FL	*327.00 FL
28	1		*SPARE TYRE PANEL COVER BTM	Dented	70.20 FL	*70.20 FL
29	1		*TOOLBOX SPONGE	Deformed	195.10 FL	*195.10 FL
30	1		*REAR WIPER MOTOR	Serviceable	333.00 FL	*- FL
31	1		*REAR VIEW CAMERA	Shorted	676.80 FS	*350.00 FS
32	1		*REAR BUMPER CTR BRACKET	Cracked	5.40 FL	*5.40 FL
33	2		*REAR BUMPER STAY	Cracked	22.80 FL	*22.80 FL
34	1		*NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
35	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
37	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					9,043.18	5,770.00
- List Item Discount on L Items 20.00/20.00% (\$)					1,587.30	1,008.14
Total Parts (\$)					7,455.88	4,761.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM, GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	120.00
4	TO REMOVE AND REINSTALL /REPLACE FUEL TANK FIXTURE AND ATTACHMENTS	New	60.00	60.00
5	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
6	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
7	TO RESET TAILGATE	New	60.00	0.00
8	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	60.00
9	TO REALIGN ,DISMANTLE AND REINSTALL /REPLACE EXHAUST PIPE	New	60.00	60.00
10	TO WELD ,KNOCK ,REPAIR AND JACK CHASSIS TO ORIGINAL CONDITION	New	250.00	250.00
11	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD END PANEL,SPARE TYRE PANEL .TO KNOCK & REPAIR REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	1,200.00	1,100.00
12	TO SPRAY TAILGATE ,REAR BUMPER ,REAR FENDER LH & RH ,END PANEL ,SPARE TYRE PANEL	New	1,200.00	1,100.00
Gross Labour Cost (S\$)			3,350.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >