

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 3117S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED / DEFORMED	1,083.30	1,083.30
1	FRONT BUMPER SIDE RETAINER O/S	NECESSARY	22.50	22.50
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	444.50	-
1	HEADLAMP O/S	CRACKED	2,800.50	2,357.30
1	FRONT FENDER O/S	BADLY DENTED	456.20	456.20
1	FRONT FENDER INNERSHIELD O/S	DISTORTED	158.00	158.00
1	SET FRONT FENDER INNERSHIELD CLIPS O/S	NECESSARY	45.00	45.00
1	FRONT FENDER INNER PANEL O/S	TO REPAIR SEE LABOUR	645.20	-
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	1,061.50	-
1	FRONT DOOR MIRROR O/S	SERVICEABLE	485.00	-
1	FRONT DOOR MIRROR COVER O/S	CRACKED	92.50	92.50
1	FRONT SPORT RIM O/S	TO REPAIR SEE LABOUR	800.00	-
	LESS 20% DISCOUNT		-	-852.96
			8,144.20	3,411.84
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO SPRAY RUST PROOFING.		50.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,FRONT FENDER INNER PANEL O/S,FRONT DOOR O/S AND FRONT SPORT RIM O/S.		880.00	550.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	900.00
			2,380.00	1,610.00
	GRAND TOTAL		10,524.20	5,021.84

Report Ref No. CS/TP21002552/Uqf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,000.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/TP21002552/Uqf3e2

CHUA KANG SENG Licensed Appraiser