

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002555/UQF3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00090002000
Claimant Vehicle No :	SMH2385E	Insured Vehicle No :	SMT7934A
Date of Loss:	19/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D200982/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2385E	Engine No:	R16B25502667
Make & Model:	HONDA CIVIC, 1.6 VTI (A)	Chassis No:	MRHFC5650JT002296
Reg. Date:	16/01/2019 (Man. Year: 2018)	Odometer:	23722 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,941.20	1,554.72	4,386.48	73.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,740.00	2,100.00	54.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,781.20	3,294.72	6,486.48	66.32
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	9,781.20	2,600.00	7,181.20	73.42

INSPECTION

Date of Assignment:	24/02/2021	
Date Inspected:	24/02/2021	Inspected At:
Estimated Period of Repair:	4.0 days	PKS Automotive Pte Ltd (HQ) 8 Kaki Bukit Avenue 4 #01 – 52 Singapore 415875

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2385E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	717.00 FL	*579.90 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	268.00 FL	*180.00 FL
3	2		*REAR BUMPER RETAINER	Not Necessary	68.00 FL	*- FL
4	1		*REAR BUMPER BRACKET	O/s Bent	78.00 FL	*32.00 FL
5	1		*REAR BUMPER REFLECTOR WITH COVER LH	Not Necessary	75.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR WITH COVER RH	Torn	75.00 FL	*75.00 FL
7	1		*REAR BUMPER INNER SIDE COVER LH	Not Necessary	90.00 FL	*- FL
8	1		*REAR BUMPER INNER SIDE COVER RH	Not Necessary	90.00 FL	*- FL
9	1		*END PANEL	Dented	545.00 FL	*265.70 FL
10	1		*END PANEL TOP GARNISH	Twisted	119.00 FL	*50.30 FL
11	1		*REAR TAILLAMP LH	Not Necessary	382.00 FL	*- FL
12	1		*REAR TAILLAMP RH	Cracked	382.00 FL	*285.50 FL
13	1		*BOOTLID LAMP LH	Not Necessary	255.00 FL	*- FL
14	1		*BOOTLID LAMP RH	Not Necessary	255.00 FL	*- FL
15	1		*BOOTLID	Repair	687.00 FL	*- FL
16	1		*BOOTLID LOCK	Not Necessary	95.00 FL	*- FL
17	1		*BOOTLID LOCK STRIKER	Not Necessary	56.00 FL	*- FL
18	1		*BOOTLID OUTER GARNISH	Not Necessary	215.00 FL	*- FL
19	1		*BOOTLID WEATHERSTRIP	Not Necessary	119.00 FL	*- FL
20	1		*BOOTLID EMBLEM-CIVIC	Not Necessary	41.00 FL	*- FL
21	1		*BOOTLID EMBLEM-I-VTEC	Not Necessary	42.00 FL	*- FL
22	1		*BOOTLID LOGO	Not Necessary	38.00 FL	*- FL
23	2		*BOOTLID HINGE	Not Necessary	102.00 FL	*- FL
24	1		*SPARE TYRE TOP BOARD	Not Necessary	115.00 FL	*- FL
25	1		*REAR EXHAUST	Repair	810.00 FL	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	95.00 FL	*- FL
27	2		*EXHAUST MOUNTING	Not Necessary	50.00 FL	*- FL
28	1		*REAR BUMPER LOWER GARNISH	Deformed	600.00 FS	*150.00 FS
29	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
30	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
31	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
32	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
					Sub Total (S\$)	7,114.00 1,848.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,172.80 293.68
					Total Parts (S\$)	5,941.20 1,554.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	80.00	20.00
2	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND RENEW REAR EXHAUST	New	120.00	60.00
5	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	700.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	800.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (S\$)			3,840.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >