

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21002556/EVF3E2

Date: 18/03/2021

REFERENCE

Insured/Claimant:	TEH CHIEW HWA WATSON	Policy No:	1900149637	
Date of Loss:	23/02/2021	Nature of Claim:	OD	Claim No: 9102179359SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8838J		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BK3288
Reg. Date:	23/08/2019 (Man. Year: 2019)	Chassis No:	GF7W0602070
Colour:	White	Odometer:	25685 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,126.29	2,434.72	2,691.57	52.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,030.00	4,265.00	3,765.00	46.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,156.29	6,699.72	6,456.57	49.08
+ GST 7.00/7.00% (S\$)	920.94	468.98	451.96	49.08
Nett Amount (S\$)	14,077.23	7,168.70	6,908.53	49.08

INSPECTION

Date of Assignment: 24/02/2021

Date Inspected: 24/02/2021 Inspected At:

Estimated Period of Repair: 5.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, RR BUMPER	Broken	811.00 FL	*811.00 FL
3	1		*BRKT, R/BMPR FACE SIDE, LH	Not Necessary	12.00 FL	*- FL
4	1		*BRKT, R/BMPR FACE SIDE, RH	Broken	12.00 FL	*12.00 FL
5	10		*CLIP, ENG ROOM COVER	Not Necessary	20.00 FL	*- FL
6	1		*REINFORCEMENT, RR BUMPER, LH	Not Necessary	79.00 FL	*- FL
7	1		*REINFORCEMENT, RR BUMPER, RH	Bent	79.00 FL	*79.00 FL
8	1		*EXTENSION, RR BUMPER	Cut	360.00 FL	*360.00 FL
9	1		*MOULDING, RR BUMPER, LH	Not Necessary	106.00 FL	*- FL
10	1		*MOULDING, RR BUMPER, RH	Necessary	106.00 FL	*106.00 FL
11	1		*REFLECTOR, TAIL LAMP, LH	Not Necessary	100.00 FL	*- FL
12	1		*REFLECTOR, TAIL LAMP, RH	Not Necessary	100.00 FL	*- FL
13	1		*PANEL ASSY, TAILGATE	Dented	989.00 FL	*989.00 FL
14	1		*GARNISH, TAILGATE	Not Necessary	496.00 FL	*- FL
15	1		*W/STRIP, TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
16	2		*DAM, TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
17	4		*FASTENER, WINDSHIELD	Necessary	24.00 FL	*24.00 FL
18	1		*DAM, TAILGATE, UPR	Necessary	13.00 FL	*13.00 FL
19	1		*STOPPER, WINDSHIELD GLASS	Necessary	3.00 FL	*3.00 FL
20	1		*DAM, TAILGATE, LWR	Necessary	41.00 FL	*41.00 FL
21	1		*LATCH, TAILGATE	Not Necessary	477.00 FL	*- FL
22	1		*STRIKER, TAILGATE LATCH	Not Necessary	19.00 FL	*- FL
23	1		*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL
24	1		*PANEL, RR END	Dented	326.00 FL	*326.00 FL
25	1		*PANEL, RR END, INR RH	Not Necessary	146.00 FL	*- FL
26	1		*TRIM, RR END	Not Necessary	113.00 FL	*- FL
27	1		*DECAL, MIVEC	Necessary	36.00 FL	*36.00 FL
28	1		*BODY KIT, OUTLANDER	Repair	1,554.00 FN	*- FN
29	1		*BUZZER,KEYLESS OPERATOPN ,RR (Supplementary)	Broken	91.00 FL	*91.00 FL
30	1		*ANT,KELYESS OPERATION,RR (Supplementary)	Broken	96.00 FL	*96.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	6,591.00	3,156.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,153.91	721.28
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	310.80	0.00
Total Parts (\$\$)	5,126.29	2,434.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW TAILGATE, RR BUMPER & RR END PNL	New	2,700.00	900.00
2	RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR FLR PNL, TAILGATE, LHR FENDER & RHR FENDER	New	2,450.00	875.00
3	REMOVE & REFIT TAILGATE COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00
8	SUPPLY REAR WINDSCREEN SEALANT	New	80.00	80.00
9	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
10	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
11	SUPPLY REVERSE SENSOR	New	220.00	0.00
12	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
13	SUPPLY BODY PNL SEALANT	New	80.00	40.00
14	SUPPLY C&C BADGE	New	40.00	40.00
15	RENEW REAR END PANEL & REPAIR REAR FLOOR PANEL (Supplementary)	New	900.00	900.00
16	SPRAY PAINT REAR END PANEL & REAR FLOOR PANEL (Supplementary)	New	700.00	700.00
Gross Labour Cost (\$\$)			8,030.00	4,265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >