

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21002560/GQF3E2

**Date:** 24/08/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001621255
<b>Claimant Vehicle No :</b>	SLN1686Z	<b>Insured Vehicle No :</b>	SLF4913R
Date of Loss:	16/02/2021	Nature of Claim:	TP
		Claim No:	253742

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1686Z	Engine No:	G4FGGH655539
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFX411MH5705497
Reg. Date:	25/04/2017 (Man. Year: 2017)	Odometer:	50342 km
Colour:	Brown		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,744.00	1,633.40	2,110.60	56.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	2,940.00	1,850.00	38.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,534.00</b>	<b>4,573.40</b>	<b>3,960.60</b>	<b>46.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	597.38	320.14	277.24	46.41
<b>Nett Amount (S\$)</b>	<b>9,131.38</b>	<b>4,893.54</b>	<b>4,237.84</b>	<b>46.41</b>

### INSPECTION

Date of Assignment:	24/02/2021	
Date Inspected:	26/02/2021 Inspected At:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3 Singapore 408650
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,525.00 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
<b>Parts:</b>	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN1686Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WRT900446, KIA K3 RIM	Cut	1,450.00 FS	*1,450.00 FS
2	1		*ORNAMENT - KIA NO.1	Necessary	32.00 FS	*32.00 FS
3	1		*COVER - FRONT BUMPER	Repair	633.00 FS	*- FS
4	10		*FASTENER - BUMPER	Necessary	20.00 FS	*20.00 FS
5	1		*LH BRACKET - FR BUMPER	Necessary	13.00 FS	*13.00 FS
6	1		*RH BRACKET - FR BUMPE	Not Necessary	13.00 FS	*- FS
7	1		*LH PANEL - FENDER	Repair	435.00 FS	*- FS
8	1		*LH GUARD ASSY - FRONT	Not Necessary	95.00 FS	*- FS
9	10		*FASTERNER - WHEEL GUA	Not Necessary	20.00 FS	*- FS
10	1		*LH STRUT ASSY - FRON	* Check	313.00 FS	*- FS
11	1		*LINK - STABILIZER	* Check	72.00 FS	*- FS
12	1		*LH KNUCKLE - FRONT AXL	* Check	350.00 FS	*- FS
13	1		*HUB ASSY - FR WHEEL	* Check	150.00 FS	*- FS
14	1		*205/55/16, TYRE (80%)	Scratched	148.00 FS	*118.40 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>3,744.00</b>	<b>1,633.40</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING / WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REPLACE FRONT BUMPER, LHF FENDER, BRACKETS, CLIPS, ETC. STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	1,920.00	1,280.00
4	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	1,650.00	1,100.00
5	TO REPLACE SHOCK ABSORBER, STABILIZER LINK, KNUCKLE AND BEARING (* Check)	New	640.00	0.00
6	WHEEL BALANCING (1PC RIM / TYRE)	New	50.00	50.00
7	WHEEL ALIGNMENT	New	180.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,790.00</b>	<b>2,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >