

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/GRB21002563/ABS3Q2
Date: 01/07/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SFH9696U	Insured Vehicle No :	SLK8646J
Date of Loss:	21/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000799

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFH9696U		
Make & Model:	HONDA FREED HYBRID SENSING, 1.5 G (A)	Engine No:	LEB5622184
Reg. Date:	26/02/2020 (Man. Year: 2018)	Chassis No:	GB71084745
Colour:	Silver	Odometer:	14108 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,825.20	3,356.96	9,468.24	73.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	2,320.00	1,510.00	39.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,655.20	5,676.96	10,978.24	65.91
Approved Total (Overridden) (S\$)		4,500.00		

(S\$)	16,655.20	4,500.00	12,155.20	72.98
+ GST 7.00/7.00% (S\$)	1,165.86	315.00	850.86	72.98
Nett Amount (S\$)	17,821.06	4,815.00	13,006.06	72.98
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,242.45		

INSPECTION

Date of Assignment: 22/02/2021

Date Inspected: 22/02/2021 Inspected At: Cn Motors Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts:	M1-MPV	HONDA FREED HYBRID SENSING 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFH9696U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,460.30 F	*1,180.00 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	102.80 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	280.00 F	*- FL
4	1		*REAR BOOT LID EMBLE LOGO	Necessary	27.40 F	*27.40 FL
5	1		*REAR BOOT LID FREED LOGO	Necessary	43.10 F	*43.10 FL
6	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	320.40 F	*- FL
7	1		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	34.60 F	*- FL
8	1		*REAR BOOT LID INNER LOCK	Damaged	189.50 F	*189.50 FL
9	1		*REAR BOOT LID INNER RUBBER	Cut	120.00 F	*120.00 FL
10	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	288.50 F	*288.50 FL
11	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	65.00 F	*30.00 FL
12	1		*REAR BOOT LID WIPER ARM	Not Necessary	65.00 F	*- FL
13	1		*REAR BOOT LID WIPER MOTOR	Not Necessary	137.20 F	*- FL
14	1		*REAR BOOT LID WINDSCREEN	Not Necessary	825.90 F	*- FL
15	1		*REAR BOOT LID WINDSCREEN MOULDING	Necessary	85.30 F	*85.30 FL
16	2		*REAR TAILLAMP	Not Necessary	916.20 F	*- FL
17	4		*REAR TAILLAMP CLIP	Not Necessary	32.00 F	*- FL
18	2		*REAR TAILLAMP PANEL	Not Necessary	420.60 F	*- FL
19	1		*REAR BUMPER	Deformed	788.70 F	*788.70 FL
20	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
21	2		*REAR BUMPER SIDE RETAINER	Necessary	32.00 F	*32.00 FL
22	2		*REAR BUMPER MUD SHIELD	Not Necessary	72.00 F	*- FL
23	4		*REAR BUMPER MUD SHIELD CLIP	Not Necessary	26.00 F	*- FL
24	1		*REAR BUMPER TOWING COVER	Not Necessary	22.50 F	*- FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	654.00 F	*- FL
26	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
27	1		*REAR END PANEL	Dented	623.70 F	*623.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR END PANEL INNER	Dented	304.00 F	*304.00 FL
29	1		*REAR END PANEL OUTER GARNISH	Cracked	104.00 F	*104.00 FL
30	1		*REAR SPARE TYRE PANEL	Repair	1,155.50 F	*- FL
31	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	950.00 F	*- FL
32	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 FS	*- FS
33	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
34	1		*REAR BOOT LID VIDEO CAMERA	Not Necessary	680.00 FS	*- FS
35	1		*REAR BUMPER SIDE REFLECTOR	N/S Cracked	400.00 FS	*80.00 FS
36	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
37	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 FS	*- FS
					Sub Total (\$\$)	12,825.20
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00
					Total Parts (\$\$)	12,825.20
						3,356.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	GUM	New	50.00	50.00
6	TO CHECK WIRING	New	100.00	30.00
7	TOWING FEE	New	100.00	0.00
8	TUFF KOTE	New	200.00	60.00
9	PANEL BEATING	New	1,500.00	1,000.00
10	SPRAY PAINTING	New	1,200.00	900.00
Gross Labour Cost (S\$)			3,830.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >