

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG121002569/DVF3N2**Date:** 31/08/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SHC2998Y **Insured Vehicle No :** SFS8H  
 Date of Loss: 22/02/2021 Nature of Claim: TP Claim No: CDMPG21000343

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC2998Y**  
 Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEJU192037  
 Reg. Date: 12/03/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU141510  
 Colour: Blue Odometer: 310136 km  
 Engine Capacity: 1580 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm  
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,983.90	7,908.12	12,075.78	60.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	2,380.00	4,220.00	63.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>26,583.90</b>	<b>10,288.12</b>	<b>16,295.78</b>	<b>61.30</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,860.87</b>	<b>720.17</b>	<b>1,140.70</b>	<b>61.30</b>
<b>Nett Amount (S\$)</b>	<b>28,444.77</b>	<b>11,008.29</b>	<b>17,436.48</b>	<b>61.30</b>

INSPECTION

Date of Assignment: 24/02/2021  
 Date Inspected: 25/02/2021 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)  
 Estimated Period of Repair: 9.0 days Blk 9 Sector C, #01-42 Sin Ming Industrial Estate  
 Singapore 575644

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Aug 2021)	
<b>Parts:</b>	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC2998Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (LH)	Bent/Dented	490.70 FL	*490.70 FL
2	1		*FRONT FENDER SHIELD (LH)	Not Necessary	164.70 FL	*- FL
3	1		*FRT DOOR (LH)	Bent/Dented	1,797.20 FL	*1,797.20 FL
4	1		*FRT DOOR RUBBER	Not Necessary	250.00 FL	*- FL
5	1		*FRONT DOOR REGULATOR (LH)	Not Necessary	750.40 FL	*- FL
6	1		*FRONT DOOR POWER MOTOR,LH	Not Necessary	689.20 FL	*- FL
7	1		*FRONT DOOR HINGE UPPER (LH)	Not Necessary	165.76 FL	*- FL
8	1		*FRONT DOOR HINGE LOWER (LH)	Not Necessary	153.70 FL	*- FL
9	1		*FRONT DOOR CHECK (LH)	Not Necessary	72.98 FL	*- FL
10	1		*FRONT DOOR INNER LOCK (LH)	Not Necessary	385.60 FL	*- FL
11	1		*FRONT DOOR OUTER HANDLE (LH)	Repair	234.80 FL	*- FL
12	1		*FRONT DOOR MIRROR ASSY (LH)	Not Necessary	1,391.70 FL	*- FL
13	1		*FRONT DOOR MIRROR HOLDER (LH)	Not Necessary	175.90 FL	*- FL
14	1		*FRONT DOOR MIRROR LAMP (LH)	Not Necessary	97.10 FL	*- FL
15	1		*FRONT DOOR TRIM BOARD (LH)	Not Necessary	796.80 FL	*- FL
16	1		*FRONT DOOR PROTECTOR (LH)	Necessary	186.20 FL	*186.20 FL
17	1		*REAR DOOR (LH)	Bent/Dented	1,789.90 FL	*1,789.90 FL
18	1		*REAR DOOR RUBBER (LH)	Not Necessary	280.00 FL	*- FL
19	1		*REAR DOOR GLASS (LH/RH)	Not Necessary	190.20 FL	*- FL
20	1		*REAR DOOR OUTER HANDLE (LH)	Not Necessary	124.80 FL	*- FL
21	1		*REAR DOOR GEAR/REGULATOR (LH)	Not Necessary	367.84 FL	*- FL
22	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	256.80 FL	*- FL
23	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
24	1		*REAR DOOR HINGE UPPER (LH)	Not Necessary	173.88 FL	*- FL
25	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	170.50 FL	*- FL
26	1		*REAR DOOR CHECK (LH)	Not Necessary	85.92 FL	*- FL
27	1		*REAR DOOR TRIM BOARD (LH)	Not Necessary	613.60 FL	*- FL
28	1		*REAR DOOR PROTECTOR (LH)	Necessary	166.20 FL	*166.20 FL
29	1		*ROCKER PANEL OUTER GARNISH	Not Necessary	715.60 FL	*- FL
30	1		*BOOT LID	Not Necessary	2,480.40 FL	*- FL
31	1		*BOOT LID H EMBLEM	Not Necessary	28.00 FL	*- FL
32	1		*EMBLEM-HYBRID	Not Necessary	24.30 FL	*- FL
33	1		*EMBLEM-IONIQ	Not Necessary	31.30 FL	*- FL
34	1		*BOOT LID GLASS UPPER MOULDING	Not Necessary	186.30 FL	*- FL
35	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
36	1		*REAR BUMPER	Distorted/Cut	459.40 FL	*459.40 FL
37	1		*REAR BUMPER CENTRE MOULDING ASSY	Not Necessary	451.25 FL	*- FL
38	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
39	1		*REAR BUMPER SIDE RETAINER (LH)	Not Necessary	85.80 FL	*- FL
40	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
41	1		*REAR BUMPER SIDE UNDER (LH)	Not Necessary	123.10 FL	*- FL
42	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
43	1		*REAR FENDER (LH)	Dented	1,768.30 FL	*1,768.30 FL
44	1		*REAR TYRE RIM (LH)	Not Necessary	1,124.20 FL	*- FL
45	1		*REAR WHEEL HUP-CAP (LH)	Cut	346.40 FL	*346.40 FL
46	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR TRAILING ARM (LH)	Distorted	265.40 FL	*265.40 FL
48	1		*REAR ASSIST (LH)	Distorted	227.90 FL	*227.90 FL
49	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
50	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	133.10 FL	*- FL
51	1		*REAR ABSORBER STOPPER (LH)	Not Necessary	137.60 FL	*- FL
52	1		*REAR ABSORBER COVER (LH)	Not Necessary	175.60 FL	*- FL
53	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
54	1		*STABILIZER LINK (LH)	Not Necessary	147.30 FL	*- FL
55	1		*REAR UPPER ARM (LH)	Distorted	239.50 FL	*239.50 FL
56	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
57	1		*REAR KNUCKLE ARM (LH)	Distorted	538.10 FL	*538.10 FL
58	1		*EMBLEM-BLUE DRIVE (LH)	Necessary	26.60 F	*26.60 FN
59	1		*FRONT DOOR COMFORT LOGO (LH)	Cut/Necessary	75.00 FS	*75.00 FS
60	1		*REAR DOOR TEL NO STICKER (LH)	Necessary	10.00 FS	*10.00 FS
61	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Cut/Necessary	80.00 FS	*80.00 FS
62	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Not Necessary	35.00 FS	*- FS
63	1		*BOOT LID COMFORT CABLINK TEL NO STICKER	Not Necessary	30.00 FS	*- FS
64	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
65	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
66	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
67	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>24,781.23</b>	<b>9,808.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	4,797.33	1,894.96
<b>- Nett Item Discount on N Items 0.00/20.00% (\$)</b>	0.00	5.32
<b>Total Parts (\$)</b>	<b>19,983.90</b>	<b>7,908.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,800.00	900.00
3	WIRING CHARGE	New	120.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
10	RE-SET REAR ABS SYSTEM	New	400.00	0.00
11	REMOVE/REFIX FUEL TANK	New	80.00	0.00
12	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
13	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
14	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
15	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
16	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
17	FOUR WHEEL ALIGNMENT	New	120.00	60.00
18	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >