

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref	f:	CS3/ASM21002576/Qvf3e2
	8 SHENTON WAY TOWERSINGAPOR		Dat	te:	18/03/2021
	ATTN : TAN JUN F	IONG	Cod	de:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 6968C	Veh. Inspected		SJD 2858P
	Policy No.		Coverage (\$)		0.00
	Claim No.	S1M035AW	Excess (\$)		0.00
	Assign From	TAN JUN HONG	Assign Date		24/02/2021
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC 1.8L	c.c		1799
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	JHMFD16308S214506	Colour		BLACK
	Odometer	256899 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/45 R17	FIRENZA		6 mm
	L/H Front Tyre	225/45 R17	FIRENZA		6 mm
	R/H Rear Tyre	225/45 R17	FIRENZA		6 mm
	L/H Rear Tyre	225/45 R17	FIRENZA		6 mm
4.	Description of Damages				
	THE VEHICLE SUS	ICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5.	General Information				
	Accident Date	22/02/2021	Inspect Date / Time	е	24/02/2021 (02:32 PM)
	Survey held at	160 SIN MING DRIVE AUTOCIT	Y #03-18		
	Repairer	E M SOLUTION PTE LTD			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/ASM21002576/Qvf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser