

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21002579/KPA3Q2**Date:** 06/06/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0002791  
**Claimant Vehicle No :** SJZ245E **Insured Vehicle No :** SKN1374K  
 Date of Loss: 19/02/2021 Nature of Claim: TP Claim No: MPC2021D0000827

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJZ245E**  
 Make & Model: TOYOTA VIOS, 1.5 J (A) Engine No: 1NZX977380  
 Reg. Date: 02/10/2009 (Man. Year: 2009) Chassis No: MR053HY9305132161  
 Colour: Metallic Black Odometer: 424269 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Firenza 8 mm Rear Left Side: Firenza 8 mm  
 Front Right Side: Firenza 8 mm Rear Right Side: Firenza 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,171.69	613.14	558.55	47.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	440.00	510.00	53.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,121.69</b>	<b>1,053.14</b>	<b>1,068.55</b>	<b>50.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>850.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,121.69</b>	<b>850.00</b>	<b>1,271.69</b>	<b>59.94</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>957.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>950.00</b>		

**INSPECTION**

Date of Assignment: 24/02/2021  
 Date Inspected: 24/02/2021 Inspected At: Ngs Motorsport Pte Ltd - Ang Mo Kio (HQ)  
 Blk 10 Ang Mo Kio Ind Pk 2A, #02-01 AMK  
 AutoPoint  
 Singapore 568047  
 Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2022)
Parts:	143	TOYOTA VIOS 1.5 J (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ245E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Repair	371.40 FL	*- FL
2	1		*FRT FENDER LINER LH	Serviceable	153.80 FL	*- FL
3	1		*FRT BUMPER	Buckled / Cracked	447.90 FL	*447.90 FL
4	1		*FRT BUMPER SIDE RETAINER LH	Distorted	48.16 FL	*48.16 FL
5	1		*FRT BUMPER SUPPOER LH	Serviceable	59.80 FL	*- FL
6	1		*FRT BUMPER GRILLE LOWER LH	Serviceable	66.40 FL	*- FL
7	1		*HEADLAMP LH	Mtg Cracked	294.80 FL	*294.80 FL
8	20		*CLIPS ,FENDER LINER	Not Necessary	70.00 FS	*- FS
9	1		*NO PLATE	Cracked	20.00 FS	*20.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	1,532.26 810.86
					- List Item Discount on L Items 25.00/25.00% (S\$)	360.57 197.72
					Total Parts (S\$)	1,171.69 613.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT /ATTACHMENT STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL REPLACE DAMAGED PART ,REFIT INTO POSITION	New	400.00	200.00
2	TO SPRAY PAINTING	New	500.00	220.00
3	CHECK WIRING & LIGHTING FUNCTION	New	50.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>950.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >