

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002583/T1BA3Q2
Date: 01/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070124182
Claimant Vehicle No :	SHC3211C	Insured Vehicle No :	SMU8372J
Date of Loss:	23/02/2021	Nature of Claim:	TP
		Claim No:	6338716099SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3211C		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU167570
Reg. Date:	01/02/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU134055
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,726.44	1,929.56	1,796.88	48.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,990.00	1,240.00	750.00	37.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,716.44	3,169.56	2,546.88	44.55
+ GST 7.00/7.00% (S\$)	400.15	221.87	178.28	44.55

Nett Amount (S\$)	6,116.59	3,391.43	2,725.16	44.55
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
Nett Liability (S\$)		4,092.19		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 24/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY -FRONT DOOR RH	Bent	1,797.20 FL	*1,797.20 FL
2	1		*MOULDING ASSY -W/LINE FRT	Cut	186.20 FL	*186.20 FL
3	1		*GRIP -FRONT DOOR OUTSIDE R	Cracked	234.80 FL	*234.80 FL
4	1		*FRT DOOR LOGO SONATA CTPL	Necessary	75.00 FS	*75.00 FS
5	1		*APP LOGO REAR DOOR L/R CT	Cut	80.00 FS	*80.00 FS
6	1		*MOULDING ASSY -W/LINE RR D	Repair	166.20 FL	*- FL
7	1		*PANEL ASSY -REAR DOOR RH	Repair	1,789.90 FL	*- FL
8	1		*MOULDING ASSY -SIDE SILL R	Repair	290.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,619.30	2,373.20
- List Item Discount on L Items 20.00/20.00% (\$)	892.86	443.64
Total Parts (\$)	3,726.44	1,929.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	525.00
2	SPRAYPAINTING ON AFFECTED AREA	New	800.00	625.00
3	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
4	TRANSFER OF DOOR FRT RH	New	120.00	60.00
5	TRANSFER OF DOOR REAR RH	New	120.00	0.00
Gross Labour Cost (S\$)			1,990.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >