

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002587/T1TF3E2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100424993
Claimant Vehicle No : FX6292L Insured Vehicle No : SDK170L
Date of Loss: 11/01/2021 Nature of Claim: TP Claim No: 3336414440SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FX6292L**
Make & Model: KAWASAKI KRR ZX150, 148cc (M) Engine No: KR150EEA57702
Reg. Date: 17/01/2004 (Man. Year: 2003) Chassis No: KR150KA57702
Colour: Blue Odometer: 47821 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 80/90 R17
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/02/2021
Date Inspected: 25/02/2021 Inspected At: Halland Motor Services (HQ)
NO 1 KAKI BUKIT AVE 6, #02-24 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRONT TYRE	* Check	0.00 F	*- F
3	1		*FRONT RIM	Cut	0.00 F	*- F
4	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
5	1		*FRONT FORK ASSY	Repair	0.00 F	*- F
6	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
7	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
8	1		*FRONT WINDSHIELD	Cut	0.00 F	*- F
9	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
10	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
11	1		*METER ASSY	Cut	0.00 F	*- F
12	1		*METER BRACKET	Bent	0.00 F	*- F
13	1		*HANDLE BAR	Bent	0.00 F	*- F
14	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
15	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
16	1		*FUEL TANK	Repair	0.00 F	*- F
17	1		*CLUTCH LEVER	Cut	0.00 F	*- F
18	2		*SIDE FAIRING	Cracked	0.00 F	*- F
19	1		*SIDE FAIRING INNER GARNISH	Cut	0.00 F	*- F
20	1		*REAR FAIRING	Cut	0.00 F	*- F
21	1		*FRONT FOOT REST	Cut	0.00 F	*- F
22	1		*SIDE STAND	Bent	0.00 F	*- F
23	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
24	1		*REAR FOOT REST	Cut	0.00 F	*- F
25	1		*REAR FOOT REST BRACKET	Dented	0.00 F	*- F
26	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
27	1		*SET STICKER	Necessary	0.00 F	*- F
28	1		*HELMET	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >