

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002592/KPA3Q2

Date: 19/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100449360

Claimant
Vehicle No : SLP1675U **Insured Vehicle No :** SKZ4727T

Date of Loss: 23/02/2021 Nature of Claim: TP Claim No: 4159396237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1675U		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2421505A
Reg. Date:	27/05/2017 (Man. Year: 2017)	Chassis No:	SJNFEAJ11U1949394
Colour:	Metallic Pearl White	Odometer:	44383 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,402.73	2,241.31	161.42	6.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	1,040.00	440.00	29.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,882.73	3,281.31	601.42	15.49
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	3,882.73	3,200.00	682.73	17.58
+ GST 7.00/7.00% (S\$)	271.79	224.00	47.79	17.58
Nett Amount (S\$)	4,154.52	3,424.00	730.52	17.58
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,026.00		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 24/02/2021

Date Inspected: 25/02/2021 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Buckled	796.70 FN	*796.70 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	618.20 FN	*618.20 FN
3	1		*REAR BUMPER SPONGE	Cracked	126.40 FN	*126.40 FN
4	1		*REAR BUMPER TOW COVER	Dented	22.00 FN	*22.00 FN
5	2		*REAR BUMPER REFLECTOR	Serviceable	123.80 FN	*- FN
6	1		*REAR END PANEL	Bent	482.60 FN	*482.60 FN
7	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	400.00 FS	*350.00 FS
8	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,619.70	2,445.90
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	216.97	204.59
Total Parts (\$\$)	2,402.73	2,241.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
2	TO APPLY UNDERSEALING	New	60.00	30.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	450.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	700.00	500.00
Gross Labour Cost (\$\$)			1,480.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >