

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21002595/UBS3Q2
Date: 28/03/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLK5185S	Insured Vehicle No :	SLK2970L
Date of Loss:	06/02/2021	Nature of Claim:	TP
			Claim No: MFL2021D0000829

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK5185S		
Make & Model:	VOLVO V40, 1.5 T2 (A)	Engine No:	B4154T51865785
Reg. Date:	19/01/2017 (Man. Year: 2016)	Chassis No:	YV1MV28H0H2406325
Colour:	Grey	Odometer:	49096 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,992.00	0.00	2,992.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	710.00	470.00	39.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,172.00	710.00	3,462.00	82.98
+ GST 7.00/7.00% (S\$)	292.04	49.70	242.34	82.98
Nett Amount (S\$)	4,464.04	759.70	3,704.34	82.98
Global Sum Settlement (S\$)				0.00

INSPECTION

Date of Assignment:	24/02/2021	
Date Inspected:	25/02/2021	Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01- 2008/2010/2012 Singapore 489977
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2021)
Parts:	144	VOLVO V40 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5185S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	2,295.00 F	*- FL
2	1		*FRONT DOOR INNER RUBBER RH	Not fitted	272.00 F	*- FL
3	1		*FRONT DOOR POWER WINDOW MOTOR REGULATOR RH	Not Necessary	425.00 F	*- FL
4	1		*REAR DOOR RH (NPA)	Repair	0.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	2,992.00	0.00
				- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	0.00
				Total Parts (S\$)	2,992.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	280.00
2	SPRAY PANT ON THE AFFECTED AREAS	New	600.00	400.00
3	ANTI-RUST COATING	New	80.00	30.00
Gross Labour Cost (S\$)			1,180.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >