

ASS. REC. BY: LinuREF: CS/A421002609/RIVF3

653M

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SB38529Rat Workshop m/s: SBSTof 28,800N L&L STInsured: AU 8LT 8576EPolicy No. 1700077396Claims No. 6867968428SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SB38529R Yr Regn: 2008/066Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SCANIA KUB4X2.89A c.c. 8867Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: 1151395 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 452K4X20001862416Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5R: C A D/D

BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or. _____

Front Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 28/02/21 D.O.I. 28/02/21Survey held at SBST (Good L&L)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRX O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/4/21	Submit \$2381.60 (Red 0)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 26/4/21-Typist

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: MerimenLump Sum / L&L: (\$ \$2381.60)

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

DATE: 24.02.2021

DAY: Tuesday

Workshop Accident Repair Estimate

SBS Transit

SBS Transit Ltd

Soon Lee Depot

28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866

Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

Resue
4p 90010068
2 days
7/1p
25/02/21 @ 1650
Resue before paint

ACCIDENT DATE	23.02.2021	BUS REGISTRATION NUMBER	SBS8529R
ACCIDENT TIME	21:00 HRS	BUS TYPE (DD OR SD)	SD
THIRD PARTY CLAIM AGAINST	PRIVATE CAR, SLT8576		

S/No	SECTION A:	PARTS & MATERIAL COST	
	SBS8529R, Scania KUB4X2, SD, AC, 2 Axle		
	Part or Item Description	Quantity	Total Cost
1	HEADLAMP PANEL <i>CR</i>	1 pc	\$ -
2	CENTRE BUMPER <i>CR</i>	1 pc	\$ -
3	HINGE <i>7 X</i>	1 pc	\$ -
4	LAST ITEM		\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
	TOTAL PARTS & MATERIAL COST		\$ -

	SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
	Labour		\$ 1,625.00
	Spray Painting		
	TOTAL LABOUR COST		\$ 1,625.00

	SECTION C:	SUMMARY	
	TOTAL REPAIR COSTS		\$ 1,625.00
	TOTAL DOWNTIME		2.0 days

NOTE:

- 1) Repair cost is excluding Loss of use.
- 2) Additional parts might be required during the course of repair.

SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

DATE: 28.02.2021
DAY : Sunday

Workshop Accident Repair Estimate

ACCIDENT DATE: 23.02.2021 BUS REGISTRATION NUMBER: SBS8529R
ACCIDENT TIME: 21:00 HRS BUS TYPE (DD OR SD): SD
THIRD PARTY CLAIM AGAINST: PRIVATE CAR, SLT8576

S/No	SECTION A:	PARTS & MATERIAL COST	
	SBS8529R, Scania KUB4X2, SD, AC, 2 Axle		
	Part or Item Description	Quantity	Total Cost
1	HEADLAMP COVER N/S;F/GLASS(100 BUSES) - 30 122 002 <i>CR</i>	1 pc	\$ 296.40
2	HEADLAMP COVER O/S;F/GLASS; C - 30 122 054 <i>CR</i>	1 pc	\$ 210.60
3	LAST ITEM		\$ -
4			\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
TOTAL PARTS & MATERIAL COST			\$ 507.00

	SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
	Labour		\$ 1,874.60
	Spray Painting		
	Vinyl		
	Advertisement		
TOTAL LABOUR COST			\$ 1,874.60

	SECTION C:	SUMMARY	
TOTAL REPAIR COSTS			\$ 2,381.60
TOTAL DOWNTIME			2.0 days

NOTE:

- 1) Repair cost is excluding Loss of use.
- 2) Additional parts might be required during the course of repair.

507
1874.60
2381.60

A member of

COMFORTDELGRO



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: