

Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0090221

Date of Report

: 15/02/2021

To: M/s. Forte Auto Leasing Pte Ltd

C/o. 53, Ubi Ave 1, #05-44

Paya Ubi Industrial Park

Singapore 408934

Date of Assignment : 02/02/2021

Report requested by : M/s. Forte Auto Leasing Pte I

Date of Accident Date of Inspection : 31/01/2021

: 02/02/2021

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SLF50981.

Make & Model

Colour

: Mazda 2

Date of Registration

: 29/08/2016

Engine Capacity (cc) : 1496cc

Mileage (km)

: 253155km

: Met. Silver

Chassis / Frame No. : MM6DL2SAAGW209201

Engine No.

: P520360046

TYRE CONDITION

Front LH Make

: 7 mm

Front RH

: 7 mm

: Firenza

Rear LH

: Firenza

Rear RH

. 8 mm

Make

: 8 mm : Firenza

Make

Make

: Firenza

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

Handbrake

: Good

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate

Revised Amount

: \$ 7,612.00

6,302.56

Less Excess

: \$: S

Recommended Reserve

: **S**

5,040.00 (Lump Sum)

Estimated Normal Period of Repairs : 7 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Business Reg. 201404434D

Vehicle No: SLF5098L

Report No. : PAS/TP/0090221

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Neo Automotive Pte Ltd, 53, Ubi Ave I, #05-44, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$6,302.56.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$5,040.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew/How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com Business Reg. 201404434D

Vehicle No: SLF5098L

Report No. : PAS/TP/0090221

APPRAISEMENT SCHEDULE

I	l pc	Boot lid /	Dented/Distorted				\$ 862.40	ı	\$	862.40	
2	•	Boot hinge R/L		s	127.60		\$ 255.20		6	002140	
3		Boot emblem (Logo) /	Bent/Repair Necessary	•	127.00		\$ 255.20 \$ 62.30		6	62.30 /	
4		Boot emblem (Mazda 2)	•				\$ 61.40		2	61.40	
5	-	Boot reflector lamp R/L	Necessary Broken/Defaced	\$	231.70		\$ 463.40		\$	463.40 /	
6		Boot lock X	Bent Bent	ð	231.70		\$ 403.40 \$ 181.80		\$	181.80 X	
7	1 00	Boot inner trim lining V	Refit				\$ 288.10		6	197.00	
8	1 pc	Boot inner trim lining X 7500 Boot weatherstrip							D	133.60	
9	•	• •	Torn/Necessary	•	207.20		\$ 133.60		4		
10		Taillamp R/L	Cracked	\$	397.20		\$ 794.40		Ď.	794.40	
11	•	Rr bumper	Dented/Deformed	•	50.70		\$ 931.70		2	931.70	
	-	Rr bumper reflector lamp R/L XSV		\$	52.70		\$ 105.40		v v	52:70 ×	
12 13	/ pcs	Rr bumper clip	Necessary	\$	3.20		\$ 22.40		2	22.40	
-	2 pcs	Rr bumper retainer R/L XSVC	Cracked/Necessary	\$	28.30		\$ 56.60		2	56.60 28.3	
14	2 pcs	Rr bumper stay K/LXSUC	Necessary	2	18.20		36.40		2	36.40	
15	ı pc	Rr end panel trim garnish	Dented/Distorted				657.10		\$	657 . 10 ×	
16			Dented/Deformed				82.00		\$	82.00 /	
17		Rr spare tyre board cover	Serviceable	_			278.30		\$		
18		Rr fender inner trim R/L X	Cracked/Deformed	\$	198.20		396.40		\$	396.40	
19		Rr fender inner trim clip R/L	Necessary	\$	2.80	;	33.60		\$	3/3.60 ×	
20	•	Rr fender R/L	Dented/Repair					(Refer labour no. 3, 5 & 6)			
21		Rr floor panel	Dented/Repair		(Refer labour no. 3, 5 & 6) (Refer labour no. 3, 5 & 6)						
22	2 pcs	Rr chassis member R/L	Dented/Repair				. (Ref	er labour	110.	. 3, 5 & 6)	
							5,702.50		\$	4,828.20 44	
				Less D	Discount : :	20%	1,140,50	20%	\$	965.64	
			List	Parts Su	ıb-Total :	=	4,562.00	= =	\$	3,862.562753.5	
1	1 set	Rr reverse sensor X (com	Dented/Damaged		S/N	:	200.00		\$	200.00	
2	1 pc	Rr reverse sensor X Rr end panel scalant	Necessary		S/N	:	50.00		\$	40.00 X	
		• •	Special	Nett Su	ib-Total:	_	250.00		\$	240.00	

Parts Total:

\$ 4,812.00

\$ 4,102.56



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singspore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com Business Reg. 201404434D

venic	le No: SLF5098L		50311033 11eg. 201404434D					
S/No.		Report No. Repairer's Estimate (5\$)		Our Assessment (SS)				
1	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	· \$	60.00	s	59:00 } O			
2	To transfer boot component parts to new boot.	\$	100.00	s	80.00 ×			
3	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$	100.00		80.0060			
4	To remove, replace and reinstall rear reverse sonsors & control unit.	\$	50.00					
5	and replace damaged parts.	s	1,200.00	\$	888.00 500			
. 6	To spray painting, blending on affected and adjacent area.	\$	1,200.00	\$	1,000,00 &00			
7	To spray anti-rust coating on new and affected panels.	\$	90.00	\$	69:00 🔀			
	Labour Total :	\$	2,800.00	\$	2,200.00			
	Total (Parts & Labour) :	\$	7,612.00	_\$	6,302.56			

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 5,040.00

Under normal circumstances, the repairs should be completed within a reasonable period

Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

90 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

4183.52 20%: 3350 5 Days.