

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	INDIA INTERNATIO	ONAL INSURANCE PL	Ref:	CS3/III20009410/Kqf3e2-2	
	64 CECIL STREET #05-02 IOB BUILD	ING SINGAPORE 049711	Date	: 18/03/2021	
			Code	e: III2	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHA 5765T	Veh. Inspected	SMN 5492C	
	Policy No.	MCOM0015	Coverage (\$)	0.00	
	Claim No.	MCT20090009	Excess (\$)	0.00	
	Assign From	PRIYA MANIVEL	Assign Date	22/02/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT (A)	c.c	1317	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GK33422546	Colour	METALLIC DARK BLUE	
	Odometer	29482 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	175/70 R14	YOKOHAMA	5 mm	
	L/H Front Tyre	175/70 R14	YOKOHAMA	5 mm	
	R/H Rear Tyre	175/70 R14	YOKOHAMA	5 mm	
	L/H Rear Tyre	175/70 R14	YOKOHAMA	5 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	01/09/2020	Inspection Date	26/02/2021	
	Survey held at	vey held at BLK 348 YISHUN AVE 11 S761348			
	Repairer	Repairer XIN YUN AUTO PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				