

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002622/EVF3Q2

Date: 23/03/2021

REFERENCE

Insured/Claimant:	SADAYAN EQBAL	Policy No:	2070122906	
Date of Loss:	25/02/2021	Nature of Claim:	OD	Claim No: 0834098019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU6648C			
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)		Engine No:	4J11CN0387
Reg. Date:	25/08/2020 (Man. Year: 2020)		Chassis No:	GF7W0700630
Colour:	Grey		Odometer:	0 km
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$117,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,485.53	7,130.53	5,355.00	42.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,840.00	4,090.00	6,750.00	62.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,325.53	11,220.53	12,105.00	51.90
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	23,025.53	10,920.53	12,105.00	52.57
+ GST 7.00/7.00% (S\$)	1,611.79	764.44	847.35	52.57
Nett Amount (S\$)	24,637.32	11,684.97	12,952.35	52.57

INSPECTION

Date of Assignment: 25/02/2021

Date Inspected: 25/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER	Dented	811.00 FL	*811.00 FL
2	1		*BRKT,R/BMPR FACE SIDE,LH	Not Necessary	12.00 FL	*- FL
3	1		*BRKT,R/BMPR FACE SIDE,RH	Not Necessary	12.00 FL	*- FL
4	1		*REINFORCEMENT,RR BUMPER,LH	Not Necessary	79.00 FL	*- FL
5	1		*REINFORCEMENT,RR BUMPER,RH	Bent	79.00 FL	*79.00 FL
6	15		*CLIP,ENG ROOM COVER	Not Necessary	30.00 FL	*- FL
7	1		*EXTENSION,RR BUMPER	Crushed	360.00 FL	*360.00 FL
8	1		*MOULDING,RR BUMPER,LH	Necessary	106.00 FL	*106.00 FL
9	1		*MOULDING,RR BUMPER,RH	Necessary	106.00 FL	*106.00 FL
10	1		*REFLECTOR,TAIL LAMP,LH	Not Necessary	100.00 FL	*- FL
11	1		*REFLECTOR,TAIL LAMP,RH	Not Necessary	100.00 FL	*- FL
12	1		*PANEL,RR END	Repair	326.00 FL	*- FL
13	1		*PANEL,RR END,INR LH	Not Necessary	146.00 FL	*- FL
14	1		*PANEL,RR END,INR RH	Not Necessary	146.00 FL	*- FL
15	1		*TRIM,RR END	Not Necessary	113.00 FL	*- FL
16	1		*BOX,CARGO FLOOR	Not Necessary	204.00 FL	*- FL
17	1		*PANEL ASSY,TAILGATE	Dented	989.00 FL	*989.00 FL
18	1		*GARNISH,TAILGATE	Not Necessary	496.00 FL	*- FL
19	1		*W/STRIP,TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
20	1		*LATCH,TAILGATE	Necessary	477.00 FL	*477.00 FL
21	1		*STRIKER,TAILGATE LATCH	Necessary	19.00 FL	*19.00 FL
22	2		*DAM,TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
23	4		*FASTENER,WINDSHIELD	Necessary	24.00 FL	*24.00 FL
24	1		*DAM,TAILGATE UPR	Necessary	13.00 FL	*13.00 FL
25	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
26	1		*DAM,TAILGATE,LWR	Necessary	41.00 FL	*41.00 FL
27	1		*MARK,OUTLANDER	Necessary	95.00 FL	*95.00 FL
28	1		*LAMP ASSY,COMB,RR LH	Not Necessary	603.00 FL	*- FL
29	1		*LAMP ASSY,COMB,RR RH	Not Necessary	603.00 FL	*- FL
30	1		*LAMP ASSY,TAIL,LH	Not Necessary	506.00 FL	*- FL
31	1		*LAMP ASSY,TAIL,RH	Not Necessary	506.00 FL	*- FL
32	1		*DECAL,MIVEC	Necessary	36.00 FL	*36.00 FL
33	1		*BODY KIT,OUTLANDER	Not Necessary	1,554.00 FN	*- FN
34	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
35	1		*FACE,FR BUMPER	Broken	1,048.00 FL	*1,048.00 FL
36	1		*EXTENSION,FR BUMPER	Cut	509.00 FL	*509.00 FL
37	1		*BRACKET,FR BUMPER SIDE,LH	Not Necessary	18.00 FL	*- FL
38	1		*BRACKET,FR BUMPER SIDE,RH	Not Necessary	18.00 FL	*- FL
39	1		*GARNISH,FR BUMPER,LH	Not Necessary	48.00 FL	*- FL
40	1		*GARNISH,FR BUMPER,RH	Not Necessary	48.00 FL	*- FL
41	1		*COVER,FR BUMPER	Crushed	361.00 FL	*361.00 FL
42	1		*GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
43	1		*GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
44	1		*GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
45	1		*GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
46	1		*GARNISH,FR BUMPER SIDE	Not Necessary	112.00 FL	*- FL
47	1		*GARNISH,FR BUMPER SIDE	Not Necessary	112.00 FL	*- FL
48	1		*REINFORCEMENT,FR BUMPER	Not Necessary	493.00 FL	*- FL
49	1		*BAR,FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
50	1		*REINF,FR BUMPER SIDE,LH	Bent	60.00 FL	*60.00 FL
51	1		*REINF,FR BUMPER SIDE,RH	Bent	69.00 FL	*69.00 FL
52	2		*REINFORCEMENT,FR BMPR SIDE	Not Necessary	44.00 FL	*- FL
53	1		*REINFORCEMENT,FR BUMPER	Bent	135.00 FL	*135.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*MOULDING,FR BUMPER,LH	Necessary	116.00 FL	*116.00 FL
55	1		*MOULDING,FR BUMPER,RH	Necessary	116.00 FL	*116.00 FL
56	1		*REVERSE SENSOR	Torn	220.00 FS	*220.00 FS
57	1		*RR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
58	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
59	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
60	1		*BODY PNL SEALANT	Necessary	80.00 FS	*80.00 FS
61	1		*HEADLAMP ASSU, RH (Supplementary)	Broken	1,948.00 FL	*1,948.00 FL
62	1		*GRILLE ASSY,RADIATOR (Supplementary)	Broken	550.00 FL	*550.00 FL
63	1		*BUZZER, KEYLESS OPERATION, RR (Supplementary)	Broken	91.00 FL	*91.00 FL
64	6		*RIVET,FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	16,023.00	9,129.00
- List Item Discount on L Items 23.00/23.00% (\$)	3,226.67	1,998.47
- Nett Item Discount on N Items 20.00/20.00% (\$)	310.80	0.00
Total Parts (\$)	12,485.53	7,130.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW (RR PORTION) RR BUMPER,RR END PNL & TAILGATE REPAIR/RE-ALIGN RR FLR PNL,LHR FENDER & RHR FENDER	New	2,700.00	900.00
2	RENEW (FRT PORTION) FRT BUMPER,REPAIR FRT SUPPORT PNL,LHF FENDER & RHF FENDER	New	2,250.00	450.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AIRCON GAS	New	50.00	0.00
5	REMOVE & REFIT TAILGATE COMPONENT	New	120.00	120.00
6	REMOVE & REFIT RR FLR BOARD TRIM & CARPET	New	120.00	0.00
7	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00
10	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
11	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	50.00
12	RE-SEAL FRT & RR NUMBER PLATE	New	180.00	180.00
13	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
14	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
15	RESPRAY RR BUMPER, RR END PNL, TAILGATE, RR FLR PNL, LHR FENDER, RHR FENDER, BODY KIT, FRT BUMPER, LHF FENDER & RHF FENDER	New	3,850.00	1,050.00
16	REPAIR REAR END PANEL (Supplementary)	New	450.00	450.00
17	SPRAY PAINT REAR END PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			10,840.00	4,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >