



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV15926/SADAYAN EQBAL
	Reg No/Reg Date	SMU6648C / 25/08/202
	Date In/Mileage	/ 5431
	Chassis No	GF7W0700630
	Engine No	4J11CN0387
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								910 2700.00
RENEW (RR portion) RR <sup>1</sup> BUMPER , RR END PNL & TAILGATE					450 x 2			
REPAIR / RE-ALIGN RR FLR PNL , LHR FENDER & RHR FENDER								450 2250.00
E PNT88000								
RENEW (FRT portion) FRT <sup>1</sup> BUMPER					450 x 1			
REPAIR FRT SUPPORT PNL , LHF FENDER & RHF FENDER								? 100.00
E PNT88000								
REMOVE & REFIT AC COND & RADIATOR								? 50.00
M SUNDRY								
TOP UP AIRCON GAS								120.00
E PNT88000								
REMOVE & REFIT TAILGATE COMPONENT								? 120.00
E PNT88000								
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET								30.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								240.00
USING HI-SCAN PRO TEST								
E PNT88000								
REMOVE & REFIT RR WINDSCREEN GLASS								80.00
M SUNDRY								
SUPPLY RR WINDSCREEN SEALANT								50.00
M SUNDRY								
SUPPLY FRT NUMBER PLATE WITH CASING								50.00
M SUNDRY								
SUPPLY RR NUMBER PLATE WITH CASING								180.00
M SUNDRY								
RE-SEAL <u>FRT</u> & <u>RR</u> NUMBER PLATE								60.00
E PNT88000								
REMOVE & REFIT REVERSE SENSOR								? 220.00
M SUNDRY								
SUPPLY REVERSE SENSOR								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								42 120.00
APPLY ANTI CORROSION ON AFFECTEAD AREAS								80.00
M SUNDRY								40.00
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								3850.00
SUPPLY C&C BADGE								
M SUNDRY								
Sundries								
E PNT98000								
RESPRAY RR BUMPER , RR END PNL , TAILGATE , RR FLR PNL , LHR FENDER , 3 X 350 ●								1050
RHR FENDER , BODYKIT ,								
FRT BUMPER , LHF FENDER & RH FLENDER								
M	FACE,RR BUMPER	/ 00			1.00	811.00	23.00	624.47
M	BRKT,R/BMPR FACE SIDE,LH	X			1.00	12.00	23.00	9.24
M	BRKT,R/BMPR FACE SIDE,RH				1.00	12.00	23.00	9.24
M	REINFORCEMENT,RR BUMPER,LH				1.00	79.00	23.00	60.83
M	REINFORCEMENT,RR BUMPER,RH				1.00	79.00	23.00	60.83
M	CLIP,ENG ROOM COVER				15.00	2.00	23.00	23.10
M	EXTENSION,RR BUMPER	/ CRU (Silver)			1.00	360.00	23.00	277.20
M	MOULDING,RR BUMPER,LH	/ nec (Black)			1.00	106.00	23.00	81.62
M	MOULDING,RR BUMPER,RH	/ nec (Black)			1.00	106.00	23.00	81.62
M	REFLECTOR,TAIL LAMP,LH	X			1.00	100.00	23.00	77.00
M	REFLECTOR,TAIL LAMP,RH	X			1.00	100.00	23.00	77.00
M	PANEL,RR END				1.00	326.00	23.00	251.02
M	PANEL,RR END,INR LH	X			1.00	146.00	23.00	112.42
M	PANEL,RR END,INR RH	X			1.00	146.00	23.00	112.42
M	TRIM,RR END	X			1.00	113.00	23.00	87.01
M	BOX,CARGO FLOOR	X			1.00	204.00	23.00	157.08
M	PANEL ASSY,TAILGATE	/ 00			1.00	989.00	23.00	761.53
M	GARNISH,TAILGATE	X			1.00	496.00	23.00	381.92
M	W/STRIP,TAILGATE OPENING	X			1.00	213.00	23.00	164.01
M	LATCH,TAILGATE	/ nec ●			1.00	477.00	23.00	367.29
M	STRIKER,TAILGATE LATCH	/ nec ●			1.00	19.00	23.00	14.63

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	DAM, TAILGATE SIDE	✓ REC			2.00	27.00	23.00	41.58
M	FASTENER, WINDSHIELD	✓ REC			4.00	6.00	23.00	18.48
M	DAM, TAILGATE, UPR	✓ REC			1.00	13.00	23.00	10.01
M	STOPPER, WINDSHIELD GLASS	✓ REC			2.00	3.00	23.00	4.62
M	DAM, TAILGATE, LWR	✓ REC			1.00	41.00	23.00	31.57
M	MARK, OUTLANDER	✓ REC			1.00	95.00	23.00	73.15
M	LAMP ASSY, COMB, RR LH	✓ X			1.00	603.00	23.00	464.31
M	LAMP ASSY, COMB, RR RH	✓ X			1.00	603.00	23.00	464.31
M	LAMP ASSY, TAIL, LH	✓ X			1.00	506.00	23.00	389.62
M	LAMP ASSY, TAIL, RH	✓ X			1.00	506.00	23.00	389.62
M	DECAL, MIVEC	✓ REC			1.00	36.00	23.00	27.72
M	BODY KIT, OUTLANDER	✓ X			1.00	1554.00	20.00	1243.20
M	LLC 4L	✓ X			1.00	26.00	23.00	20.02
M	FACE, FR BUMPER	✓ BR			1.00	1048.00	23.00	806.96
M	EXTENSION, FR BUMPER	✓ CUT (Silver)			1.00	509.00	23.00	391.93
M	BRACKET, FR BUMPER SIDE, LH	✓ ?			1.00	18.00	23.00	13.86
M	BRACKET, FR BUMPER SIDE, RH	✓ ?			1.00	18.00	23.00	13.86
M	GARNISH, FR BUMPER, LH	✓ X			1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER, RH	✓ X			1.00	48.00	23.00	36.96
M	COVER, FR BUMPER	✓ CR4 (Black)			1.00	361.00	23.00	277.97
M	GARNISH, FR BUMPER SIDE	✓ ?			1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER SIDE	✓ ?			1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER SIDE	✓ BR (chrome)			1.00	220.00	23.00	169.40
M	GARNISH, FR BUMPER SIDE	✓ BR (chrome)			1.00	220.00	23.00	169.40
M	GARNISH, FR BUMPER SIDE	✓ ?			1.00	112.00	23.00	86.24
M	GARNISH, FR BUMPER SIDE	✓ ?			1.00	112.00	23.00	86.24
M	GARNISH, FR BUMPER SIDE	✓ ?			1.00	493.00	23.00	379.61
M	REINFORCEMENT, FR BUMPER	✓ ?			1.00	130.00	23.00	100.10
M	BAR, FR BUMPER GUARD	✓ ?			1.00	60.00	23.00	46.20
M	REINF, FR BUMPER SIDE, LH	✓ ?			1.00	69.00	23.00	53.13
M	REINF, FR BUMPER SIDE, RH	✓ ?			2.00	22.00	23.00	33.88
M	REINFORCEMENT, FR BUMPR SIDE	✓ ?			1.00	135.00	23.00	103.95
M	REINFORCEMENT, FR BUMPER	✓ ?			1.00	116.00	23.00	89.32
M	MOULDING, FR BUMPER, LH	✓ REC (Black)						

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M MOULDING,FR BUMPER,RH ✓ <i>Net (Black)</i>					1.00	116.00	23.00	89.32

Estimate

*Stere (LKK) 25/2/21, 1.99pm**00- NH A/L**Excess - ?**P/P**By Bel sty**8 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm &amp; accepted by

Signature:  
Date:

	Nett	20,508.90
7% GST on	20508.90	1435.62
<b>Total Payable</b>		<b>21,944.52</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.