

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)	
1	1	N/S Front Skid Plate Assembly	Damaged	73.00	73.00	✓
2	1	'A' X/Member Box;Underframe	Damaged	199.00	199.00	✓
3	1	Frame Support Angle Ent Step Frame	Dent	251.00	251.00	✓
4	1	J Rail Crash Protection Brkt; Frt Frame	Dent	18.00	18.00	✓
5	1	Mid Crash Bracket;Frt Frame	Damaged	50.00	50.00	✓
6	1	Mid Crash Bracket;Frt Frame	Damaged	27.00	27.00	✓
7	1	'A' Pillar Endplate	Dent	89.00	89.00	✓
8	1	O/S Front Pillar Assy;Frt Frame	Damaged	466.00	466.00	✓
9	9	Nipple; Frt.Lvl.Val.W/Conn	Damaged	71.00	71.00	✓
10	1	Underframe To Body Bracket	Dent	80.00	80.00	✓
11	1	Angle Section;Frt Assy	Damaged	49.00	49.00	✓
12	4	Nr715 Black Plastic Angle; Ent Door	Cut	72.00	72.00	✓
13	2	Cab Door Hinge;Anodised Alloy	Damaged	148.00	148.00	✓
14	3	Sealer To Match Ral7039 (Quartz Grey)	Necessary	172.00	172.00	✓
15	1	Dash Kicker Panel	Shifted	509.00	509.00	✓
16	1	Cladding Capping Endcap Lhs	Necessary	13.00	13.00	✓
17	1	Sbs Dash Rail;Hgp-00378-Pu2n-Ss-Ab	Damaged	735.00	735.00	✓
18	2	Pillar Trim Infill	Damaged	278.00	278.00	✓
19	2	Door Pillar Capping;Ent/Exit Door	Damaged	143.00	143.00	✓
20	1	Nr715 Black Plastic Angel;Ent Door	Damaged	18.00	18.00	✓
21	3	Sika 711 Windscreen Sealant	Necessary	90.00	90.00	✓
22	1	Lower Front Dome-CI2;F/Glass	Damaged	1080.00	1080.00	✓
23	1	Frt O/S Quarter Light Glass	Cracked	75.00	75.00	✓
24	1	Frt N/S Quarter Light Glass	Cracked	75.00	75.00	✓
25	1	Millen Screen Perimeter Rubber;Frt;Lower	Cut	207.00	207.00	✓
26	1	Plexus Adhesive	Necessary	113.00	113.00	✓
27	1	Chrome W/Plastic Packet;Frt;Exterior	Damaged	16.00	16.00	✓
28	1	Offside A Pillar Internal Capping	Damaged	216.00	216.00	✓
29	1	Sika 206 G+P Primer 1 Litre Tin	Necessary	137.00	137.00	✓
30	1	Blanking Plate;Daytime Running Light	Broken	54.00	54.00	✓
31	1	Main Beam Headlamp	Broken	66.00	66.00	✓
32	3	Adh Sika 205 Clean; 1 Litre	Necessary	150.00	150.00	✓
33	1	Glass.Side.No 2.Low/S.N/S	Cracked	776.00	776.00	✓
34	1	Frt Screen Filler Strip;1 RI=50m	Necessary	150.00	150.00	✓
35	1	'A' Pillar Capping N/S L/D	Damaged	277.00	277.00	✓
36	1	Dash Pedestal;Frt;Interior	Damaged	4054.00	4054.00	✓
37	1	Wiper Washer System-With Lever Sensor	Damaged	477.00	477.00	✓
38	1	Side Sheetmetal Panel	Dent	853.00	853.00	✓
39	1	Number Plate Recess Pane;Ext.Rr	Broken	151.00	151.00	✓
40	1	Panel.Rear.Bumper.O/S	Cracked	143.00	143.00	✓
41	1	Panel.Rear.Bumper.N/S	Cracked	143.00	143.00	✓
42	1	Front Door Canopy Assy	Damaged	142.00	142.00	✓
43	1	Mid Door Gutter;Exit Door	Damaged	35.00	35.00	✓
44	1	Door Canopy Assy;Exit Door	Damaged	143.00	143.00	✓
45	3	SHEET METAL ARRACHMENT BRACKET		140.00	140.00	✓

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)
46	8	Panel Attachment Brkt; Sheetmetal	Damaged	236.00	236.00 ✓
47	1	Battery Access Panel; Sheetmetal	Dent	1050.00	1050.00 ✓
48	2	Attachment Brkt. Battery Access Dr	Dent	134.00	134.00 ✓
49	2	Battery Door Hinge; Btry Access Panel	Damaged	120.00	120.00 ✓
50	1	Side Panel. O/S. Top Battery Access	Dent	82.00	82.00 ✓
51	1	Side Sheetmetal Panel	Dent	783.00	783.00 ✓
52	1	Side Sheetmetal Panel	Crumpled	705.00	705.00 ✓
53	1	N/S Dash Rail Brkt Assy; Frt Frame	Damaged	162.00	162.00 ✓
54	1	Lock Mech. Frt Bumper	Cracked	961.00	961.00 ✓
55	1	Frt N/S Pillar; Frt Frame	Broken	423.00	423.00 ✓
56	1	Bracket. 08 Frt Dome Attachment. N/S	Damaged	41.00	41.00 ✓
57	1	Alloy Capping; Ext Dr To Rr; L/S	Damaged	32.00	32.00 ✓
58	1	Cladding Capping Endcap Rhs	Damaged	12.00	12.00 ✓
59	1	Front Dash Beltrail; Interior	Damaged	2306.00	2306.00 ✓
60	1	08 Frt Hanging Strap; Frt Frame	Cut	71.00	71.00 ✓
61	1	First Aid Box Glass	Broken	219.00	219.00 ✓
62	2	Stainless Steel Hinge; Front Frame	Damaged	63.00	63.00 ✓
63	1	Screw; Flange; Coup. Fan.	Necessary	3.00	3.00 ✓
64	8	Nipple. Oil Resvr & Servo Pump	Damaged	108.00	108.00 ✓
65	2	Plug; A/Tnk. W/Fttg.	Damaged	4.00	4.00 ✓
66	50	Plastic Pipe; Rad. Cool. Sys	Damaged	133.00	133.00 ✓
67	4	Fitting Nut. Pwr Strg Pipes. Frt/Mid/Rr	Damaged	36.00	36.00 ✓
68	4	Screw; Air Cond.	Damaged	10.00	10.00 ✓
69	1	Flange Screw; Battery Bx; Wright	Necessary	2.00	2.00 ✓
70	3	Screw M16x65; R/Axle Outer Right	Necessary	10.00	10.00 ✓
71	2	S/S Compression Gas Spring. 200n	Damaged	551.00	551.00 ✓
72	10	Flange Screw; T/Chrg. W/Mtg	Necessary	4.00	4.00 ✓
73	4	Flange Screw. Air Brake	Necessary	1.00	1.00 ✓
74	2	Pull. Rod; Btry W/Fttg	Necessary	9.00	9.00 ✓
75	2	O-Ring; Press. Sensor; Air Tank	Necessary	5.00	5.00 ✓
76	50	Plastic Pipe Od-6mm; F/Val	Damaged	155.00	155.00 ✓
77	1	Terminal. Battery Cables/Box	Damaged	6.00	6.00 ✓
78	2	Elbow Nipple; Frt/Rr Level Val	Damaged	25.00	25.00 ✓
79	14	A1/2 Nipple; Frt. Lvl. Val	Damaged	130.00	130.00 ✓
80	4	Valve. Nipple Union. F/R Brake	Damaged	48.00	48.00 ✓
81	1	F-Nipple. Lvl Ctl Val. Frt Susp	Damaged	16.00	16.00 ✓
82	10	Nipple; A/Drier Regtr. W/Co	Damaged	94.00	94.00 ✓
83	4	Flange Lock Nut; Radiator	Necessary	4.00	4.00 ✓
84	6	Hexagon Screw. Shk Absorber. Frt	Necessary	20.00	20.00 ✓
85	6	Flange Lock Nut; Fan Dr	Necessary	3.00	3.00 ✓
86	1	Valve. Drian. Air Tank. Mbs.	Damaged	7.00	7.00 ✓
87	4	Nipple; Protecting Valve	Damaged	59.00	59.00 ✓
88	12	Washer; Rr; Wheel Brake; Vv	Damaged	4.00	4.00 ✓
89	4	Washer; Battery Mounting	Damaged	2.00	2.00 ✓
90	1	Nipple; PWR. STRG. PIPES; FRT		39.00	39.00 ✓

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)
91	2	Air Silencer;Lod Sensitive	Damaged	35.00	35.00 ✓
92	8	Flange Lock Nut;Battery Box	Damaged	8.00	8.00 ✓
93	2	T-Nipple;Ctl.Pnl.A/Prss/I	Damaged	34.00	34.00 ✓
94	4	Flange Bearing.Battery Bx Assy	Damaged	38.00	38.00 ✓
95	2	Rubber Ring;R/Cir Tank&Conn Parts	Damaged	20.00	20.00 ✓
96	12	Flange Screw.Frt/Trailing Axle	Damaged	47.00	47.00 ✓
97	1	Sbs Front End Loom	Damaged	179.00	179.00 ✓
98	1	J Rail Crash Protection Brkt; Frt Frame	Damaged	19.00	19.00 ✓
99	4	Washer;Frt.Suspn.Stabl	Damaged	11.00	11.00 ✓
100	2	Ball Joint;Level Ctl;Frt	Necessary	14.00	14.00 ✓
101	9	Split Pin;Strg System	Necessary	1.00	1.00 ✓
102	2	Flange Lock Nut;Cooling Package Assy	Necessary	3.00	3.00 ✓
103	4	Flange Screw.Strg.Trailing Axle	Damaged	37.00	37.00 ✓
104	4	Lock Nut;Flange;Coup.Fan	Necessary	4.00	4.00 ✓
105	20	Nut;Clamp;Exh.System.	Necessary	7.00	7.00 ✓
106	2	Ball Stud.Frt.Valve.F/S.	Necessary	19.00	19.00 ✓
107	2	Nut Retainer.Strg Kunkle.Frt	Necessary	29.00	29.00 ✓
108	1	Frt O/S Light Bezel Comp Mould-CI 2 ;Frt	Broken	136.00	136.00 ✓
109	1	Frt Mid Bumper Comp Mould-CI 2;Frt	Broken	316.00	316.00 ✓
110	1	Frt Os Corner Deflector Comp Mould CI 2	Broken	106.00	106.00 ✓
111	1	Bumper Corner.CI2.Frt Bumper.G/G.N/S	Broken	321.00	321.00 ✓
112	1	Crash Protection Support Bkt	Damaged	11.00	11.00 ✓
113	1	O/S Corner Bumper Comp Mould-CI 2;Frt	Damaged	285.00	285.00 ✓
114	1	Frt N/S Light Bezel Comp Mould-CI2	Damaged	112.00	112.00 ✓
115	1	Arm.C/W Bracket.Blindspot Mirror	Damaged	138.00	138.00 ✓
116	1	Main Beam Headlamp	Damaged	66.00	66.00 ✓
117	1	Filter Regulator;Door	Damaged	36.00	36.00 ✓
118	1	Support Brkt.O/S Top Battery Access	Damaged	67.00	67.00 ✓
119	1	Cab Floor & Footrest	Damaged	2337.00	2337.00 ✓
120	1	Sbs Front Light Loom	Damaged	306.00	306.00 ✓
121	1	Steering Column Att Brkt	Damaged	229.00	229.00 ✓
122	1	Box End Cap;Underframe	Damaged	5.00	5.00 ✓
123	1	Bracket.Bumper Top Attachment.N/S	Damaged	16.00	16.00 ✓
124	1	O/S Skid Plate.Frt Underframe	Damaged	61.00	61.00 ✓
125	1	Bracket.Bumper Bottom Attachment.N/S	Damaged	13.00	13.00 ✓
126	1	Mid Door Ramp Att Br;Erection	Dent	5.00	5.00 ✓
127	1	N/S Modular Frt To Interfloor Bracket	Dent	163.00	163.00 ✓
128	2	'A' Pillar Endplate	Dent	122.00	122.00 ✓
129	1	Underframe To Body Bracket	Dent	54.00	54.00 ✓
130	1	Skid Plate Gusset.Underframe	Damaged	3.00	3.00 ✓
131	2	Side Cladding Strip	Damaged	115.00	115.00 ✓
132	1	Front Door Gutter;Ent Door	Damaged	65.00	65.00 ✓
133	1	Entrance Step Frame;Underframe	Damaged	999.00	999.00 ✓
134	1	Frame Attachment Plate;Underframe	Damaged	23.00	23.00 ✓
135	1	ENTRANCE FRAME SUPPORT ANGLE; UNDERFLAME		99.00	99.00 ✓

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)	
136	1	Entreance Frame Support Angle;Underframe	Damaged	169.00	169.00	✓
137	1	Side Pull Magnetic Latch;Cab Dr	Damaged	110.00	110.00	✓
138	4	Headlight Mounting Frame;Ext.Frt	Broken	50.00	50.00	✓
139	1	Side Plank.Frt.N/S	Damaged	1739.00	1739.00	✓
140	1	Front Windscreen.Low/S	Cracked	826.00	826.00	✓
141	1	Cash Vault Door; Frt;Interior	Damaged	337.00	337.00	✓
142	1	Washer Bottle Bracket	Damaged	68.00	68	68.00 ✓
143	1	Step Edging.Entrance Door	Damaged	86.00	86	86.00 ✓
144	1	Entrance Door Step Finisher	Damaged	9.00	9.00	✓
145	8	M6x35 M1/B38 Bighead Bolt	Necessary	54.00	54.00	✓
146	8	Lug Nut-Zinc Mickel;M6	Damaged	32.00	32.00	✓
147	1	Dash First Aid Box	Damaged	302.00	302.00	✓
148	1	Wiper Arm O/S. Ext Frt	Damaged	377.00	377.00	✓
149	1	Structural Brace.Partition.Frt	Damaged	1012.00	1012.00	✓
150	10	M10x25 Csk Socket Zinc Nickel	Damaged	162.00	162.00	✓
151	1	Bottom Brush-Rh;Ent Dr 1	Damaged	73.00	73.00	✓
152	1	Body Pillar Assy.N/Sframe	Damaged	823.00	823.00	✓
153	1	Sealer To Match Ral7039 (Quartz Grey)	Necessary	57.00	57.00	✓
154	3	Flange Screw;M8x75;Thmst.Hsg.	Necessary	1.00	1.00	✓
155	10	Chrome W/Plastic Packer;Frt;Exterior	Damaged	169.00	169.00	✓
156	1	Battery Cable;Batt.W/Fttg	Damaged	34.00	34.00	✓
157	2	Cap;Anti-Rollbar;Dr Shift	Damaged	76.00	76.00	✓
158	2	King Pin Kit;Steering Knuckle Frt	Damaged	512.00	512.00	✓
159	1	Arm;Level Ctl;Frt	Damaged	17.00	17.00	✓
160	2	Spacer Rbbr.Bush;Anti-R/Bar	Damaged	181.00	181.00	✓
161	2	Valve.Solenoid.A/Brk.Modulator.Frt	Damaged	306.00	306.00	✓
162	7	Pressure Sensor.Air Tank	Damaged	1810.00	1810.00	✓
163	1	Bearing;Front Wheel Disc Brakes	Damaged	353.00	353.00	✓
164	2	Reaction Rod;Track Rod;Frt Susp	Damaged	1071.00	1071.00	✓
165	4	Elbow Nipple;Conn-Parts	Damaged	68.00	68.00	✓
166	4	Nut;Rr.Dist.Val.W/Conn.	Damaged	24.00	24.00	✓
167	1	Vertical Hollow Member;Strg Column	Damaged	403.00	403.00	✓
168	3	Nipple;Rr.Dist.Val.W/Conn	Damaged	43.00	43.00	✓
169	2	Hub Cover.Frt/Trailer Wh.Hub	Damaged	50.00	50	50.00 ✓
170	1	Trunk Cable;Cable Harness;Batt.Bx	Cut	494.00	494.00	✓
171	4	Screw M20x40;Steering	Necessary	103.00	103.00	✓
172	1	Switch.Press.Sensor.Brk.	Damaged	66.00	66.00	✓
173	1	Pressure Switch.Park.Brk.Eel	Damaged	38.00	38.00	✓
174	1	Switch.Press.Sensor.Brk.	Damaged	61.00	61.00	✓
175	1	Pressure Switch;C/Sender	Damaged	65.00	65.00	✓
176	1	Pressure Switch;Sensor	Damaged	95.00	95.00	✓
177	2	Stud;Anti-Roll Bar;Trailing Axle	Damaged	12.00	12.00	✓
178	1	Pressure Switch;Sensor Contact	Damaged	84.00	84.00	✓
179	1	Plug;Air Valve	Damaged	22.00	22.00	✓
180	2	SCREW-F/TANK STRAP MID-SCREEN PORT BRACKET		12.00	12.00	✓

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)	
181	1	Valve.Shut-Off.Cx4.5 Npsf.Ft/Brk	Damaged	98.00	98.00	✓
182	10	Hose;Cable Harness;Cable Channels	Damaged	49.00	49.00	✓
183	1	O-Ring;Hub;Trailer Axle	Damaged	5.00	5.00	✓
184	1	Clamping Sleeve;Frt/Trailing Axle	Damaged	5.00	5.00	✓
185	1	Adaptor;Pressure Switch	Damaged	27.00	27.00	✓
186	10	Wheel Stud;Frt/Trailer Wh.Hub	Damaged	126.00	126.00	✓
187	2	Sealing;Hub;Trailer Axle	Damaged	19.00	19.00	✓
188	1	Switch.Press.Sensor.Brk.	Damaged	66.00	66.00	✓
189	2	Hexagon Screw.Strg Knuckle.Frt	Necessary	5.00	5.00	✓
190	4	Sensor;Level Ctl Val;Frt/Rr Susp	Damaged	503.00	503.00	✓
191	2	Cover.King Pin.Strg Knuckle.F/A	Damaged	19.00	19.00	✓
192	2	Cover.King Pin.Strg Knuckle.F/A	Damaged	14.00	14.00	✓
193	2	Reaction Rod;Track Rod;Frt Axle	Damaged	1146.00	1146.00	✓
194	1	Cable.Brk Lining Wear Sensor.O/S Rr	Damaged	29.00	29.00	✓
195	1	Cable.Brk Lining Wear Sensor.N/S Rr	Damaged	43.00	43.00	✓
196	1	Link Rod;Steering;Frt	Damaged	447.00	447.00	✓
197	4	Attaching Clamp;Pwr Strg	Damaged	17.00	17.00	✓
198	1	Switch Windscreen Wiper;Signal Wiper	Damaged	137.00	137.00	✓
199	1	Steering Wheel Adjuster; Strg Column	Damaged/Shifted	612.00	612.00	✓
200	1	Stay;Battery Box Assy	Damaged	51.00	51.00	✓
201	1	Bracket;Floor Plate;Pedal	Damaged	206.00	206.00	✓
202	2	Shock Absorber; Frt Axle	Damaged	350.00	350.00	✓
203	1	Bracket.Battery Box Assy	Damaged	39.00	39.00	✓
204	1	Member;Battery Bx	Dent	593.00	593.00	✓
205	1	Valve.Control.Frt Susp	Damaged	672.00	672.00	✓
206	1	Sensor;Ambient Air Temp	Damaged	32.00	32.00	✓
207	1	Spacer. Bracket.Battery Bx Assy	Necessary	2.00	2.00	✓
208	1	Wheel Bracket.Battery Box Assy	Dent	36.00	36.00	✓
209	4	Attaching Clamp;Pwr Strg	Necessary	14.00	14.00	✓
210	1	Shaft;Battery Bx;Wright	Necessary	19.00	19.00	✓
211	2	Strap;Battery Box; Divider	Necessary	14.00	14.00	✓
212	1	Brk Disc Kit.Hub;Frt/Trailer Axle	Damaged	279.00	279.00	✓
213	1	Pressure Switch;Press.Sensor Contact	Damaged	81.00	81.00	✓
214	1	Cable Harness;Temp.Sensor	Damaged	12.00	12.00	✓
215	1	Nut;Steering Gear	Necessary	21.00	21.00	✓
216	2	Casing.Trailing Axle.Brakes	Necessary	1.00	1.00	✓
217	1	Nipple;M22-A1/2nptf F/A/I	Necessary	21.00	21.00	✓
218	10	Hose;Steering Column	Necessary	36.00	36.00	✓
219	2	Washer.Steering Gear	Necessary	67.00	67.00	✓
220	1	Retainer.Battery Box	Damaged	180.00	180.00	✓
221	2	Link;Anti-Roll Bar;F/A	Damaged	201.00	201.00	✓
222	1	Sensor.Lh.Brk Lining Wear.Tag Axle.	Damaged	82.00	82.00	✓
223	9	Castle Nut.Strg.Trailer Axle	Necessary	41.00	41.00	✓
224	1	MD STEER SUPPORT BR	Damaged	61.00	61.00	✓
225	1	SENSOR; LEVEL CTL; FRT/RR		162.00	162.00	✓

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)	
226	2	Air Spring Assy; Frt Axle	Damaged	434.00	434.00	✓
227	2	Hose Assy;Val Union;Rr Brake	Damaged	70.00	70.00	✓
228	1	Track Rod; Steering; Frt	Damaged	265.00	265.00	✓
229	1	Link Rod;Steering;Frt	Damaged	266.00	266.00	✓
230	1	Sensor.Brk Lining Wear.Rh	Damaged	82.00	82.00	✓
231	1	Brk Disc Kit.Hub;Frt/Trailer Axle	Damaged	279.00	279.00	✓
232	1	Pedal Plate;Foot Plate	Damaged	116.00	116.00	✓
233	1	Valve.Pressure Limiting Val.A/Tank	Damaged	110.00	110.00	✓
234	1	Sensor;Left;Brake Lining Wear;Frt	Damaged	91.00	91.00	✓
235	1	Control Rod;Level Ctl;Frt	Damaged	22.00	22.00	✓
236	1	Sensor. Rh.Brk Lining Wear.Frt	Damaged	75.00	75.00	✓
237	8	Stud;Trl.Wh.Ax.Suspn;Rr	Necessary	18.00	18.00	✓
238	11	Nipple;Frt.Lvl.Val.W/Conn	Necessary	105.00	105.00	✓
239	8	Nipple.Air Drier W/Conn	Necessary	36.00	36.00	✓
240	2	Clamp;Eng;Suct/Prss.Pipe;Dia 19	Necessary	1.00	1.00	✓
241	1	Washer;Power Strg Pump	Necessary	2.00	2.00	✓
242	2	Nut;Mod&Kick-Down Val	Necessary	11.00	11.00	✓
243	2	O-Ring;Wa/Pmp/King Pin	Necessary	7.00	7.00	✓
244	1	Nipple.3 Way.Frt Circuit Tk;W/T	Necessary	19.00	19.00	✓
245	6	Nipple;G/Box Fttgs	Necessary	86.00	86.00	✓
246	1	Bracket;T/Chrg.W/Mtg Part	Necessary	2.00	2.00	✓
247	1	Clevis Pin.Battery Box Assy	Necessary	1.00	1.00	✓
248	2	Emblem.Decals	Necessary	93.00	93.00	✓
249	2	O-Ring,Strg Knuckle.Frt	Necessary	10.00	10.00	✓
250	2	Gasket;Hyd.Eqpt	Necessary	5.00	5.00	✓
251	1	Bottom Bracket.Strg Column	Damaged	241.00	241.00	✓
252	1	Bracket;L=112;Air Brake	Necessary	3.00	3.00	✓
253	1	Hub Kit.Frt Axle.B9tl E5	Bent/Shifted	1262.00	1262.00	✓
254	1	Brk Chamber Frt B9tl Eu5	Damaged	226.00	226.00	✓
255	1	Brk Caliper.Wh Brk.F/A.Lh	Damaged	889.00	889.00	✓
256	2	Steering Knuckle Frt B9tl E5	Damaged	3454.00	3454.00	✓
257	1	Acc Pedal B9 TI Eu5	Damaged	1046.00	1046.00	✓
258	1	Bracket;Engine With Fucntion System	Necessary	3.00	3.00	✓
259	4	Flange Screw;Lub Oil Sys	Necessary	1.00	1.00	✓
260	1	Washer;Cyl.Head Val.Mechn	Necessary	1.00	1.00	✓
261	1	Brk Caliper.Wh Brk.F/A.Rh	Damaged	889.00	889.00	✓
262	1	Modulator.Air Brk.Frt	Damaged	508.00	508.00	✓
263	1	Valve Footbrake.B9tl Eu5	Damaged	592.00	592.00	✓
264	9	Nipple;3/8 Frt Level Val	Necessary	70.00	70.00	✓
265	1	Elbow Nipple;Cl.Servo W/C	Necessary	7.00	7.00	✓
266	50	Plastic Pipe;l/Dia 16mm	Necessary/Damaged	481.00	481.00	✓
267	9	Elbow Nipple;G/Box Fttgs	Damaged/Necessary	101.00	101.00	✓
268	9	Nipple M22x13;A/Tnk.W/Fit	Damaged	91.00	91.00	✓
269	4	Flange Screw;F/Tank W/Mtg	Necessary	1.00	1.00	✓
270	6	ELBOW NIPPLE; AIR DRIER REFTR W/CONN		81.00	81.00	✓

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)	
271	2	Nipple;Air Sprgs Assy;Trailing Axle	Damaged	27.00	27.00	✓
272	7	Nipple;G/Box Fttgs	Damaged	75.00	75.00	✓
273	2	Elbow Nipple M16xm16;A/T	Necessary	23.00	23.00	✓
274	50	Plastic Pipe;Od-12mm F/P	Damaged/Necessary	241.00	241.00	✓
275	8	Nipple;Cl.Servo W/Conn	Damaged/Necessary	85.00	85.00	✓
276	10	Plug;A/Tnl.W/Fttg	Necessary/Damaged	25.00	25.00	✓
277	8	Flange Screw;Clmp/Brkt	Necessary	4.00	4.00	✓
278	4	Flange Screw;T/Chrg.W/Mtg	Necessary	1.00	1.00	✓
279	4	T-Nipple M16x13;A/Tnk.W/F	Damaged/Necessary	44.00	44.00	✓
280	1	Clevis.Battery Box Assy	Damage	9.00	9.00	✓
281	2	Protecting Plug;Elect D/Ctre	Damaged	12.00	12.00	✓
282	9	Washer;Press.Sensor;Air Tank	Necessary	27.00	27.00	✓
283	1	Cable Harness;Compl.Instrument ✱	Damaged	4800.00	4800.00	✓
284	2	Pillar Repair Kit ✱	Damage	1000.00	1000.00	✓
285	4	Nut-Flange;Mounting Drive	Necessary	1.00	1.00	✓
286	1	Frame;Dash Mounting	Damaged	49.00	49.00	✓
287	2	Flange Screw;Thmst Hsg W/Conn.Parts	Necessary	2.00	2.00	✓
288	1	Bottom Doorshaft Brg Assy Rh;Ent Dr	Damaged	82.00	82.00	✓
289	1	Bottom Doorshaft Bgr Assy Lh;Ent Dr	Damaged	82.00	82.00	✓
290	2	Alum Flat Bar;Ent Dr	Dent	43.00	43.00	✓
291	1	Door & Shaft Assy;Ent Dr 2 ✱	Dent	1559.00	1559.00	✓
292	1	Door & Shaft Assy;Ent Dr1 ✱	Dent	1559.00	1559.00	✓
293	1	Bottom Brush-Lh;Ent Dr2	Damaged	73.00	73.00	✓
294	1	Edge Rubber Out Swing D;Exit Dr.2.3m	Damaged/Cut	178.00	178.00	✓
295	1	Retainer.Battery Box	Damaged	179.00	179.00	✓
296	1	Frt Ns Corner Deflector Comp Mould Cl2	Broken	106.00	106.00	✓
297	1	Valve.Quick Release.R/Brk	Damaged	40.00	40.00	✓
298	1	Steering Gear.Strg B9tl Eu5A ✱	Damaged	2773.00	2773.00	✓
299	4	Split Pin;Air Sprg Assy;F/Axle	Necessary	5.00	5.00	✓
300	4	Spacer Sleeve;Pwr Strg	Necessary	12.00	12.00	✓
301	2	Support Member.Battery Bx	Damaged	386.00	386.00	✓
302	1	Pipe.Pwr Strg Pipes;Frt	Damaged	107.00	107.00	✓
303	1	Steering Arm;Rh Strg Frt	Broken	537.00	537.00	✓
304	2	Terminal Battery Cables Batt Bx	Damaged	2.00	2.00	✓
305	12	Test Nipple;Frt Wh Brake	Broken	72.00	72.00	✓
306	8	Pressure Screw Hub F/A	Necessary	6.00	6.00	✓
307	17	Electric Cables Red Batt Bx	Snapped	126.00	126.00	✓
308	10	M8x16 Allen Head Bolt Patched	Necessary	19.00	19.00	✓
309	1	Valve.Control	Damaged	484.00	484.00	✓
310	2	Pressure Sensor;Air Tank	Damaged/Dent	515.00	515.00	✓
311	1	Shaft.Battery Box Assy	Dent	428.00	428.00	✓
312	1	Sealing Plate.Rhs Underframe	Damaged	5.00	5.00	✓
313	2	Mudflap.505x200x6mm.Underframe	Dent	34.00	34.00	✓
314	1	Steering Column Stregthener	Damaged	51.00	51.00	✓
315	1	MID STEP SUPPORT BRACKET		6.00	6.00	✓

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)	
316	1	Member Battery Box Assy	Broken	405.00	405.00	✓
317	4	Toothed Washer Air Brk Val Frt	Necessary	3.00	3.00	✓
318	2	Lubricating Nipple Batt Bx	Necessary	18.00	18.00	✓
319	2	Support Air Tank Mtg & Fittings	Damaged	47.00	47.00	✓
320	1	Elbow Nipple Air Brk Modulator	Damaged	15.00	15.00	✓
321	2	Elbow Nipple Pwr Strg Pipe Frt	Damaged	47.00	47.00	✓
322	2	Nipple Pwr Strg Pipe Frt	Damaged	29.00	29.00	✓
323	1	Wires Sensor Brk Lining Wear	Snapped	74.00	74.00	✓
324	1	Steering Shaft;Upper;Strg Column	Dent	527.00	527.00	✓
325	1	Battery Cover;Battery Box	Broken	225.00	225.00	✓
326	1	Slide Rail;Bracket Battery Bx Assy	Dent	76.00	76.00	✓
327	2	Hexagon Nut;Hub;Trialer Axle	Broken	38.00	38.00	✓
328	1	Direction Ind.Swt.Switches	Damaged	134.00	134.00	✓
329	2	Flange Screw.Strg Parts.Frt	Broken	14.00	14.00	✓
330	2	Sleeve Nut.Braked.F/A	Broken	30.00	30.00	✓
331	1	T-Niple Pwr Strg Pipes Frt	Broken	56.00	56.00	✓
332	2	Weld Nut Batt Box	Broken	52.00	52.00	✓
333	1	Chain.Air Valve	Broken	12.00	12.00	✓
334	1	Plug Air Brk Val Frt	Necessary	4.00	4.00	✓
335	1	Sealing Ring Air Brk Val Frt	Necessary	2.00	2.00	✓
336	1	Diaphragm Air Brk Val Frt	Necessary	16.00	16.00	✓
337	1	Deflector Braked F/A	Broken	71.00	71.00	✓
338	1	Lock Battery Box	Damaged	9.00	9.00	✓
339	2	Snap Ring Air Brk Val Frt	Necessary	5.00	5.00	✓
340	1	Bracket Rh Anti Roll Bar F/A	Dent	242.00	242.00	✓
341	1	Shield Rh Brakes F/A	Damaged	73.00	73.00	✓
342	1	Sensor Wheel.Wh Hub F/A	Damaged	35.00	35.00	✓
343	1	Bracket Battery Bx	Damaged	25.00	25.00	✓
344	1	Bracket Lh Anti Roll Bar F/A	Dent	309.00	309.00	✓
345	1	Mounting Kit Wh Hub F/A	Bent	60.00	60.00	✓
346	4	Washer 3mm Rection Rod F/A	Necessary	14.00	14.00	✓
347	4	Washer 1mm Rection Rod F/A	Necessary	12.00	12.00	✓
348	1	Shield Lh Brakes F/A	Broken	73.00	73.00	✓
349	1	Pitman Arm Strg Frt	Bent	496.00	496.00	✓
350	12	Simson 7005-Black (600ml)	Necessary	174.00	174.00	✓
351	2	Dipped Beam Headlamp	Broken	137.00	137.00	✓
352	4	Sheet Metal Attachment Bracket	Dent	188.00	188.00	✓
353	1	Single View Mirror O/S;Ashtree	Broken	52.00	52.00	✓
354	1	Water Tank.Wiper	Deformed	75.00	75.00	✓
355	1	Side Sheetmetal Panel	Dent	769.00	769.00	✓
356	1	Glass.Side.No 1 Glazing.Low/S.O/S	Cracked	899.00	899.00	✓
357	2	Suspension Access Plug;Floor	Damaged	224.00	224.00	✓
358	1	Packer.N/S 'A' Pillar	Necessary	15.00	15.00	✓
359	1	Wiper Blade;O/S;31 (80cm)	Damaged	60.00	60.00	✓
360	1	ATTACHMENT BRACKET. BOTTOM.O/S BUMPER		13.00	113.00	ext hve

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)	
361	1	Attachment Bracket.Top.O/S Bumper	Damaged	14.00	14.00	✓
362	1	Comp Front Mid Bumper Brkt;Frt Frame	Cracked	22.00	22.00	✓
363	1	Millen Screen Perimeter Rubber;Frt;Lower	Cut	207.00	207.00	✓
364	3	Adh Sika 205 Clean;1 Litre	Necessary	150.00	150.00	✓
365	1	Glass.Side.No 2 Low/S.N/S	Cracked	776.00	776.00	✓
366	1	Member.Reaction Rod.F/A *	Broken	3248.00	3248.00	✓
367	1	Cover, Steering Column	Cut	15.00	15.00	✓
368	2	Filler Cap;Non-Lockable;Adblue Tank	Damaged	45.00	45.00	✓
369	5	Screw; Dashboard W/Ftfg.	Necessary	4.00	4.00	✓
370	1	Pipe.Pwr Strg Pipe.Frt	Damaged	141.00	141.00	✓
371	2	Hex Socket Screw;Strg Column	Necessary	1.00	1.00	✓
372	1	Panhard Rod;Rr.Tr/Wh.Axle	Bent	718.00	718.00	✓
373	1	Attachment Kit;Strg Column	Damaged	18.00	18.00	✓
374	2	Flange Bearing.Battery Bx Assy	Damaged	19.00	19.00	✓
375	1	Oil Filler Cap;Oil Filler Pipe	Damaged	9.00	9.00	✓
376	1	Label.Air Valve	Necessary	36.00	36.00	✓
377	1	Pipe.Pwr Strg Pipes.Frt	Damaged	107.00	107.00	✓
378	1	Electric Cable.Battery Bx	Snapped	26.00	26.00	✓
379	1	Retainer,Steering Column	Damaged	2.00	2.00	✓
380	2	Brk Pad Kit.Frt/Tag Axle	Damaged	338.00	338.00	✓
381	1	Retainer,Steering Column	Damaged	2.00	2.00	✓
382	2	Shock Abrorber;Pusher Axle	Damaged	459.00	459.00	✓
383	1	Contact Reel; Strg Column	Damaged	27.00	27.00	✓
384	1	Farebox.Lp009;Mu-10-1^	Damaged	198.00	198.00	✓
385	2	Support Bracket.Battery Door	Dent	99.00	99.00	✓
386	1	Toggle Bar.4 Hole (62mm Pitch)	Dent	20.00	20.00	✓
387	1	Electrical Panel Packer.Underframe	Snapped	9.00	9.00	✓
388	1	Brake Housing.Rh Disc.F/A *	Damage	1259.00	1259.00	✓
389	8	Lock Nut.Suspension Trailer	Necessary	73.00	73.00	✓
390	1	Anti-Roll Bar.F/A *	Dent	1294.00	1294.00	✓
391	1	Brake Housing.Lh Disc Brk.F/A *	Damaged	1259.00	1259.00	✓
392	1	Anchorage.Reaction Rod.Fa/A	Bent	138.00	138.00	✓
393	1	Service Kit.Acc Pedal & Plate	Bent	29.00	29.00	✓
394	4	Flange Lock Nut;Fan Drive System	Necessary	6.00	6.00	✓
395	1	Hub Kit.Frt Axle.B9tl E5 *	Wrapped	1250.00	1250.00	✓
396	1	Fuse Box.Elect.Distribution Bx.Frt	Damaged	912.00	912.00	✓
397	2	Carrier Kit.Disc Brk.F/A	Damaged	328.00	328.00	✓
398	2	Flange Bearing.Battery Bx Assy	Damaged	19.00	19.00	✓
399	2	Bridge Kit.Disc Brk.F/A	Damaged	269.00	269.00	✓
400	4	Flange Screw;Anti-Roll Bar;Trail Axl	Necessary	16.00	16.00	✓
401	1	Sbs Mid Crash Assembly-Pivot	Dent	550.00	550.00	✓
402	4	Sealed Lever Latch;Os/Ns;Rr Side Dr	Damaged	208.00	208.00	✓
403	1	Side Sheetmetal Panel	Dent	444.00	444.00	✓
404	1	Mirror Arm; N/S;C/W Male Brkt.Ma	Broken	145.00	145.00	✓
405	1	BLINDSPOT MIRROR N/S		90.00	90.00	✓

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)	
406	1	Two View Mirror N/S;Ashtree	Broken	67.00	67.00	✓
407	1	08 Frt Steel Belt Rail; Assy	Damaged	486.00	486.00	✓
408	1	O/S Lower Deck Frt Pillar Trim;Interior	Cracked	447.00	447.00	✓
409	1	Chrome W/Plastic Packer;Frt;Exterior	Damaged	16.00	16.00	✓
410	1	Semi Maint.Free Battery 200ah; Furukawa	Damaged	187.00	187.00	✓
411	1	Semi Maint.Free Battery 200ah; Furukawa	Damaged	187.00	187.00	✓
412	2	Sealer To Match Ral7039 (Quartz Grey)	Necessary	114.00	114.00	✓
413	1	Battery Box *	Damaged	1298.00	1298.00	✓
414	1	Cables.Single Core.Red.1.0mm	Snapped	60.00	60.00	✓
415	1	Cables.Single Core.Black.1.0mm	Snapped	73.00	73.00	✓
416	1	Mudflap Support.Underframe	Dent	38.00	38.00	✓
417	1	'B' Crossmember Seal.Underframe	Necessary	7.00	7.00	✓
418	1	Gangway Frame.Frt	Broken	604.00	604.00	✓
419	1	'B' Pillar Endplate.N/S.Underframe	Dent	37.00	37.00	✓
420	1	Wheelarch Patch.N/S.Frt	Damaged	42.00	42.00	✓
421	50	15.2*Lg Ny Ties Ct4062b	Necessary	120.00	120.00	✓
422	1	'B' Crossmember.Underframe	Dent	165.00	165.00	✓
423	2	M8x16 Allen Head Bolt Patched	Necessary	3.00	3.00	✓
424	5	40mm P-Clips St/St 15mm Wide Band	Damaged	38.00	38.00	✓
425	2	Frt Indicator Green W/Position Red	Broken	545.00	545.00	✓
426	6	Frame Attachment Plate;Underframe	Dent	142.00	142.00	✓
427	5	35mm P-Clip St/St 15mm Wide Band	Damaged	36.00	36.00	✓
428	2	Suspension Access Collar;Floor	Damaged	163.00	163.00	✓
429	4	Panel Attachment Brkt.Sheetmetal	Dent	52.00	52.00	✓
430	1	Compress Fix Bracket.N/S.Mid Bumper	Damaged	26.00	26.00	✓
431	2	Rail.Comp Frt Bumper.20x40 Frt Frame	Necessary	4.00	4.00	✓
432	1	Side Sheetmetal Panel	Dent	689.00	689.00	✓
433	1	First Aid Kit W/Pouch	Necessary	26.00	26.00	✓
434	1	5.8m Horizontal Face Piece;Acropolis	Damage	103.00	103.00	✓
435	4	Rubber Cushion;Siln & Exh Pipes Mtg Parts	Necessary	58.00	58.00	✓
436	1	Symbol;Switches;Dashboard	Damaged	6.00	6.00	✓
437	1	Switch.Dashboard	Damaged	63.00	63.00	✓
438	1	Ent Divider Handrail;Hgp-0041-Pu2n-Ssa	Damaged	560.00	560.00	✓
439	1	Knob;Blocking Valve;B/Sys	Damaged	3.00	3.00	✓
440	1	Ecu.Bbm.Vv Eu5 *	Damaged	1104.00	1104.00	✓
441	1	Sensor Rh.Brk Lining Wear Tag Axle	Snapped	60.00	60.00	✓
442	1	Wiring Harness.Frt Axle *	Snapped	1011.00	1011.00	✓
443	1	Wbgem Chrome Plated Abs Kit Ext Frt	Broken	154.00	154.00	✓

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

SBS3061E @ 31/01/2020

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
			Subtotal	: 105616.00	105616.00
			TOTAL	: 105616.00	105616.00
			TOTAL FOR SPARE PARTS	: 105616.00	105616.00

VICOM LTD
SURVEY REPORT

SBS3081E @ 31/01/2020

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Assessment to be done by contractor.	188.00	188.00 ✓
2	Contractor's repair charges	44000.00	18000.00 16500 ✓
TOTAL FOR LABOUR AND SPRAY PAINTING :		44188.00	18188.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS :	105616.00	105616.00
TOTAL FOR LABOUR AND SPRAY PAINTING :	44188.00	18188.00
TOTAL REPAIR COST :	149804.00	123804.00

105616.00
16500.00
188.00
122,304.00
55 days