

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INDIA INTERNATION	ONAL INSURANCE PL	Ref:	CS/III20013534/Ktf3e2-2		
	64 CECIL STREET #05-02 IOB BUILD	- ING SINGAPORE 049711	Date:	11/03/2021		
			Code:	III2		
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SHA 3564U	Veh. Inspected	SLE 1874U		
	Policy No.	199303821R	Coverage (\$)	0.00		
	Claim No.	MCT20120122	Excess (\$)	0.00		
	Assign From	DHANYA	Assign Date	25/02/2021		
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA SIENTA (A)	c.c	1496		
	Engine No.	HIDDEN	Year of Reg.	2016		
	Chassis No.	NSP1707008583	Colour	METALLIC BLUE		
	Odometer	92385 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	NIL		
	General	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	185/60 R15	MICHELIN	8 mm		
	L/H Front Tyre	185/60 R15	MICHELIN	8 mm		
	R/H Rear Tyre	185/60 R15	MICHELIN	8 mm		
	L/H Rear Tyre	185/60 R15	MICHELIN	8 mm		
4.	Description of Damages					
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.					
	REPAIR CONDITION SEE DETAILS.					
5.	General Information					
	Accident Date	05/12/2020	Inspection Date	04/03/2021		
	Survey held at SAU HOCK MOTOR SERVICES					
		BLK 10 ANG MO KIO INDUSTRIAL PARK 2A (AVE 5) #02-14 AMK AUTOPOINT SINGAPORE 568047.				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
			ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			