

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002629/KGA3Q2
Date: 29/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499261
Claimant Vehicle No :	GBH7542R	Insured Vehicle No :	SLL2123K
Date of Loss:	22/02/2021	Nature of Claim:	TP
		Claim No:	8518830517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH7542R		
Make & Model:	MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M)	Engine No:	R9MA503C052160
Reg. Date:	14/09/2018 (Man. Year: 2018)	Chassis No:	WDF44760323474388
Colour:	Red	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Gremax 9 mm	Rear Left Side:	Gremax 9 mm
Front Right Side:	Gremax 9 mm	Rear Right Side:	Gremax 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,817.00	17,147.73	16,669.27	49.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	2,780.00	2,920.00	51.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	39,517.00	19,927.73	19,589.27	49.57
+ GST 7.00/7.00% (S\$)	2,766.19	1,394.94	1,371.25	49.57

Nett Amount (S\$)	42,283.19	21,322.67	20,960.52	49.57
		<hr/>		
+ Loss of Use (33.0 x S\$60.00/day) (S\$)		1,980.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		50.00		
		<hr/>		
Nett Liability (S\$)		23,360.12		
		<hr/>		

INSPECTION

Date of Assignment: 25/02/2021

Date Inspected: 26/02/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Tong Luck Auto Pte Ltd (HQ)
 160 Sin Ming Drive, #07-01 Sin Ming AutoCity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DASHBOARD ASSY	Torn	1,850.00 FN	*1,591.87 FN
2	1		*STEERING AIR BAG	Burst	2,455.00 FN	*2,455.00 FN
3	1		*PASSENGER AIR BAG	Burst	2,455.00 FN	*2,455.00 FN
4	1		*AIR BAG CONTROL UNIT	Necessary	1,495.00 FN	*1,495.00 FN
5	2		*FRONT SAFETY BELT -RH/LH	Jammed	1,580.00 FN	*1,580.00 FN
6	1		*FRONT SAFETY BELT BUCKLE-RH	Serviceable	485.00 FN	*- FN
7	2		*FRONT SAFETY BELT ADJUSTER -RH/LH	Serviceable	570.00 FN	*- FN
8	1		*FRONT SAFETY BELT -CENTRE	Jammed	790.00 FN	*790.00 FN
9	1		*FRONT SAFETY BELT BUCKLE-LH	Serviceable	325.00 FN	*- FN
10	1		*FRONT SAFETY BELT BUCKLE-CENTRE	Serviceable	325.00 FN	*- FN
11	1		*BATTERY CUT OFF SWITCH	Activated	520.00 FN	*520.00 FN
12	1		*BONNET	Bent	1,475.00 FN	*1,378.20 FN
13	1		*BONNET LOCK -LOWER	Distorted	185.00 FN	*122.77 FN
14	2		*BONNET HINGE -RH/LH	Distorted	160.00 FN	*148.22 FN
15	1		*SUPPORT PANEL	Cracked	590.00 FN	*590.00 FN
16	1		*SUPPORT PANEL TOP GARNISH	Cracked	115.00 FN	*115.00 FN
17	1		*SUPPORT PANEL BRACKET -LH	Distorted	48.00 FN	*48.00 FN
18	1		*FRONT FENDER -LH	Buckled	788.00 FN	*788.00 FN
19	1		*FRONT FENDER INNER SHIELD -LH	Cracked	188.00 FN	*188.00 FN
20	1		*FRONT FENDER INNER SHIELD FLAP-LH	Missing	58.00 FN	*58.00 FN
21	20		*FRONT FENDER INNER SHIELD CLIPS-LH	Necessary	162.00 FS	*50.00 FS
22	1		*HEADLAMP ASSY -LH	Broken	845.00 FN	*845.00 FN
23	1		*FRONT BUMPER	Cracked	965.00 FN	*775.33 FN
24	1		*FRONT BUMPER REINFORCEMENT	Bent	680.00 FN	*635.88 FN
25	1		*FRONT BUMPER CARRIER-LH	Cracked	104.00 FN	*104.00 FN
26	1		*FRONT BUMPER SIDE RETAINER -LH	Distorted	98.00 FN	*98.00 FN
27	1		*FRONT BUMPER STRUT -LH	Serviceable	64.00 FN	*- FN
28	1		*FRONT BUMPER CROSS MEMBER BRACKET -LH	Bent	74.00 FN	*74.00 FN
29	1		*FRONT BUMPER UNDER COVER	Serviceable	265.00 FN	*- FN
30	1		*FRONT BUMPER LOWER CROSS MEMBER	Serviceable	290.00 FN	*- FN
31	1		*FRONT BUMPER CLIPS (15 PCS)	Necessary	121.50 FS	*50.00 FS
32	1		*WASHER TANK	Damaged	145.00 FN	*145.00 FN
33	1		*WASHER TANK NECK	Dented	58.00 FN	*58.00 FN
34	1		*WASHER TANK COVER	Dented	28.00 FN	*28.00 FN
35	1		*AIR-CON CONDENSER	Serviceable	650.00 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*AIR-CON CONDENSER SUPPORT FRAME	Serviceable	165.00 FN	*- FN
37	1		*RADIATOR ASSY	Serviceable	660.00 FN	*- FN
38	1		*RADIATOR AUTO FAN ASSY	Cracked	980.00 FN	*901.21 FN
39	1		*RADIATOR GUIDE-LH	Cracked	78.00 FN	*78.00 FN
40	1		*RADIATOR LOWER COVER	Cracked	125.00 FN	*125.00 FN
41	1		*RADIATOR SUPPORT LH	Missing	48.00 FN	*48.00 FN
42	1		*RADIATOR TOP CLIPS -LH	Necessary	28.00 FN	*28.00 FN
43	1		*RADIATOR TOP BEARING -LH	Not Necessary	58.00 FN	*- FN
44	1		*INTER-COOLER ASSY	Serviceable	780.00 FN	*- FN
45	1		*FRONT SHOCK ABSORBER -LH	Serviceable	1,515.00 FN	*- FN
46	1		*FRONT UPPER ARM-LH	Serviceable	1,210.00 FN	*- FN
47	1		*FRONT LOWER ARM -LH	Serviceable	1,250.00 FN	*- FN
48	1		*FRONT KNUCKLE ARM -LH	Serviceable	2,315.00 FN	*- FN
49	1		*STEERING TIE-ROD-LH	Serviceable	280.00 FN	*- FN
50	1		*STEERING TIE-ROD END-LH	Serviceable	198.00 FN	*- FN
51	1		*FRONT TORSION BAR	Serviceable	340.00 FN	*- FN
52	1		*FRONT LINKAGE -LH	Serviceable	111.00 FN	*- FN
53	1		*SUB FRAME	Serviceable	2,030.00 FN	*- FN
54	1		*FRONT AXLE	Serviceable	2,870.00 FN	*- FN
55	1		*FRONT WHEEL RIM -LH	Serviceable	380.00 FN	*- FN
56	1		*FRONT WHEEL HUP CAP -LH	Dented	88.00 FN	*88.00 FN
57	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
58	2		*RADIATOR COOLANT	Necessary	120.00 FS	*50.00 FS
59	1		*FRONT TYRE -LH	Serviceable	280.00 FS	*- FS
60	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
61	1		*ERP BRACKET	Not Necessary	26.00 FS	*- FS
62	1		*WASHER TANK MOTOR	Cracked	188.00 FN	*188.00 FN
63	1		*WASHER TANK LOWER MOUNTING	Bent	52.00 FN	*52.00 FN
64	1		*WATER HOSE (LONG)	Dented	118.00 FN	*118.00 FN
65	1		*WATER HOSE (SHORT)	Cracked	85.00 FN	*85.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	37,484.50	19,027.48
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	3,667.50	1,879.75
Total Parts (\$\$)	33,817.00	17,147.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	150.00	120.00
2	TO REMOVE AND REFIT FRONT DASHBOARD ASSY ,METER AND GROVE COMPARTMENT	New	350.00	250.00
3	TO REMOVE AND REFIT AIR-CON CONDENSER ,RADIATOR INTER-COOLER ASSY AND REFILL AIR-CON GAS	New	280.00	100.00
4	TO CHECK AND RECTIFY WIRING SYSTEMS	New	80.00	20.00
5	TO REMOVE AND REFIT STEERING AIR BAG ,PASSENGER AIR BAG AIRBAG CONTROL UNIT ,FRONT BOTH SIDE AND CENTRE SAFETY BELT	New	550.00	300.00
6	TO REMOVE AND REFIT BATTERY CUT OFF SWITCH	New	150.00	80.00
7	TO REMOVE AND REFIT LH FRONT UNDERCARRIAGE	New	580.00	0.00
8	TO PANEL BEAT AND STRAIGHTEN LH FRONT CHASSIS FRAME ,LH FRONT FENDER INNER PANEL ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESARY TO REFIT AND ADJUST THE SAME	New	1,500.00	700.00
9	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
10	TO RE-PROGRAME AND CODING ALL FAULTY CODE (ONLINE)	New	580.00	450.00
11	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
12	TO OPEN AND SEAL UP REAR CUSHION TO ENABLE TO CHARGE SAFETYBELT	New	180.00	100.00
Gross Labour Cost (\$\$)			5,700.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >