

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002630/GPA3Q2
Date: 12/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800061728
Claimant Vehicle No :	SHD1265E	Insured Vehicle No :	SMA2686Z
Date of Loss:	25/02/2021	Nature of Claim:	TP
		Claim No:	2861269100SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1265E		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ088798
Reg. Date:	14/12/2016 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ117503
Colour:	Silver	Odometer:	346282 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,407.87	1,186.74	2,221.13	65.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	640.00	1,300.00	67.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,347.87	1,826.74	3,521.13	65.84
Approved Total (Overridden) (S\$)		1,450.00		

(S\$)	5,347.87	1,450.00	3,897.87	72.89
+ GST 7.00/7.00% (S\$)	374.35	101.50	272.85	72.89
Nett Amount (S\$)	5,722.22	1,551.50	4,170.72	72.89
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/02/2021

Date Inspected: 05/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOWER GARNISH	Cracked	362.61 FL	*362.61 FL
2	1		*TAILGATE LOCK	Not Necessary	216.48 FL	*- FL
3	1		*TAILGATE STRIKER	Not Necessary	36.50 FL	*- FL
4	1		*TAILGATE INNER TRIM	Not Necessary	431.12 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Not Necessary	276.98 FL	*- FL
6	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL
7	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
8	1		*EMBLEM HYUNDAI	Not Necessary	29.40 FL	*- FL
9	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL
10	1		*REAR BUMPER SPONGE	Not Necessary	79.20 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	815.64 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT CENTRE	Not Necessary	79.20 FL	*- FL
13	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Not Necessary	104.40 FL	*- FL
14	1		*REAR BUMPER N/S & O/S REFLECTOR	O/S Cracked / N/S Not Necessary	215.00 FL	*107.50 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
16	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
17	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*30.00 FS
18	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	38.00 FS	*38.00 FS
19	1		*REAR BUMPER TOP PROTECTOR	Not Necessary	80.00 FS	*- FS
20	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,110.84	1,454.42
- List Item Discount on L Items 20.00/20.00% (S\$)	702.97	267.68
Total Parts (S\$)	3,407.87	1,186.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	40.00
2	TO DISMANTLE/REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGES FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/CUT AND WELD ON THE END PANEL.INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE TAILGATE ETC	New	800.00	300.00
4	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL ,TAILGATE	New	800.00	300.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (S\$)			1,940.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >