

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002631/KBA3Q2
Date: 15/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505216
Claimant Vehicle No :	SLV4761C	Insured Vehicle No :	SLM4653D
Date of Loss:	24/02/2021	Nature of Claim:	TP
		Claim No:	8492061856SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV4761C	Engine No:	CHZ584044
Make & Model:	VOLKSWAGEN GOLF, 999cc TSI (A)	Chassis No:	WVWZZZAUZJW090429
Reg. Date:	29/12/2017 (Man. Year: 2017)	Odometer:	61448 km
Colour:	Metallic Brown		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 2 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,398.00	4,416.21	5,981.79	57.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,125.00	1,070.00	2,055.00	65.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,523.00	5,486.21	8,036.79	59.43
Approved Total (Overridden) (S\$)		4,350.00		

(S\$)	13,523.00	4,350.00	9,173.00	67.83
+ GST 7.00/7.00% (S\$)	946.61	304.50	642.11	67.83
Nett Amount (S\$)	14,469.61	4,654.50	9,815.11	67.83
+ Car Rental (5.0 x S\$110.00/day) (S\$)		550.00		
Nett Liability (S\$)		5,204.50		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 25/02/2021

Date Inspected: 01/03/2021

Inspected At:

Wega Engineering Pte Ltd (HQ)
 BLK 176 Sin Ming Drive #04-16, Sin Ming AutoCare
 Singapore 57521

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cut	1,140.00 F	*1,140.00 FL
2	1		*FRONT HEADLAMP RH	Cut	761.00 F	*761.00 FL
3	1		*FRONT FENDER RH	Bent	649.00 F	*649.00 FL
4	1		*FRONT HEADLAMP BRACKET RH (TOP PANEL)	Repair	61.00 F	*- FL
5	1		*FRONT BUMPER BRACKET RH	Necessary	53.00 F	*53.00 FL
6	1		*FRONT FOG LAMP COVER RH	Serviceable	104.00 F	*- FL
7	1		*FRONT FOG LAMP RH	Serviceable	245.00 F	*- FL
8	1		*FRONT SPORT RIM RH	Serviceable	1,473.00 F	*- FL
9	1		*FRONT TYRE RH	Serviceable	225.00 F	*- FL
10	1		*FRONT KNUCKLE ARM RH	Bent	758.00 F	*616.45 FL
11	1		*FRONT WHEEL HUP RH	Bent	589.00 F	*501.50 FL
12	1		*FRONT WHEEL BEARING RH	Necessary	280.00 F	*280.00 FL
13	1		*FRONT LOWER ARM RH	Distorted	487.00 F	*487.00 FL
14	1		*FRONT ABSORBER RH	Bent	484.00 F	*418.95 FL
15	1		*FRONT TIE ROD RH	Serviceable	166.00 F	*- FL
16	1		*FRONT TIE ROD INNER RH	Serviceable	122.00 F	*- FL
17	1		*FRONT TORSION BAR LINK RH	Serviceable	125.00 F	*- FL
18	1		*FRONT DRIVE SHAFT ASSY RH	Repair	2,676.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	10,398.00	4,906.90
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	490.69
Total Parts (\$)	10,398.00	4,416.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	20.00
2	TO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	20.00
3	TO REMOVE AND REFIX UNDERCARRIAGE	New	600.00	200.00
4	TO RESPRAY ACCIDENT FRONT PORTION	New	1,000.00	400.00
5	TO KNOCKING AND WELDING FRONT PORTION	New	1,000.00	400.00
6	TO APPLY RUST PROOFING TO AFFECTED AREA	New	150.00	30.00
7	TO REPLACE FRONT TYRE	New	55.00	0.00
8	TO CHECK FOR FUNCTION AND ALIGNMENT HEADLAMP	New	80.00	0.00
Gross Labour Cost (S\$)			3,125.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >