

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002633/EQE2

Date: 01/04/2021

REFERENCE

Insured/Claimant:	LEUNG HOK LUN	Policy No:	1900102299		
Date of Loss:	23/02/2021	Nature of Claim:	OD	Claim No:	2909745340SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB3377A	Engine No:	G4CLKH020358
Make & Model:	KIA STINGER, 2.0 2WD SUNROOF (A)	Chassis No:	KNAE351AMK6060627
Reg. Date:	10/06/2019 (Man. Year: 2019)	Odometer:	14756 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,076.00	1,601.20	1,474.80	47.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	1,600.00	2,820.00	63.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,496.00	3,201.20	4,294.80	57.29
+ GST 7.00/7.00% (S\$)	524.72	224.08	300.64	57.30
Nett Amount (S\$)	8,020.72	3,425.28	4,595.44	57.29

INSPECTION

Date of Assignment:	26/02/2021		
Date Inspected:	25/02/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*ULTRASONIC SENSOR ASSY (A) - PAS	Shorted	189.00 F	*189.00 FN
3	1		*ULTRASONIC SENSOR ASSY (B) - BWS	Shorted	189.00 F	*189.00 FN
4	1		*MUFFLER ASSY RR LH (NPA)	Not Necessary	0.00 FS	*- FS
5	1		*MUFFLER ASSY RR RH (NPA)	Not Necessary	0.00 FS	*- FS
6	1		*COVER-RR BUMPER	Dented	639.00 FL	*639.00 FL
7	1		*COVER-RR BUMPER LWR	Crushed	342.00 FL	*342.00 FL
8	1		*BRACKET-RR BUMPER RAIL LWR, LH	Not Necessary	29.00 FL	*- FL
9	1		*BRACKET-RR BUMPER RAIL LWR, RH	Not Necessary	29.00 FL	*- FL
10	1		*LAMP ASSY-REAR R/REFL, LH	Not Necessary	29.00 FL	*- FL
11	1		*LAMP ASSY-REAR R/REFL, RH	Not Necessary	29.00 FL	*- FL
12	1		*TRIM ASSY-TAIL, LH	Not Necessary	216.00 FL	*- FL
13	1		*TRIM ASSY-TAIL, RH	Not Necessary	216.00 FL	*- FL
14	1		*MOULDING ASSY-RR BUMPER, CTR	Crushed	93.00 FL	*93.00 FL
15	1		*CAP-RR HOOK	Cut	6.00 FL	*6.00 FL
16	1		*COVER-RR BPR BLANKING, LH	Not Necessary	12.00 FL	*- FL
17	1		*COVER-RR BPR BLANKING, RH	Not Necessary	12.00 FL	*- FL
18	1		*EXTN WIRING ASSY-BWS	Not Necessary	201.00 FL	*- FL
19	1		*BEAM-RR BUMPER	Broken	263.00 FL	*263.00 FL
20	1		*STAY-RR BUMPER LH	Not Necessary	85.00 FL	*- FL
21	1		*STAY-RR BUMPER RH	Not Necessary	85.00 FL	*- FL
22	2		*BRACKET-RR BUMPER, UPR	Not Necessary	10.00 FL	*- FL
23	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	79.00 FL	*- FL
24	1		*BRACKET-RR BEAM LWR, CTR	Broken	6.00 FL	*6.00 FL
25	2		*BRACKET-RR BUMPER, LWR	Broken	10.00 FL	*10.00 FL
26	1		*BRACKET ASSY-RR BUMPER SIDE, LH	Not Necessary	64.00 FL	*- FL
27	1		*BRACKET ASSY-RR BUMPER SIDE, RH	Not Necessary	64.00 FL	*- FL
28	1		*PANEL ASSY-BACK	Not Necessary	377.00 FL	*- FL
29	1		*MOULDING-BACK PANEL	Not Necessary	212.00 FL	*- FL
30	1		*LOGO-KIA	Necessary	64.00 FL	*64.00 FL
31	1		*EMBLEM-STINGER	Necessary	68.00 FL	*68.00 FL
32	1		*EMBLEM-GT LINE	Necessary	45.00 FL	*45.00 FL
33	1		*REAR LICENSE PLATE WITH FRAME (Supplementary)	Bent	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	3,733.00	1,984.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	657.00	307.20
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	75.60
Total Parts (\$\$)	3,076.00	1,601.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER. REPAIR / RE-ALIGN RR END PNL & BOOTLID PNL	New	2,000.00	400.00
2	RESPRAY RR BUMPER, RR END PNL & BOOTLID	New	1,050.00	350.00
3	REMOVE & REFIT RR EXHAUST MUFFLER	New	400.00	0.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
8	SUPPLY C&C BADGE	New	40.00	40.00
9	REPAIR REAR END PANEL (Supplementary)	New	200.00	200.00
10	SPRAY PAINT REAR END PANEL AND BOOT GARNISH (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			4,420.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >