

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002641/EVF3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00136702005
Claimant Vehicle No :	SGH59G	Insured Vehicle No :	SJW5147M
Date of Loss:	24/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D201095/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH59G	Engine No:	8AR4253717
Make & Model:	LEXUS NX300, 2.0 (A)	Chassis No:	JTJBARBZ802230568
Reg. Date:	01/04/2020 (Man. Year: 2020)	Odometer:	16785 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R18	Rear Tyre Size:	225/60R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	211.90	161.90	50.00	23.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,628.50	1,824.50	804.00	30.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,840.40	1,986.40	854.00	30.07
+ GST 7.00/7.00% (S\$)	198.83	139.05	59.78	30.07
Nett Amount (S\$)	3,039.23	2,125.45	913.78	30.07

INSPECTION

Date of Assignment:	26/02/2021	
Date Inspected:	01/03/2021	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2021)
Parts: M1-SUV	LEXUS NX300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH59G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SET MOULDING	Necessary	111.90 FS	*111.90 FS
Total Parts (S\$)					211.90	161.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON LHS REAR DOOR AND FIX NEW PARTS	New	1,299.00	866.00
2	TO SPRAY PAINT ON LHS REAR DOOR	New	1,113.00	742.00
3	TO RESET ECU AND REPROGRAMME	New	216.50	216.50
Gross Labour Cost (S\$)			2,628.50	1,824.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >