

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21002646/KPS3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999993662

Claimant Vehicle No : SLT3606K**Insured Vehicle No :**

SMM4199L

Date of Loss: 30/01/2021

Nature of Claim:

TP

Claim No:

0630718184SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT3606K**

Make & Model: NISSAN QASHQAI, 1.2 (A)

Engine No:

HRA2498932A

Reg. Date: 26/10/2017 (Man. Year: 2017)

Chassis No:

SJNFEAJ11U2040315

Colour: Metallic Pearl White

Odometer:

57009 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,815.50	1,726.18	1,089.32	38.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,415.50	2,126.18	1,289.32	37.75
Approved Total (Overridden) (S\$)		1,700.00		

Nett Amount (S\$)	3,415.50	1,700.00	1,715.50	50.23
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,887.45		

INSPECTION

Date of Assignment: 26/02/2021

Date Inspected: 26/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

CARPLUS AUTO PTE LTD (HQ)
 160 SIN MING DRIVE #04-06, SIN MING AUTOCITY
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cut	853.00 F	*796.70 FN
2	1		*REAR BUMPER SPONGE	Cracked	152.00 F	*152.00 FN
3	1		*REAR REINFORCEMENT	Bent	740.50 F	*691.50 FN
4	4		*REVERSE SENSOR	Shorted (2 PCS ONLY)	1,070.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,815.50	1,890.20
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	164.02
Total Parts (\$\$)	2,815.50	1,726.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RESPRAY PAINTING	New	350.00	200.00
2	BEING LABOUR TO DISMANTLE & RENEW THE ABOVE MENTIONED PARTS	New	250.00	200.00
Gross Labour Cost (S\$)			600.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >