



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 6676P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	MTG CRACKED	633.60	633.60
1	FRONT BUMPER RH FOG LAMP	CUT	149.83	149.83
1	FRONT BUMPER RH SIDE RETAINER	SERVICEABLE	91.40	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	RH HEADLAMP	CUT	2,368.20	2,209.00
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	341.16	-
1	FRONT RH SPORTS RIMS	SERVICEABLE	833.50	-
	LESS 10% DISCOUNT		-446.77	-304.24
			4,020.92	2,738.19
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT BUMPER LOWER SKIRTING (SN)	MTG CRACKED	1,200.00	500.00
			1,200.00	500.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES FOR REMOVE/REFIT,PANEL BEATING AND REPLACE ACCIDENT DAMAGES.INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		600.00	400.00
	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES.		600.00	550.00
	TO CHECK WIRINGS AND LIGHTINGS.		40.00	20.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.	NOT NECESSARY	80.00	-
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	50.00	-
			1,370.00	970.00
<b>GRAND TOTAL</b>			<b>6,590.92</b>	<b>4,208.19</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,350.00</b>

Report Ref No. CS/AGI21002647/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.