

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002650/GQF3E2

Date: 31/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900017856
Claimant Vehicle No :	FBL6265B	Insured Vehicle No :	GBJ2124L
Date of Loss:	17/02/2021	Nature of Claim:	TP
		Claim No:	7015805455SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL6265B	Engine No:	MC46E5030051
Make & Model:	HONDA CBF190WH, 184cc	Chassis No:	LWBMC4695H1110141
Reg. Date:	04/01/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80-17	Rear Tyre Size:	140/70-17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/02/2021		
Date Inspected:	19/03/2021	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Repair	0.00 F	*- F
2	1		*FRONT FORK OIL	Necessary	0.00 F	*- F
3	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
4	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
5	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
6	1		*STEERING STEM	Necessary	0.00 F	*- F
7	1		*STEERING CONE AND BEARING	Necessary	0.00 F	*- F
8	1		*HANDLE BAR	* Check	0.00 F	*- F
9	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
10	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
11	1		*SIDE FAIRING	Cut	0.00 F	*- F
12	1		*REAR FAIRING	Cut	0.00 F	*- F
13	1		*FRONT FOOT REST	Cut	0.00 F	*- F
14	1		*REAR FOOT REST	Cut	0.00 F	*- F
15	1		*REAR BOX	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >