

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21002655/Gvf3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	15/03/2021	
	ATTN : DOMINIC Y	U		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 3998R	Veh. Inspected		FX 898D
	Policy No.		Coverage (\$)		0.00
	Claim No.	S1M0359J	Excess (\$)		0.00
	Assign From	DOMINIC YU	Assign Date		26/02/2021
2. Vehicle Particulars & Condition					
	Make & Model	HONDA PHANTOM	c.c		197
	Engine No.	HIDDEN	Year of Reg.		2003
	Chassis No.	TA2000018113	Colour		BLACK
	Odometer	93429 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	100/80-17	DELI		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	130/90-15	VEE RUBBER		4 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY, FRONT AND REAR PORTION.			ND	
5.	. General Information				
	Accident Date	13/02/2021	Inspect Date /	Time	26/02/2021 (05:00 PM)
	Survey held at	EQUATOR BROTHERHOOD			
	25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800				
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21002655/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor